



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002485/Uga3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 16-04-2020



ATTN:YVONNE

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMH 9855U	Veh. Inspected	SGV 3741B
Policy No.	GA444374/1	Coverage (\$)	0.00
Claim No.	S0M02G13	Excess (\$)	0.00
Assign From		Assign Date	12/02/2020

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR053HY9305003305	Colour	GREY
Odometer	289038	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	MICHELIN	6 mm
L/H Front Tyre	195/60 R15	MICHELIN	6 mm
R/H Rear Tyre	195/60 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/60 R15	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.
---

### 5. General Information

Accident Date	10/02/2020	Inspection Date	13/02/2020
Survey held at	23 KAKI BUKIT AVE 4, KB VICOM #04-01		
Repairer	AUTOMOBILE INTEGRATED MANAGEMENT PL		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------