

ASS. REC. BY:

REF: CS/AIG20002531 / kvd31

Special Instruction:

alc

Surveyor: Kennedy

ASSIGNMENT (Office)

From (Person): Chin Lee Ying of AIG Date/Time: 13/2/2020 @ 8:51am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 4508X Insured:

at Workshop m/s: Tong Luck Tel: 6250 0088

of 160 Sin Ming Drive # 0701

Policy No: 0999995580 Claim No: 6823282483 SG

Sum Insured: Excess: 1400

Make of Veh: D.O.A. 13/01/2020

(Client's Record)

CA (REV) / REF. / REV 24 HRS MV: \$42K H.O.D. Endorsement:

Date/Time: 9:11am @ 13/2/2020 Person Contacted: Terrence Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate
	GBF 4508X - X	✓
14/2/20	Revert via merimen	
19/2/20	Rece approved \$1605.30 from Victor by merimen	
19/2/20	Informed Candy c/A ex \$1400 by email	

ASS. REC. BY:

REF: AIG (S/AIG 2000253) / kvd3

ASSIGNMENT

From: Date: 13/02/2020

Veh No: GBF 4508X Yr Regn: 11/16

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: GBF 4508X

Make: Mer on Citar 108cc 1461

at Workshop m/s Tong Luck Auto

Colour: M. Silver A/C: Insured / Std / NI / NA

of 160 Sin Ming Drive #07-01/06

Sp. Reading: 53270 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess: TBA

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: vehicle In

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: Newton 195/65R15

Remark: The veh had commenced its repair at the time of inspection.

	
N/S	O/S

R: Kapsen

Bal. or Market Value: \$42K

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

IDAC Accident Rpt: Consistent? : Yes or No

TOYO / YOKO or

GIA / PR Seen: Consistent? : Yes or No

Front R/Bal. 9 mm Rear R/Bal. 8 mm

Est. Repairs: days Res: Yes or No

L/Bal. 9 mm L/Bal. 8 mm

Lum Sum: % 3 Val.: Yes or No

D.O.A. 13/1/20 D.O.I. 13/2/20

CA / (REV) / REP. / 24 HRS

Survey held at

Date: Person Contacted:

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/3	\$2696.10 Car Insured (Red 2557-50, 4919)
RECEIVED 31 MAR 2020	
RECEIVED 17 MAR 2020	

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 3

1)

: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee: 200

2) 31/3 - typist

Add Fee: : Site Insp (\$)

Transportation:

Report Format: Merimen

: Interview (\$)

S + PS, SI

Lump Sum / I.B.F: 2696.10

: Tech. Invs (\$)

Photos

: Wheel and (\$)

Others: 11

TOTAL

211

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 19 February 2020 12:54 PM
To: Operation / Candy Ong; SUR
Subject: GBF 4508X-DOA: 13/1/2020 (AIG OD)

Dear Candy,

As instructed by our client , please proceed to repair the **insured vehicle GBF 4508X, (Excess S1400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

NOTE: NEED TO TAKE HEADLAMP DAMAHD PHOTOS.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***GBF4508X (6823282483SG)**
 OD
 Jan 13 2020 9:00AM
 [DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]
 Tong Luck Auto Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 19/02/2020 12:17 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1605.30) - GBF4508X - Claim Handler: Azlan, Syazairdina

Approved:1605,30:Authorise repair. Headlamp damage photos? Panel beating labour? Re-inspection to be done for damage check and supplementary items / labour with clear photos.

DOCUMENTS SUMMARY
 There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #08-16 Singapore 079120	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:		Date:	13 Feb 2020
<u>Preliminary Advice</u>			

Vehicle No	: GBF4508X	Accident Date	: 13/01/2020
Make	: MERCEDES-BENZ CITAN	Policy No.	: 0999995580
Assignment Date	: 13/02/2020	Excess	: S\$0.00
Date of Inspection	: 13/02/2020	Est. Duration of Repair	: 4.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,189.80
Revised Amount	:S\$	1,605.30
Check Items (Estimated)	:S\$	2,611.00
Total	:S\$	4,216.30

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	32,435.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,565.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Estimated cost of repair for repairing of vehicle no.: GBF4508X -- OD Claim

From: Chin, Lee-Ying
To: assignments, Admin-D (LKKAuto)
Cc: Lim, Kok-Chong
Sent: 2/13/2020 8:51:43 AM

Hi LKK,

Kindly assist to survey today, document will send to you later.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Operation / Candy Ong [mailto:operation@tlauto.com.sg]

Sent: Wednesday, February 12, 2020 3:37 PM

To: Chin, Lee-Ying

Subject: [EXTERNAL] Estimated cost of repair for repairing of vehicle no.: GBF4508X -- OD Claim

This message is from an external sender; be cautious with links and attachments.

Dear Lee Ying,

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop

Kindly arrange your surveyor to inspect the vehicle at an earlier date

Thanks & regards,

Candy Ong



Tong Luck Auto Pte Ltd

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	778Z
Vehicle Details	
Vehicle No.:	GBF4508X
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CITAN 108 CDI L 5MT 5DR
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	K9KE628D159240
Chassis No.:	WDF4156032U191735
Maximum Power Output:	-
Open Market Value:	\$22,395.00
Original Registration Date:	01 Nov 2016
First Registration Date:	01 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$1,120.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$48,302.00
COE Rebate Amount:	\$32,435.00
Total Rebate Amount:	\$32,435.00

The information contained herein is correct as at 13 Feb 2020

OK

ANNOUNCING AA Trust Automotive
as sgCarMart Premium Dealer for the 2nd Consecutive Year




Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

New 5 Years Renewal COE Toyota Airtis 1.6A.

2.98% P.A, \$0 Admin, \$0 Down,
Monthly \$488, 2 Years Warranty
Engine And Gearbox.
GV Credit StarAd



Post an Ad Advertiser Login Ways of Selling

Sort by Date Posted 20 results/page

Browse by Category

1 vehicles

mercedes benz citan 108

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
mercedes benz	citan 108	Any	Any	2017	Any	Any	Any	Available
	Mercedes-Benz Citan 108 CDI	\$45,800	\$6,490 /yr	06-Mar-2017	1,461 cc	54,000 km	Van	Available

Fuel Type: Diesel
1 Owner, Agent Unit, Low Mileage, Full Agent Service, Best Compact Delivery Van In Its Class, Where Power Meet Prestige, Deliver Goods In This Beautiful Mercedes Benz. Uncompromising Ride Quality With Great Cargo Space. Loan Trade In Welcome. Call Us For Details An...

Posted: 03-Feb-2020 Tags: 2017 Mercedes-Benz Citan, 2017 mercedes-benz citan, Mercedes-Benz Citan, mercedes-benz citan, Mercedes-Benz, Citan, citan, Used Mercedes-Benz

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

20 results/page

For old advertisements, view Expired ads

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used mercedes benz citan 108, mercedes benz citan 108 Singapore, used mercedes benz citan 108 Singapore, used mercedes benz citan 108, used vehicles Singapore or even buy used mercedes benz citan 108 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



COVER NOTE

Cover Note No. 100880547		Date 12 Feb 2020	
The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.			
SCHEDULE			
Policyholder	Daimler Fleet Management Singapore Pte Ltd		
Age Condition	N/A	Registration No	GBF4508X
Policy Type	COMPREHENSIVE COMMERCIAL MOTOR	Make/Model	Mercedes Benz Citan 108 CDI
Effective Date	1 Jan 2020	CC/Tonnage	0.63
Expiry Date	31 Dec 2020	Engine No	K9KE628D159240
Hire Purchase Company	NA	Chassis No	WDF4156032U191735
		Year of Registration	2016
			
This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.			
Usage of vehicle only for the following purposes:			
<ol style="list-style-type: none"> Use only for social, domestic and pleasure purposes and for the Policyholder's business. Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes. 			
Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.			
The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.			
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)			
CERTIFICATE OF INSURANCE			
I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)			

Issued at SINGAPORE

AIG ASIA PACIFIC INSURANCE PTE. LTD.

IMPORTANT NOTICE
THIS COVER NOTE IS VALID FOR
60 DAYS FROM THE FIRST DAY OF
THE POLICY PERIOD.



 Authorised Representative

SSPYTP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2020 18:16
Date Of Accident	13/01/2020 09:45
Exact Location Of Accident	KJE(PIE) BEFORE PIE(CHANGI) EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF4508X
Insured/Policyholder	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No	1XXXXX778Z
Email Address	KATHRYN.ADRIANO@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68498118
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	CITAN 108 CDI L 5MT 5DR
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	
Driver	
Name of Driver	MUHAMAD FAEZ BIN HUSSIN
NRIC No	SXXXX483D
Date Of Birth	10/11/1991
Occupation	OUTDOOR
Date Of Driving Pass	24/04/2017
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88111940
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MAZLAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was traveling along KJE(PIE) on the 2nd lane from the right. Traffic was heavy at that point of time. Only right lane was moving. So i change lane to the right lane. Car SLQ4335B in front of me made a sudden braking. I managed to brake but could not stop on time and collided onto the rear of car SLQ4335B. Damages to my vehicle were on the front portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ4335B
Vehicle Make/Model/Colour	TOYOTA / VIOS 1.5E CVT
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	ONG BOON CHIAN
NRIC/Passport Number	SXXXX806F
Contact Number	97960286
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

**VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD FAIZAL BIN PABILA**

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

13/1/2020

ACCIDENT STATEMENT (2000 characters)

I was traveling along KJE(PIE) on the 2nd lane from the right. Traffic was heavy at that point of time. Only right lane was moving. So i change lane to the right lane. Car SLQ4335B in front of me made a sudden braking. I managed to brake but could not stop on time and collided onto the rear of car SLQ4335B. Damages to my vehicle were on the front portion. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

13 January 2020 at 2:13 PM

Date/Time:

13 January 2020 at 2:13 PM



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE
ACCIDENT DATE : 13/01/2020

*Not with work
Return by pain*

ESTIMATE

NO : QUOT202001-000038(00)
DATE : 12/02/2020
POLICY NO : 999995580
VEH REG NO : GBF4508X
MAKE/MODEL : MERCEDES BENZ CITAN 108
CDI L 5MT 5DR
CHASSIS NO : WDF4156032U191735
ENGINE NO : K9KE628D159240
REG. DATE : 0

Estimate Repair Cost to Vehicle No : GBF4508X

*3-4 days
Fax 62564315*

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Support Panel	1	480.00 <i>SVC</i>	480.00 <i>?X</i>
2 Front grille	1	175.00 <i>SVC</i>	175.00 <i>?X</i>
3 Front grille support	1	120.00 <i>CSG</i>	120.00 <i>?V</i>
4 Front grille centre logo	1	58.00 <i>CM</i>	58.00 <i>✓</i>
5 Headlamp assy - RH / LH	2	285.00 <i>cls m/om</i>	570.00 <i>✓</i>
6 Front bumper	1	880.00 <i>B</i>	880.00 <i>✓</i>
7 Front bumper reinforcement	1	450.00 <i>Bu</i>	450.00 <i>?✓</i>
8 Front bumper reinforcement cover	1	285.00 <i>SVC</i>	285.00 <i>?X</i>
			3,018.00
		Add 10%	301.80
			3,319.80
SPECIAL NET			
9 Front number plate	1	40.00 <i>CM</i>	40.00 <i>✓</i>
			40.00
LABOUR			
10 To remove and refit air-co condenser, radiator and refill air-con gas	1	150.00	150.00 <i>?X</i>
11 To check and rectify wiring system	1	80.00	80.00 <i>200</i>
12 To panel beat and repair front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00 <i>?H00</i>
13 To putty and spray paint on affected areas	1	800.00	800.00 <i>2000</i>
		5253.60	1,830.00
		TOTAL	S\$ 5,189.80
		ADD GST @ 7%	363.29
		GRAND TOTAL	S\$ 5,553.09

LKK Auto Consultants hence notify the Repairer of the following:

SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED FIFTY-THREE AND CENTS NINE ONLY

- To resurvey before/after repair completion
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ESTIMATE

NO : QUOT202001-000038(00)
DATE : 12/02/2020
POLICY NO : 999995580
VEH REG NO : GBF4508X
MAKE/MODEL : MERCEDES BENZ CITAN 108
CDI L 5MT 5DR
CHASSIS NO : WDF4156032U191735
ENGINE NO : K9KE628D159240
REG. DATE : 0

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 13/01/2020

Fn
[Signature]

13/2/2020

Not Withheld

Return by 84 paint

3-4 days
fax 62564315

Estimate Repair Cost to Vehicle No : GBF4508X

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Support Panel	1	480.00	480.00
2 Front grille	1	175.00	175.00
3 Front grille support	1	120.00	120.00
4 Front grille centre logo	1	58.00	58.00
5 Headlamp assy - RH/LH	2	285.00	570.00
6 Front bumper	1	880.00	880.00
7 Front bumper reinforcement	1	450.00	450.00
8 Front bumper reinforcement cover	1	285.00	285.00
<i>Front reinforcement bracket</i>		<i>58/- (A)</i>	
		Add 10%	301.80
			3,319.80
SPECIAL NET			
9 Front number plate	1	40.00	40.00
LABOUR			
10 To remove and refit air-co condenser, radiator and refill air-con gas	1	150.00	150.00
11 To check and rectify wiring system	1	80.00	80.00
12 To panel beat and repair front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00
13 To putty and spray paint on affected areas	1	800.00	800.00
			1,830.00
		TOTAL	S\$ 5,189.80
		ADD GST @ 7%	363.29
		GRAND TOTAL	S\$ 5,553.09


SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED FIFTY-THREE AND CENTS NINE ONLY

Handwritten calculations:
 $\$ 2,696.10$
 $\underline{XS \quad 1,400.00}$
 $\$ 1,296.10$
 $\underline{7\% \quad 90.73}$
 $\$ 1,386.83$

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

[Handwritten Signature]



明義汽車私人有限公司
MIN GHEE AUTO PTE LTD

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

TAX INVOICE

INVOICE NO. 8173583

DATE	14/02/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	GBF4508X	OUR REF.	54786

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: TONGLUC1 TIME:10:09
TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722
575722
Telephone No : 62500088

ROUTE
SM1

DELIVER TO:
TONG LUCK AUTO PTE LTD
160, SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA415 885 02 01	TRIM BUMPER	4B-1B	1 PC	880.00	880.00
2 MBA415 826 03 01	HEADLAMP	6B8-5C	1 PC	285.00	285.00
3 MBA415 885 00 48	CROSS MEMBER	3B-5C	1 PC	450.00	450.00
4 MBA415 885 02 16	SUPPORT BEAM	3B-5B	1 PC	120.00	120.00
5 MBA207 817 03 16	LOGO	1B-03E	1 PC	58.00	58.00
6 MBA415 882 00 14	BRACKET	1B-07F	1 PC	58.00	58.00

TOTAL	SIN	1,851.00
ADD GST	7%	129.57
AMOUNT DUE	SIN	1,980.57

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046
Account No.: 503-309-511-3
*Please send a screen shot of your payment/
transfer confirmation to
account@minghee.com

Exclusive Distributor
EDK
Stockists

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

SIGN & COMPANY'S STAMP

[Signature]



DATE
ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jan 2020		13 Feb 2020 14:49 Edit Adj Rpt	S\$2,696.10 Edit Estimates	S\$2,696.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. , Co. Reg. No.: 199803778Z, Tel: +6588111940								
Vehicle Reg. No.:	GBF4508X	Date of Loss:	13/01/2020 09:00 - :59 [38 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 6823282483SG	Policy/Cover Note No.:	0999995580 (Comprehensive)						
		Excess:	S\$1,400.00						
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syzairdina] syzairdina.azlan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/02/2020]								
Driver/Custodian:	MUHAMAD FAEZ BIN HUSSIN (28 / Male) , NRIC: S9140483D, Tel: +6588111940 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (31/03/2020): Alert - Adj Mandate Approved (S\$2696.10) - GBF4508X - Claim Handler: Azlan, Syz... AIG_SG (19/02/2020): Alert - Adj Mandate Approved (S\$1605.30) - GBF4508X - Claim Handler: Azlan, Syz... AIG_SG (18/02/2020): GBF4508X / OD / 13/01/2020 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF4508X (68232824835G)

OD

Jan 13 2020 9:00AM

[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.]

Tong Luck Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	14/02/20 08:52	Adjuster Immediate Advice							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
2	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
3	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
4	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
5	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
6	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
7	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
8	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
9	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
10	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
11	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
12	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
13	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
14	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
15	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
16	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
17	14/02/20 08:55	General View							Load JPG	<input checked="" type="checkbox"/>	
18	16/03/20 11:31	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
19	16/03/20 11:31	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
20	16/03/20 11:31	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
21	16/03/20 11:31	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
22	16/03/20 11:31	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
23	16/03/20 11:31	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
24	16/03/20 11:31	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
25	16/03/20 11:31	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
26	16/03/20 11:31	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	14/02/20 08:57	Singapore Accident Statement							Load PDF		
2	14/02/20 08:58	LTA							Load PDF		
3	14/02/20 08:58	SG CAR MART							Load PDF		
4	14/02/20 08:58	Driver's Driving License							Load PDF		
5	14/02/20 08:58	MARK ESTIMATE							Load PDF		
6	17/02/20 11:37	COVER NOTE							Load PDF		
7	17/03/20 11:10	FINAL MARKING							Load PDF		
8	20/03/20 13:17	Parts Invoice							Load PDF		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
9	02/04/20 12:40	Supplementary		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/01/20 18:47	Accident Statement		Load HTM
2	12/02/20 15:02	Addendum Sheet		Load TIF
3	12/02/20 15:03	Accident Statement Addm. #1		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
11	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
12	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
13	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
14	13/01/20 18:21	Accident Photo		Load JPG <input checked="" type="checkbox"/>
15	13/01/20 18:21	Identification Card		Load JPG <input checked="" type="checkbox"/>
16	13/01/20 18:21	Identification Card		Load JPG <input checked="" type="checkbox"/>
17	13/01/20 18:21	Driving License		Load JPG <input checked="" type="checkbox"/>
18	13/01/20 18:21	Driving License		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	13/01/20 18:23	Sketch Plan		Load TIFF
2	13/01/20 18:23	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>
3	13/01/20 18:23	Sketch Plan #3		Load TIFF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CS/AIG20002531/KVD3E2

Date: 02/04/2020

REFERENCE

Insured/Claimant:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.	Policy No:	0999995580
Date of Loss:	13/01/2020	Nature of Claim:	OD
		Claim No:	6823282483SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF4508X	Engine No:	K9KE628D159240
Make & Model:	MERCEDES-BENZ CITAN, 1.5 D 109CDI (M)	Chassis No:	WDF4156032U191735
Reg. Date:	01/11/2016 (Man. Year: 2016)	Odometer:	53270 km
Colour:	Metallic Silver		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	S\$42,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 9 mm	Rear Left Side:	KAPSEN 8 mm
Front Right Side:	Neuton 9 mm	Rear Right Side:	KAPSEN 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,423.60	2,076.10	1,347.50	39.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	620.00	1,210.00	66.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,253.60	2,696.10	2,557.50	48.68
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	3,853.60	1,296.10	2,557.50	66.37
+ GST 7.00/7.00% (S\$)	269.75	90.73	179.02	66.37
Nett Amount (S\$)	4,123.35	1,386.83	2,736.52	66.37

INSPECTION

Date of Assignment: 13/02/2020
Date Inspected: 13/02/2020 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUPPORT PANEL (WCP)	Serviceable	480.00 F	*- F	
2	1		*FRONT GRILLE (WCP)	Serviceable	175.00 F	*- F	
3	1		*FRONT GRILLE SUPPORT (WCP)	Cracked	120.00 F	*120.00 F	
4	1		*FRONT GRILLE CENTRE LOGO (WCP)	Cracked	58.00 F	*58.00 F	
5	1		*HEADLAMP ASSY - RH / LH (WCP)	O/S Mtg Cracked	570.00 F	*285.00 F	
6	1		*FRONT BUMPER (WCP)	Bent	880.00 F	*880.00 F	
7	1		*FRONT BUMPER REINFORCEMENT (WCP)	Buckled	450.00 F	*450.00 F	
8	1		*FRONT BUMPER REINFORCEMENT COVER (WCP)	Serviceable	285.00 F	*- F	
9	1		*FRONT REINFORCEMENT BRACKET (WCP)	Bent	58.00 F	*58.00 F	
10	1		*FRONT NUMBER PLATE	Cracked	40.00 FS	*40.00 FS	
					Sub Total (S\$)	3,116.00	1,891.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	307.60	185.10
					Total Parts (S\$)	3,423.60	2,076.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT AIR-CON CONDENSER, RADIATOR AND REFILL AIR-CON GAS	New	150.00	0.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	800.00	200.00
4	TO PANEL BEAT AND REPAIR FRONT CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	800.00	400.00
Gross Labour Cost (\$\$)			1,830.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >