



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tllauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
TEL : 5419 3000 FAX : 6415 3723

YOUR REF NO :
CLAIM TYPE : OWN DAMAGE *Not authorized*
ACCIDENT DATE : 13/01/2020 *Resurvey by paint*

ESTIMATE

NO : QUOT202001-000038(00)
DATE : 12/02/2020
POLICY NO : 999995580
VEH REG NO : GBF4508X
MAKE/MODEL : MERCEDES BENZ CITAN 108
CDI L 5MT 5DR
CHASSIS NO : WDF4156032U191735
ENGINE NO : K9KE628D159240
REG. DATE : 0

Estimate Repair Cost to Vehicle No : GBF4508X

3-4063
For 62564315

Description	Quantity	Unit Price	Amount
		\$S	\$S
PARTS			
1 Support Panel	1	480.00	480.00 ?
2 Front grille	1	175.00	175.00 ?
3 Front grille support	1	120.00	120.00 ?
4 Front grille centre logo	1	58.00 <i>CM</i>	58.00 ✓
5 Headlamp assy - RH / LH	2 <i>o/s original</i>	285.00	570.00 ✓
6 Front bumper	1	880.00 <i>R</i>	880.00 ✓
7 Front bumper reinforcement	1	450.00	450.00 ?
8 Front bumper reinforcement cover	1	285.00	285.00 ?
			3,018.00
		Add 10%	301.80
			3,319.80
SPECIAL NET			
9 Front number plate	1	40.00 <i>CM</i>	40.00 ✓
			40.00
LABOUR			
10 To remove and refit air-co condenser, radiator and refill air-con gas	1	150.00	150.00 ?
11 To check and rectify wiring system	1	80.00	80.00 <i>201</i>
12 To panel beat and repair front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00 ?
13 To putty and spray paint on affected areas	1	800.00	800.00 <i>201</i>
			1,830.00
		TOTAL	\$S 5,189.80
		ADD GST @ 7%	363.29
		GRAND TOTAL	\$S 5,553.09

SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED FIFTY-THREE AND CENTS NINE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FOR TONG LUCK AUTO PTE LTD
[Signature]
AUTHORISED SIGNATURE