

TK Lee Automotive Pte Ltd

TK LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER FOUR

SINGAPORE 038986

SMH2515Y

ESTIMATE

DATE : 13.02.2020

VEHICLE NO : SJK6175M

MAKE/MODEL : TOYOTA VIOS

ACC DATE : 08.02.2020

Not Almt
d/s #7200
12 days
the price of the
13/2/20

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	SS	SS
1	1 REAR WINDSCREEN MOULDING	79.30	79.30
2	1 REAR BOOT	665.90	665.90
3	2 REAR BOOT HINGE RH/LH	68.50	137.00
4	1 REAR BOOT RUBBER	162.84	162.84
5	1 REAR BOOT LOCK 145.00	289.50	289.50
6	1 REAR BOOT LOCK CATCH	48.85	48.85
7	2 REAR BOOT STOPPER	8.90	17.80
8	1 REAR BOOT MOULDING	286.95	286.95
9	1 REAR BOOT EMBLEM LOGO	42.60	42.60
10	1 REAR BOOT EMBLEM VIOS	48.85	48.85
11	1 REAR BOOT EMBLEM E	30.94	30.94
12	2 REAR TAILLAMP RH/LH	481.65	963.30
13	2 REAR TAILLAMP SIDE HOLDER CLIP	9.80	19.60
14	2 REAR TAILLAMP PANEL HOUSING RH/LH	115.60	231.20
15	1 REAR BUMPER	459.75	459.75
16	2 REAR BUMPER REFLECTOR RH/LH	106.25	212.50
17	2 REAR BUMPER BRACKET RH/LH	95.50	191.00
18	2 REAR BUMPER SIDE HOLDER RH/LH	82.50	165.00
19	2 REAR BUMPER SIDE RETAINER RH/LH	89.65	179.30
20	1 CENTRE EXHAUST PIPE	899.50	899.50
21	1 REAR EXHAUST BOX	569.05	569.05
22	1 REAR EXHAUST BOX HEAT SHEILD	162.80	162.80
23	1 REAR EXHAUST BOX CHORME PIPE	199.80	199.80
24	5 REAR EXHAUST MOUNTING	42.60	213.00
25	1 REAR END PANEL 645.00	777.25	777.25
26	1 REAR END PANEL GARNISH	89.65	89.65
27	1 REAR SPARE TYRE PANEL	781.65	781.65
28	2 REAR SPARE TYRE PANEL SIDE EXTENSION RH/LH	214.65	429.30
29	1 REAR SPARE TYRE PANEL FOAM CENTRE	110.35	110.35
30	2 REAR SPARE TYRE PANEL FOAM RH/LH	126.20	252.40
31	1 REAR SPARE TYRE PANEL CARDBOARD	202.60	202.60
32	1 REAR SPARE TYRE SCREW CARRIER	39.20	39.20
33	1 REAR CHASIS MEMBER RH	458.60	458.60
34	2 REAR FENDER RH/LH	828.50	1,657.00

n/sa o/saue

T K LEE AUTOMOTIVE PTE.LTD

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
35	2 REAR FENDER INNER TRIM RH/LH	286.50	573.00
36	2 REAR FENDER LOWER SHIELD RH/LH	58.50	117.00
			11,764.33
		7035.88 LESS 25%	2,941.08
			8,823.25

SPECIAL NETT ITEMS

1	1 (SET) REAR WINDSCREEN SPONGE TAPE	20.00	20.00
2	1 (SET) REAR WINDSCREEN SEALANT	80.00	80.00
3	1 (SET) REAR INNER TRIM CLIP	45.00	45.00
4	1 (SET) REAR BUMPER REVERSE SENSOR	280.00	280.00
5	1 (SET) REAR BUMPER CLIP	35.00	35.00
			460.00

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT / WELD REAR PANEL, REAR SPARE TYRE PANEL, REAR CHASIS MEMBER RH, REAR FENDER RH/LH AND REPLACE ACCIDENT PARTS	2,500.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	1,300.00
3	TO CHECK WIRING	30.00
4	TO REMOVE, REFIX REAR WINDSCREEN	120.00
5	TO REMOVE, REFIX CUSHION AND INNER TRIM	120.00
6	TO REMOVE, REPLACE REVERSE SENSOR	80.00
7	TO REMOVE, REPLACE CENTRE EXHAUST PIPE AND REAR EXHAUST BOX	180.00
8	TO TUFF KOTE	150.00
9	TO REMOVE, REFIX FUEL TANK	150.00
	Total :	4,630.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 13,913.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-527681
S.W-295
L-3530
9/10/91
202
721