

2200000

ASS. REC. BY:

REF:

CS/CTI20002546/R1vd3^{SP}

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Ben Tang

of CTI

Date/Time: 13/2/2020 @ 9.55am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJG 9678E

Insured:

SGW 6827M

at Workshop m/s

Xinya Auto

Tel:

6270 3481

of

BLK 1002 Bukit Merah Lane 3 # 01-75

Policy No:

DMPKSN30593719022

Claim No:

SNM20D200748/SGW6827M/BEN

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7/02/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10.50am @ 13/2/2020

Person Contacted:

May

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	
	SGW 6827M - NBA / NC 20002258 / Y		DOA: 7/2/2020
	SJG 9678E - NBA / NC 20002258 / Y		DOA: 7/2/2020

ASS. REC. BY: Pame

REF: C12

0552

108 XPRY: 2028 July

ASSIGNMENT

From: _____ Date: 18.2.2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To / Inspection Vehicle No: SGW 6827M

at Workshop m/s Xinya Auto

of BIK1002 Bukit Muih Law 3 #0175

Insured: _____


Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ap"

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SG 9678E Yr Regn: 2008 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda CIVIC 1.6L VTI A c.c. 1595

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 138938 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 54 MFD462085201970

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or _____

Brake: Order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 01/02/2020 D.O.I. 18/02/2020

Survey held at Xinya

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>24/3/20</u>	<u>finalised (LS) 81,200 / 4 days contract (Red 2002.96, 5490)</u>

RECEIVED 26 MAR 2020

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to? 26/3 - typst

Report Format: MRimen

Lump Sum / LBS: (\$) 17000

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2020		25 Mar 2020 18:25 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	YU WEIHAO
Vehicle Reg. No.:	SJG9678E
Claim Type:	TP / SNM20D200748
Vehicle Reg. No. (Insured):	SGW6827M
Date of Loss:	07/02/2020 08:00 - :59
Policy/Cover Note No.:	DMPCSN30593719022
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3, 159719 Bukit Merah - Tel: 6270 3481
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/04/2020]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Thursday, 13 February 2020 9:55 AM
To: 'assignments'
Subject: FW: OUR REF: SNM20D200748/SGW6827M/BEN & YOUR REF: SGW6827M - pre-inspect for SJG 9678E involving SGW6827M along AYE TWDS TUAS AFTER JURONG TOWN HALL ON 07.02.20.

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SGW6827M.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Xinya Auto Services <xinyaauto@singnet.com.sg>
Sent: Wednesday, February 12, 2020 9:19 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200748/SGW6827M/BEN & YOUR REF: SGW6827M - pre-inspect for SJG 9678E involving SGW6827M along AYE TWDS TUAS AFTER JURONG TOWN HALL ON 07.02.20.

Hi,

Pls. arrange for LKK to inspect

Thank you
Regards

From: Ben Tang [<mailto:Ben.Tang@sg.cntaiping.com>]
Sent: Wednesday, February 12, 2020 9:11 AM
To: xinyaauto@singnet.com.sg
Cc: Lim Shu Min <shumin.lim@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200748/SGW6827M/BEN & YOUR REF: SGW6827M - pre-inspect for

SJG 9678E involving SGW6827M along AYE TWDS TUAS AFTER JURONG TOWN HALL ON 07.02.20.

WITHOUT PREJUDICE

Dear Sir,

We refer to your email dated 11 February 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, February 12, 2020 8:44 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>; xinyaauto@singnet.com.sg
Cc: Lim Shu Min <shumin.lim@sg.cntaiping.com>

Subject: OUR REF: SNM20D200748/SGW6827M/BEN & YOUR REF: SGW6827M - pre-inspect for SJG 9678E involving SGW6827M along AYE TWDS TUAS AFTER JURONG TOWN HALL ON 07.02.20.

Dear Ben ,

Please conduct PRS SGW6827M soonest possible.

Note : officer in charge – Ben Tang; DID: 63896175

Dear Sirs,

*** *Kindly quote our reference number when replying.*

Thank You.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

TEL: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Xinya Auto Services <xinyaauto@singnet.com.sg>

Sent: Tuesday, February 11, 2020 9:09 AM

To: DL-CLAIMS <claims@sg.cntaiping.com>

Subject: FW: pre-inspect for SJG 9678E involving SGW6827M along AYE TWDS TUAS AFTER JURONG TOWN HALL ON 07.02.20.

From: Xinya Auto Services [<mailto:xinyaauto@singnet.com.sg>]

Sent: Tuesday, February 11, 2020 9:08 AM

To: 'eclaims@sg.cntaiping.com' <eclaims@sg.cntaiping.com>

Subject: pre-inspect for SJG 9678E involving SGW6827M along AYE TWDS TUAS AFTER JURONG TOWN HALL ON 07.02.20.

Hi, Sir / Mdm

Pls. arrange for pre-inspection

Thank you

Regards



Virus-free. www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/02/2020 12:49
Date Of Accident	07/02/2020 08:25
Exact Location Of Accident	AYE TOWARDS TUAS AFTER JURONG TOWN HALL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJG9678E
Insured/Policyholder	
Name Of Registered Owner	YU WEIHAO
NRIC No	SXXXX055C
Email Address	YAWEHA@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91768860
Alternative Phone No	OTHERS-91768860

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110934092
Cover Note Number	

Driver

Name of Driver	YU WEIHAO
NRIC No	SXXXX055C
Date Of Birth	14/02/1964
Occupation	INDOOR
Date Of Driving Pass	23/06/2008
Driving Experience	11 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91768860
Fax Number	
Contact Number	OTHERS-91768860
Email Address	YAWEHA@YAHOO.COM

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

XINYA AUTO SERVICE PTE LTD

Add: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719
 E-mail : xinyauto@singnet.com.sg
 Tel: 6270 3481 Fax: 6278 7522

Date : 07-Jan-19

Address : MR YU WEI HAO
 BLK 13 REDHILL CLOSE
 # 06-57
 SINGAPORE 151013

Reference : TP 1191/01/19
 Vehicle No : SJG 9678E
 Make/Model : HONDA CIVIC
 Insurance Co. : EQ INSURANCE

RE : QUOTATION REPAIRS TO SJG 9678E FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>AMT \$</u>
1) REAR BUMPER <i>de/</i>	1	\$ 730.00
2) REAR BUMPER RETAINER <i>LH-X/RH-X</i>	2 <i>1 pc</i>	\$ 29.20 <i>14.60</i>
3) REAR BUMPER CLIPS <i>na/</i>	10	\$ 38.00
4) TAIL LAMP <i>sc/</i>	1	\$ 308.70
5) END PANEL <i>repair</i>	1	\$ 300.50 <i>X R</i>
6) END PANEL GARNISH <i>X sc</i>	1	\$ 56.10 <i>X</i>
7) REAR MUDFLAP <i>cut/</i>	1	\$ 79.50
8) EXHAUST BOX <i>X sc</i>	1	\$ 451.30 <i>X</i>
9) EXHAUST BOX RUBBER HOLDER <i>X sc</i>	1	\$ 35.40 <i>X</i>

1170.80
20%
936.64

LIST PRICE TOTAL \$ 2,028.70
 LESS DISCOUNT 20% \$ 405.74
 LIST PRICE TOTAL AFTER LESS \$ 1,622.96

936.64

10) REVERSE SENSOR *na/* 180.00 1 \$ 180.00 *180*
 NETT PRICE TOTAL \$180.00

1010.00
2126.64
20%
1701.31

TOTAL PARTS COST

\$1,982.96

4/5-1,700 *4 days*

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE REAR BUMPER, TAILLAMP AND TO PANEL BEAT CUT & WELD END PANEL	\$ 600.00 <i>350</i> (3 days)
2)	TO PUTTY & SPRAY PAINT REAR BUMPER, END PANEL & OTHER AFFECTED AREA.	\$ 600.00 <i>1010</i> (3 PANEL)
3)	TO CHECK & RECTIFY WIRING & REPLACE REVERSE	\$ 120.00 <i>60</i>

SENSOR.

- 4) TO REMOVE & REFIT REAR EXHAUST BOX \$ 120.00 X 1.14
- 5) TUFF KOTE \$ 280.00 X 1.14

LABOUR TOTAL

\$ 1,720.00

TOTAL ESTIMATED REPAIR COST

\$ 3,702.96

3522.96

[Handwritten signature]
18/02/2020
K. Hsu

Up 900/100 68

4 days

HS

18/02/2020 @ 1200

Revy after repair

LHK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAUTO)

From: Xinya Auto Services <xinyaauto@singnet.com.sg>
Sent: Tuesday, 24 March 2020 5:16 PM
To: Rasul (LKKAUTO)
Subject: FW: SJG 9678E DOA : 07/02/2020

4DAYS

From: Xinya Auto Services [mailto:xinyaauto@singnet.com.sg]
Sent: Tuesday, March 24, 2020 4:15 PM
To: 'Rasul (LKKAUTO)' <Rasul@lkkauto.com>
Subject: RE: SJG 9678E DOA : 07/02/2020

Hi, Rasul

Can we close at \$ 1700.00.

Thank you

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: Tuesday, March 24, 2020 9:23 AM
To: xinyaauto@singnet.com.sg
Subject: SJG 9678E DOA : 07/02/2020

Hi May,

Refer to attachment
Finalised amount is \$ 1,550 / 3 days of lump sum repair
Kindy confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



Virus-free. www.avg.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2020		25 Mar 2020 18:25 Edit Adj Rpt	S\$1,700.00 Edit Estimates	S\$1,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	YU WEIHAO		
Vehicle Reg. No.:	SJG9678E	Date of Loss:	07/02/2020 08:00 - :59 [138 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D200748	Policy/Cover Note No.:	DMPCSN30593719022
Vehicle Reg. No. (Insured):	SGW6827M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3, 159719 Bukit Merah - Tel: 6270 3481		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/04/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.


ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJG9678E (SNM20D200748)**
[SGW6827M]
TP
YU WEIHAO
Feb 7 2020 8:00AM
[-]
Xinya Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/20 08:19	General View	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI2002546/R1VD3S2

Date: 01/04/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30593719022
Claimant Vehicle No :	SJG9678E	Insured Vehicle No :	SGW6827M
Date of Loss:	07/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG9678E	Engine No:	R16A13006016
Make & Model:	HONDA CIVIC, 1.6 L VTI (A)	Chassis No:	JHMF46208S201970
Reg. Date:	22/07/2008 (Man. Year: 2008)	Odometer:	138938 km
Colour:	White		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,802.96	1,116.64	686.32	38.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,720.00	1,010.00	710.00	41.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,522.96	2,126.64	1,396.32	39.63
Approved Total (Overridden) (S\$)		1,700.00		
Nett Amount (S\$)	3,522.96	1,700.00	1,822.96	51.75

INSPECTION

Date of Assignment:	25/03/2020		
Date Inspected:	18/02/2020	Inspected At:	Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3 Singapore 159719
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2020)
Parts:	143	HONDA CIVIC 1.6 L VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG9678E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	730.00 FL	*730.00 FL
2	1		*REAR BUMPER RETAINER	N/s Serviceable/O/s Necessary	29.20 FL	*14.60 FL
3	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
4	1		*TAIL LAMP	Scratched	308.70 FL	*308.70 FL
5	1		*END PANEL	Repair	300.50 FL	*- FL
6	1		*END PANEL GARNISH	Serviceable	56.10 FL	*- FL
7	1		*REAR MUDFLAP	Cut	79.50 FL	*79.50 FL
8	1		*EXHAUST BOX	Serviceable	451.30 FL	*- FL
9	1		*EXHAUST BOX RUBBER HOLDER	Serviceable	35.40 FL	*- FL
10	1		*REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	2,208.70	1,350.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	405.74	234.16
Total Parts (\$\$)	1,802.96	1,116.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE REAR BUMPER, TAILLAMP AND TO PANEL BEAT CUT & WELD END PANEL.	New	600.00	350.00
2	TO PUTTY & SPRAY PAINT REAR BUMPER, END PANEL & OTHER AFFECTED AREA.	New	600.00	600.00
3	TO CHECK & RECTIFY WIRING & REPLACE REVERSE SENSOR.	New	120.00	60.00
4	TO REMOVE & REFIT REAR EXHAUST BOX.	New	120.00	0.00
5	TUFF KOTE.	New	280.00	0.00
Gross Labour Cost (S\$)			1,720.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >