

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SBT3189R
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

ATTN: Motor Claim Department

FAX: 65073849

Estimate No: ES2090139/YISHUN

Date: 13 Feb 2020

Policy No: 5071994847-04

Veh Reg No: SBT3189R

Make/Model: HONDA VEZEL 1.5X CVT

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 12/02/2020

TP Veh Reg No: SHC164A

Chassis No: RU11019281

Engine No: L15B3519295

Reg. Date: 05/06/2015

Estimate Repair Cost to Vehicle No : SBT3189R

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 REAR BUMPER	508.20	1 PC	508.20	✓
2 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
3 REAR TAILGATE	1,100.90	1 PC	1,100.90	✓
4 TAILGATE EMBLEM (VEZEL)	75.00	1 PC	75.00	✓
5 TAILGATE INNER LOCK	189.10	1 PC	189.10	✓
6 TAILGATE INNER RUBBER	96.80	1 PC	96.80	✓
7 REAR END PANEL	411.90	1 PC	411.90	✓
8 SMART KEY SENSOR	85.00	1 PC	85.00	✓
9 REAR WINDSCREEN GLASS MOULDING	131.80	1 PC	131.80	✓
			2,622.10	
		Less 20%	524.42	2,097.68
Special Net				
10 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
11 REVERSE SENSOR	200.00	1 SET	200.00	✓
12 REAR BUMPER BODY STICKER	80.00	1 PC	80.00	✓
13 TAILGATE FRAME RUBBER	40.00	1 PC	40.00	✓
			360.00	360.00
Labour				
14 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
15 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE ASSY, REAR TOP SPOILER, REAR WIPER, LOCK ASSY, CUT, WELD & RENEW REAR END PANEL, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	800.00	1 LA	800.00	850
16 PUTTY & RESPRAY ON REAR END PANEL, REAR SPARE TYRE COMPARTMENT, TAILGATE, REAR BUMPER SIDE PADS	800.00	1 LA	800.00	700
17 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	40.00	1 LA	40.00	✓
18 REMOVE & REFIX SMART KEY SENSOR & RESET LOCKING	80.00	1 LA	80.00	60
19 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,880.00	1,880.00

Total S\$ 4,337.68

Add GST @ 7% 303.64

Total Amount Payable S\$ 4,641.32

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: