

fcie

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

not allowed
over
2/5# 2350/?
3 days.
17/2/20
The 16 Attraction

Name of Insurance Company: M/S INDIA INSURANCE

DATE OF ACCIDENT : 07/02/2020

VEHICLE NO : SLL4404L

DEAR SIR / MADAM

NO	QTY	DESCRIPTION
1	1 PC	REAR BUMPER
2	10 PC	REAR BUMPER CLIPS
3	1 PC	REAR BUMPER RH RED REFLECTOR
4	1 PC	REAR END PANEL
5	1 PC	BOOTLID ? 792
6	1 PC	BOOTLID BADGE
7	1 PC	BOOTLID ATTRAGE EMBLEM
8	1 PC	BOOTLID MIVEC EMBLEM
9	1 PC	BOOTLID LOCK
10	1 PC	NUMBER PLATE LAMP CHROME GARNISH
11	1 PC	RH LICENCE LAMP
12	1 PC	TAILLAMP

2/pc	\$	708.00	✓
10	\$	40.00	✓
1	\$	25.00	X
1	\$	402.00	X
1	\$	828.00	✓
1	\$	41.00	✓
1	\$	25.00	✓
1	\$	48.00	✓
1	\$	206.00	✓
1	\$	318.00	✓
1	\$	48.00	X
1	\$	276.00	X

LESS 10%

\$ 2,965.00
\$ (296.50)
\$ 2,668.50

13	1 PC	NUMBER PLATE
14	1 PC	REVERSE SENSOR
15		REMOVE AND RENEW SENSOR
16		TUFF COAT
17		TO REMOVE AND RENEW REAR PARTS
18		WIRING CHECK (REAR)
19		SPRAY PAINTING

1	\$	40.00	X
1	\$	280.00	200
	\$	80.00	50
	\$	80.00	30
	\$	980.00	300
	\$	30.00	20
	\$	980.00	400
	\$	5,138.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part's prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

1000
P-2178
201
1960.20
1000.00
2960.20
20%
2368.16