

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 18-Feb-20

INSURANCE: _____

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA2098E

| DESCRIPTION | QTY | LIST PRICE | AMOUNT |
|---|-----|------------|--------------------|
| UNIT ASSY, HEADLAMP, RH (LED) <i>mainly work</i> | 1 | \$3,455.00 | \$3,455.00 |
| FRONT FENDER TOP GARNISH LEFT <i>distorted</i> | 1 | \$148.00 | \$148.00 |
| FRONT WINDSCREEN GLASS <i>crack</i> | 1 | \$1,627.30 | \$1,627.30 |
| FRONT WINDSCREEN GLASS MOULDING LOWER <i>new</i> | 1 | \$268.80 | \$268.80 |
| | | | |
| | | | |
| | | | |
| SUB TOTAL | | | \$5,499.10 |
| LESS 20% <i>25%</i> | | | \$1,099.82 |
| DISCOUNTED TOTAL | | | \$4,399.28 |
| | | | |
| | | | |
| FRONT WINDSCREEN GLASS SEALANT <i>new</i> SN | 2 | \$40.00 | \$80.00 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| SUB TOTAL | | | \$ 80.00 |
| | | | |
| | | | |
| | | | |
| ESTIMATE TOTAL | | | \$ 4,479.28 |
| will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance | | | |

✓
✓
✓
✓
5499.10
- 25%
4124.32

✓ 50

50 /

[Signature]
JKE Auto

P- 4124-32
AI- 50
4174-32