

ESTIMATE

Our Ref: AC2020008/OD/SGD333K-07.02.2020

Vehicle number: SGD333K

Vehicle Made & Model: PORSCHE CAYENNE TURBO

Items	Qty	Items	Cost \$
1	1	Front bonnet ✓ BT	4,200.00
2	1	Front bonnet badge ✓ new	220.00
3	1	Front bonnet lock X (R)	185.00
4	2	Front bonnet dampers - L/R @ 120 R/H only ✓ Jm 2/HX (svc)	240.00
5	2	Front bonnet hinges - L/R @ 160 R/H only ✓ CRM 2/HX (LR)	320.00
6	1	Front bumper ✓ CRA	980.00
7	1	Front bumper lower guard ✓ CRA	960.00
8	1	Front bumper fog lamp - RH - Lower ✓ mis	580.00
9	1	Front bumper side grille ✓ mis R/H	250.00
10	1	Front bumper side cover ✓ mis R/H	250.00
11	1	Front bumper L.E.D light ✓ CRA	750.00
12	1	Front bumper CTR grille X (svc)	330.00
13	1	Front bumper side pad X (svc)	160.00
14	1	Front bumper frame pad X (svc)	295.00
15	1	Front bumper side holder X (svc)	60.00
16	1	Front bumper side bracket ✓ BT R/H	120.00
17	1	Front bumper side retainer ✓ CRM R/H	65.00
18	1	Front bumper tow cover ✓ R/H mis	95.00
19	2	Front bumper PDC sensors @ 285 ✓ R/H (mis)	570.00
20	1	Front bumper PDC sensor wire harness ✓ CRA	670.00
21	1	Front bumper top beam X (svc)	180.00
22	1	Front bumper reinforcement X (R)	750.00
23	1	Front bumper top guide (supp top garnish) ✓ CRA	230.00
24	1	Front bumper stay X (svc)	120.00
25	1	Front fender - RH ✓ int	1,500.00
26	1	Front fender wheel arch garnish ✓ mis R/H	430.00
27	1	Front fender inner shield ✓ CRA R/H	350.00
28	10	Front fender inner shield clips @ 6 ✓ new	60.00
29	1	Front fender inner top cover ✓ serv R/H	310.00
30	1	Front fender inner panel ✓ int R/H	1,800.00
31	1	Front fender wheel housing X (R)	3,200.00
32	1	Front fender wheel housing extension X (R)	450.00
33	1	Front headlamp - RH ✓ CRA	5,200.00
34	1	Front headlamp seal ✓ new R/H	220.00
35	1	Front headlamp lower bracket ✓ CRA	185.00

36	1	Front	headlamp bulb		650.00
37	1	Front	headlamp bulb cover		120.00
38	1	Front	headlamp control unit - No. 1		600.00
39	1	Front	headlamp control unit - No. 2		1,150.00
40	1	Front	headlamp spray nozzle pen	✓ CRA	280.00
41	1 set	Front	headlamp kit	X (svc)	250.00
42	1	Front	support panel	X (R)	750.00
43	1	Front	support top garnish	X (RPT)	210.00
44	20	Front	support top garnish clips @ 6	✓ all	120.00
45	1	Front	shock absorber assy - RH	X (svc)	3,500.00
46	1	Front	sub frame assy	X (svc)	3,200.00
47	1	Front	sport wheel - RH	✓ (C.R.) R/H outy	4,200.00
48	1	Front	top arm	X (svc)	980.00
49	1	Front	lower arm	X (svc)	1,550.00
50	1	Front	knuckle arm	?	1,200.00
51	1	Front	wheel hub bearing	?	750.00
52	1		Washer tank	✓ CRA	280.00
53	1		Washer tank neck	✓ CRA	95.00
54	1		Washer tank motor	X (svc)	195.00
55	1		Air cleaner box assy	R/H ✓ CRA	780.00
56	1		Air cleaner duct - Inlet	? R/H	180.00
57	1		Air cleaner duct - Outlet	? R/H	180.00
58	1		Air intercooler	✓ CRA R/H	2,600.00
59	1		Air intercooler intake duct	? R/H	210.00
60	1		Air intercooler hose - Inlet	? R/H	450.00
61	1		Air intercooler hose - Outlet	? R/H	450.00
62	1		Air con condenser	X (svc)	1,600.00
63	1		Air con condenser intake duct	X (svc)	280.00
64	1		Radiator assy	X (svc)	1,200.00
65	1	Front	windshield assy	✓ CRA	1,250.00
66	2	Front	windshield side mouldings - L/R @ 180	X (svc)	360.00
67	1		Steering wheel	X (svc)	4,500.00
68	1		Steering wheel S.R.S	R/H ✓ (Bus)	3,500.00
69	1		Steering wheel clock sensor	✓ Jim R/H	750.00
70	1		Passenger S.R.S	✓ R/H (Bus)	3,600.00
71	1		Dashboard assy	✓ CRA	8,300.00
72	1		S.R.S control unit	✓ all	2,600.00
73	2	Front	safety belts @ 850	✓ Jim	1,700.00
74	2	Rear	safety belts @ 850	✓ Jim	1,700.00
Sub-total					82,555.00
Additional 10%					8,255.50
Total List					90,810.50

Special Nett Items

75	1 set	Front	windscreen sealant	✓	80.00 50
76	1	Front	tyre - RH	X (svc)	1,200.00
77	1		I.U bracket	✓ all	30.00 / 0
78	1 bot		Brake fluid	✓ all	50.00 20

Total Special Nett

1,360.00

Labour charges

79	To check front electrical wiring ✓	180.00	30
80	Towing charges ✓	200.00	70
81	To remove, refix front undercarriage ? photo	650.00	?
82	To check wheel alignment and ? <i>Align report</i>	120.00	60?
83	To remove, reinstall & reset A.B.S brake systems ✓	200.00	40
84	To remove, refix front A/C condenser & refill A/C gas R134A	180.00	80?
85	To remove, refix front dashboard ✓	450.00	180
86	To diagnos, erase fault memory after repair	450.00	} 250
87	To remove, refix & reset S.R.S systems ✓	580.00	
88	To respray painting and etc	2,000.00	1000
89	Panel beating, cut, weld remove & replacing above parts	3,000.00	300
Total Labour		<u>8,010.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

100,180.50

*Hidden, inaccessible damage parts shall be submitted through supplementary

*Not Authorized
 need to check (m.v)
 Excess \$3000
 Home ANN (IKK)
 (744) 8434 / 8531893
 Reming before paint / arrange after paint?
 P/P repair / H/s report?
 without purchase
 12/2/20
 6:15 pm
 need to Rivert #*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: