

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 18 Feb 2020

Preliminary Advice

Vehicle No	: SGD333K	Accident Date	: 07/02/2020
Make	: PORSCHE CAYENNE	Policy No.	: 28968500MPQ
Assignment Date	: 17/02/2020	Excess	: S\$3,000.00
Date of Inspection	: 17/02/2020	Est. Duration of Repair	: 11 days
Inspection At	: Automobile Integrated Management Pte Ltd (HQ) 28 Sin Ming Lane, #07-147 Midview City Singapore 573972		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s & o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	100,180.50
Revised Amount	:S\$	60,156.60
Check Items (Estimated)	:S\$	4,712.00
Total	:S\$	64,868.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	380,000.00
COE / PARF Rebate	:S\$	226,434.00
Salvage Value	:S\$	
Margin for Repair	:S\$	153,566.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.