

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S: LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388 FAX: 62962706
ATTN: Motor Claim Department \ CLAIMS

Estimate No: EST2000046
Date: 14 Feb 2020

Veh Reg No: GBD3035K
Make/Model: NISSAN NV200 DX 1.6
AT ABS AIRBAG 2WD
5DR LGV

Chasis No: VM20057257
Reg. Date: 04/09/2014
Your Ref No: GBE6358D

Claim Type: Third Party
Accident Date: 13/02/2020
TP Veh Reg No: GBE6358D

Ichenchuan

Estimate Repair Cost to Vehicle No :GBD3035K

Quantity	Description	List Price S\$	Amount S\$
Net Price			
1	1 PC FRT BUMPER <i>Deled</i>	695.20 ✓	
2	1 PC FRT BUMPER REINFORCEMENT <i>Best</i>	688.10 ✓	
3	1 PC FRT BUMPER SPONGE <i>incl</i>	326.30 107.20	
4	2 PC FRT BUMPER SIDE RETAINER <i>new</i>	46.80 ✓	
5	1 PC FRT SUPPORT PANEL <i>Regis</i>	730.00 +	
6	1 PC FRT GRILLE <i>incl</i>	356.10 ✓	
7	1 PC FRT GRILLE EMBLEM <i>new</i>	52.50 ✓	
8	1 PC FRT TOWING COVER <i>Deled</i>	21.00 ✓	
9	1 PC HEADLAMP RH <i>3 years</i>	685.90 ✓	546.40
10	1 PC HEADLAMP LH <i>3 years</i>	685.90 ✓	546.40
11	1 PC BONNET <i>Deled</i>	864.20 ✓	
12	2 PCS BONNET HINGE <i>new</i>	87.40 +	
13	1 PC BONNET LOCK <i>new</i>	140.20 +	
14	1 PC HEADLAMP RH LOWER <i>garish torn</i>	388.50 torn ✓	
15	1 PC HEADLAMP LH LOWER <i>garish torn</i>	388.50 torn ✓	
16	1 PC AIR CONDENSER TOP COVER <i>Hi new</i>	68.00 X	
		6,224.60	
Less 10%		622.46	5,602.14
Special Net			
17	1 SET FRT BUMPER CLIPS <i>new</i>	48.00 30	
18	1 SET FRT GRILLE CLIPS <i>new</i>	40.00 20	
19	1 PC FRT NUMBER PLATE <i>Best</i>	50.00 ✓	
20	1 PC AIR CON CONDENSER <i>Best</i>	896.90 758	
21	1 SET AIR CONDENSER TOP COVER CLIPS <i>new</i>	20.00 +	
22	1 PC RADIATOR <i>Hi new</i>	829.90 +	
Advertisement Sticker <i>new</i>		1,884.80	1,884.80
Labour			

4700.90

4052.52

350 280

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S: LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388 FAX: 62962706

ATTN: Motor Claim Department \ CLAIMS

Estimate No: EST2000046

Date: 14 Feb 2020

Veh Reg No: GBD3035K

Make/Model: NISSAN NV200 DX 1.6
AT ABS AIRBAG 2WD
5DR LGV

Chasis No: VM20057257

Reg. Date: 04/09/2014

Your Ref No: GBE6358D

Claim Type: Third Party

Accident Date: 13/02/2020

TP Veh Reg No: GBE6358D

Estimate Repair Cost to Vehicle No :GBD3035K

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
23	1 TO CHECK WIRING	50.00 30	
24	1 TO REFILL AIRCON GAS	120.00 100	
25	1 TO SPRAY UNDERSEAL	100.00 X	
26	1 (FRONT) TO SPRAY PAINTING	800.00 650	
27	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 650	
		2,070.00	2,070.00
	Total		SS 9,556.94
	Add GST @ 7%		668.99
	Total Amount Payable		SS 10,225.93

TOTAL: SINGAPORE DOLLAR TEN THOUSAND TWO HUNDRED TWENTY FIVE AND CENTS
NINETY THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 6620.52 Adnan Lj
L/S 53K. L/S 17/02/20.
0.5 Days.

53K