

Asher

新合利服務公司

Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

12 February 2020

Attn: Motor Claim Department
AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

Shen Yunting
c/o Sin Hup Lee Service Co.
Block 1005 Bukit Merah Lane 2 #01-20
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic Accident on 07 Feb 2020 at Jalan Tiong Redhil, involving vehicle SKD4849R / SMF7053R 2018 - KNAF 3416 MK 5020 704

Quotation for Repair Vehicle No: SMF7053R (Third Party Claim)

Quantity	Net Item	Lists price	
1	Rear Boot <i>bt</i>		\$ 1,297.00
1	Boot Logo <i>neu</i>		\$ 45.00
1	Boot Emblem Cerato <i>neu</i>		\$ 55.00
1	Boot Lock <i>X 800</i>		\$ 135.00 X
2	Boot Reflector <i>X 800</i>		\$ 1,216.00 X
1	Tail Lamp RH <i>neu</i>		\$ 675.00
1	Rear End Panel <i>bt</i>		\$ 378.00
1	Rear Bumper <i>cut</i>		\$ 688.00
1	Rear Bumper Lower <i>de</i>		\$ 287.00
1	Rear Reinforcement <i>neu</i>		\$ 324.00
2	Rear Bumper Lamp <i>X 800</i>		\$ 362.00 X

- 2 Rear Bumper Lamp Garnish ~~X~~ *sn*
2 Rear Bumper Retainer ~~X~~ *sn*

3749
20%
2999.20

\$	84.00	X
\$	88.00	X
\$	5,634.00	
Less 20%	\$	1,126.80
\$	4,507.20	

- S Nett
1 Set Reverse Sensor *4nw*
1 Set Reverse Camera ~~X~~ *sn*

200
\$ 250.00 *200?*
\$ 480.00

Labour

- 1 To cut, weld Rear Panel, remove and re-fix damaged parts, straighten and realign affected areas.
2 To spray paint affected areas
3 To remove and refix luggage compartment and side garnish
4 To install Reverse Sensor and Camera & check water seepage
5 To rust proof affected area

1260
\$ 480.00 ~~450~~
\$ 850.00 *600*
\$ 80.00 *60*
\$ 150.00 *60*
\$ 80.00 *60*

Total Amount \$ 6,877.20

Kindly arrange your surveyor to survey my vehicle.
We look forward to hear from you soon.
Thank you.

Yours Faithfully
Mr Wong
81122116

2999.20
200.00
1260.00
4459.20
20%
3567.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

R. Abu
Hp 90010068

6 days

4/3

14/02/2020

@ 1510

Re-survey after repair

4/3-3,500

6 days