

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM20002701/Epa3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: SAW THENG		Date: 01-06-2020 Code: ASM			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YP 2593L	Veh. Inspected	FBA 1955J	
	Policy No.	P1790744	Coverage (\$)	0.00	
	Claim No.	S0M02FN1	Excess (\$)	0.00	
	Assign From	SAW THENG	Assign Date	17/02/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CB400	c.c	399	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	JH2NC39965M100207	Colour	RED	
	Odometer	164815	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	120/60ZR17	PIRELLI	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	160/60ZR17	PIRELLI	5 mm	
	L/H Rear Tyre			mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/02/2020	Inspection Date	18/02/2020	
	Survey held at	KIM KOCK MOTOR PTE LTD BLK 27A JURONG PORT ROAD #01-19 SINGAPORE 619101			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				