

FASTECH AUTO PTE LTD

BLK1 KAKI BUKIT AVE 6

#01-46,48,50 AUTOBAY

SINGAPORE 417883

not full
d/s 3250
4 Jys.

VEHICLE NO :SLN 6657A

QTY	PARTICULAR	AMOUNT
1 PCS	REAR DOOR N/S	\$1,125.30 X
1 PCS	REAR FENDER N/S	\$1,099.50 X
1 PCS	REAR BUMPER 936.50	\$1,180.00 ✓
1 PCS	REAR BUMPER SIDE RETAINER N/S	\$65.00 ✓
1 SET	REAR BUMPER CLIPS	\$50.00 ✓
1 PCS	ROCKER PANEL GARNISH N/S 588.20	\$885.00 ✓
1 SET	ROCKER PANEL GARNISH CLIPS N/S	\$50.00 ✓
1 PCS	REAR SHOCK ABSORBER N/S 311.20	\$399.00 ✓
1 PCS	REAR WHEEL HUB BEARING N/S 450.50	\$650.00 ✓
1 PCS	REAR AXLE BEAM	\$2,199.00 X
		\$7,702.80
	S.NETT	
1 PCS	REAR SPORT RIM N/S	\$680.00 400
1 PCS	REAR TYRE N/S	\$200.00 607.120
	TO CHECK WIRING	\$50.00 20
	TO DISMANTLE & REFIX CUSHION UPHOLSTREY	\$120.00 80
	TO CONDUCT WHEEL ALIGNMENT	\$120.00 80
	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE	\$380.00 150
	TO SPRAY RUST PROOFING	\$80.00 X
	TO DISMANTLE & REFIX PETROL TANK	\$100.00 X
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$800.00 400
	TO PUTTY & SPRAY PAINTING	\$1,500.00 800
	TOTAL	\$11,732.80

802

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2457.4
502
7-1225.70
5.2-520.00
2-1530.00
3275.7