

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CHINA TAIPING INSURANCE (S) PTE LTD CS3/CTI19014788/R1vf3e2-1 3 ANSON ROAD #16-00 SPRINGLEAF TOWER Date: 01-07-2020 SINGAPORE 079909 Code: CTI 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **GBJ 6377Y** Veh. Inspected **SLT 8909D** Policy No. Coverage (\$) 0.00 SNM19D203883 0.00 Claim No. Excess (\$) **Assign From** TAN KAH LEONG 12/02/2020 **Assign Date** 2. **Vehicle Particulars & Condition** B.M.W. 520I LED NAV Make & Model 1998 **Engine No. HIDDEN** Year of Reg. 2017 WBAJA12040BE45107 Chassis No. Colour **GREY** 67670 KM Odometer **IN ORDER** Steering **IN ORDER** SPORTS RIM Brakes Modification FAIR General **Conditions of Tyres** 3. Size Make **Balance** R/H Front Tyre 245/45 R18 CONTINENTAL 6 mm 245/45 R18 CONTINENTAL L/H Front Tyre 6 mm R/H Rear Tyre 245/45 R18 CONTINENTAL 6 mm 245/45 R18 CONTINENTAL 6 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. 5. **General Information** 18/08/2019 Inspect Date / Time 17/02/2020 (02:25 PM) **Accident Date** Survey held at 17 TECH PARK CRESCENT HARMONY MOTOR (AMK) PTE LTD Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/CTI19014788/R1vf3e2-1

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Estimate Days of Repair

Inspected By

5b.

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.