

55 Jalan Simpang

Singapore 418172

Tel

Mobile

Email: bonglei@gmail.com

418172

Joseph Tee

Document Number	Date & Tax Point	Order Number	W.I.P. No	Job No
0	27/02/2020		W 14977	0
Model	Chassis No	Reg No	Mileage	Page
0 TDS V6 27 SHP MY14	ZAMT557C001094169	5BU3822R	0	1

Description of Goods / Services	Qty	Unit Price	Unit	Discount	Net Total	V
R.H. REAR LIGHT FIXED SIDE cut/	1.00	593.00	EACH	0.00%	593.00	✓
L.H. REAR LIGHT FIXED SIDE cut/	1.00	593.00	EACH	0.00%	593.00	✓
REAR CROSS MEMBER ASSEMBLY	1.00	485.80	EACH	0.00%	485.80	✓
TRUNK LOCK	1.00	132.00	EACH	0.00%	132.00	✓
REAR HOOD BONNET repair X	1.00	2,386.50	EACH	0.00%	2,386.50	X
RIVET NEC	10.00	7.00	EACH	0.00%	70.00	✓
WATER SHIELD LUGGAGE COMPART cut/ X NN	1.00	331.50	EACH	0.00%	331.50	X

Warranty is only valid for 2 days from the date indicated

Paul

30/03/2020

V	Rate	Service/Goods	GST	Net	
0	0.00	4,591.80	121.43	Net	4,591.80
				GST	121.43
				Total	4,913.23
				Paid	0.00
				Owing	4,913.23