

ASS. REC. BY:

REF:

08/SMO20002874/E/d36

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Grace Teo

of

SMO

Date/Time: 19/2/2020 @ 10:44am

Estimated Cost:

Bill to:

OI / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN1550G

Insured:

GBJ4600R

at Workshop in/s

Ventage Automotive
305 Alexandra Road

Tel:

6477 7401 / 8383 3190

Policy No:

Claim No:

CMTD2000723 / AGC

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/02/2020

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 10:27pm @ 19/2/2020

Person Contacted:

Andy

Vehicle IN/OUT

Date/Time

Action/Instruction

Is complete /

SLN1550G-X

GBJ4600R-X

24/2 @ 10:11am - sent email preli advise.

ASS. REC. BY: Steve

REF:

SMO

ASSIGNMENT

From: _____

Date: 21/02/2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN1550Gat Workshop m/s Vantage Automotiveof 305 Alexandra Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: 10am-10:30am (waiting)Andy

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLN1550GYr Regn: 25/4/17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ford Focus Wagonc.c. 999Colour: Brown

A/C: Insured / Std / NI / NA

Sp. Reading: 87628

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WF06XXGCC66047952Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 205/55R16R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 5

mm

R/Bal. 5

mm

L/Bal. 5

mm

L/Bal. 5

mm

D.O.A. 14/2/20D.O.I. 21/2/20Survey held at Vantage AutomotiveDes. of Damages: Frty Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - 60,909
	PV - 48,440
	NV - 11,560
4/3/20	Finalise \$17,963.50, 7 days (Andy) Cred: 5812, 25%

Date/Time, File Pass to?

1) 513 Typist

Date/Time, File Return to?

2) _____

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee: 450

Transportation: _____

Photos

Others

TOTAL

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: TPLump Sum / (B.) (\$ 17,063.50)450

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 19 February 2020 10:44 AM
To: Chua Syahirul Syazwani Irwan; Chan, Shu Hui Agnes; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; 'SUR'
Cc: Katherine Chong; Liu Chun Cheong; Simon Koh Eng Aun; Ye, Yong Kang Melvin; Andy Ooi Lee Keong
Subject: CMTD2000723/AGC - LKK/ GBJ4600R (SOMPO) & SLN1550G (LIBERTY) DOA: 14/02/2020 - Pls assist to arr suv tmr 20/2 @10am (waiting)
Attachments: ESTIMATE-SLN1550G.pdf; GIA REPORT.PDF

Our Claim Reference: CMTD2000723/AGC
Your Reference: SLN1550G (LIBERTY)

Hi Syasya,

Please be informed that we will appoint **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for **SLN1550G** on a without Prejudice and any admission of liability basis. Kindly contact Ms. Chua at 9278 2710 to make the arrangement.

Please be informed that **Ms. Agnes Chan** is the handler of this case who can be contacted at 63295 327/ agnes.chan@sompo.com.sg .

Please submit with your report upon completion of survey to my colleague, **Ms. Agnes**.

Thank you.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chua Syahirul Syazwani Irwan <syazwanichua@simedarby.com.sg>

Sent: Wednesday, February 19, 2020 8:54 AM

To: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Katherine Chong <katherine.chong@simedarby.com.sg>; Liu Chun Cheong <liu.chun.cheong@simedarby.com.sg>; Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>; Andy Ooi Lee Keong <andy.ooi.leekeong@simedarby.com.sg>

Subject: RE: CMTD2000723/AGC - LIA/ GBJ4600R (SOMPO) & SLN1550G (LIBERTY) DOA: 14/02/2020

Dear Oic,

Can we arrange for a survey tomorrow at 10am?

Best Regards,

Chua Syasya

Customer Service Advisor, Body & Paint

Vantage Automotive Limited

305 Alexandra Road, Vantage Automotive Centre, Singapore 159942

T: +65 6477 7409 HP: +65 9278 2710 E: syazwanichua@simedarby.com.sg

www.simedarbymotors.com | www.vantageauto.com.sg

From: Andy Ooi Lee Keong <andy.ooi.leekeong@simedarby.com.sg>

Sent: Tuesday, February 18, 2020 2:55 PM

To: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Chua Syahirul Syazwani Irwan <syazwanichua@simedarby.com.sg>

Cc: Katherine Chong <katherine.chong@simedarby.com.sg>; Liu Chun Cheong <liu.chun.cheong@simedarby.com.sg>; Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: RE: CMTD2000723/AGC - LIA/ GBJ4600R (SOMPO) & SLN1550G (LIBERTY) DOA: 14/02/2020

Dear Agnes,

Noted with thanks .

Regards

Andy Ooi

From: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>

Sent: Tuesday, 18 February 2020 2:46 pm

To: Andy Ooi Lee Keong <andy.ooi.leekeong@simedarby.com.sg>; Chua Syahirul Syazwani Irwan

<syazwanichua@simedarby.com.sg>

Cc: Katherine Chong <katherine.chong@simedarby.com.sg>; Liu Chun Cheong <liu.chun.cheong@simedarby.com.sg>; Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>
Subject: RE: CMTD2000723/AGC - LIA/ GBJ4600R (SOMPO) & SLN1550G (LIBERTY) DOA: 14/02/2020

[External Mail] This email originated from outside of the organisation; be careful with requests, attachments and links.
WITHOUT PREJUDICE

Dear Andy

We refer to the above matter.

We are prepared to do direct settlement.

Thank you.

Best Regards

Agnes Chan

Claims Divison

D: 6329 5327 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Teo, Grace <grace.teo@sompo.com.sg>

Sent: Tuesday, 18 February, 2020 1:41 PM

To: Andy Ooi Lee Keong <andy.ooi.leekeong@simedarby.com.sg>; Chua Syahirul Syazwani Irwan <syazwanichua@simedarby.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>

Cc: Katherine Chong <katherine.chong@simedarby.com.sg>; Liu Chun Cheong <liu.chun.cheong@simedarby.com.sg>; Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD2000723/AGC - LIA/ GBJ4600R (SOMPO) & SLN1550G (LIBERTY) DOA: 14/02/2020

Our Claim Reference: CMTD2000723/AGC

Your Reference: SLN1550G (LIBERTY)

Hi Andy,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Agnes Chan** is the handler of this case who can be contacted at 63295 327/
agnes.chan@sompo.com.sg

Aside to Agnes,

Please advise on the liability request from Vantage Automotive Limited.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Andy Ooi Lee Keong <andy.ooi.leekeong@simedarby.com.sg>

Sent: Tuesday, February 18, 2020 9:02 AM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>; Chua Syahirul Syazwani Irwan <syazwanichua@simedarby.com.sg>

Cc: Katherine Chong <katherine.chong@simedarby.com.sg>; Liu Chun Cheong <liu.chun.cheong@simedarby.com.sg>; Simon Koh Eng Aun <simon.koh.engaun@simedarby.com.sg>

Subject: TP CLAIM: SLN1550G (LIBERTY) AGAINST GBJ4600R (SOMPO) DOA: 14/02/ 2020

Dear Officer-in-Charge,

Our client's vehicle was involved in an accident with your insured's vehicle at the above stated date and location.

Kindly refer to the attached documents for your further action and also advise us the LIABILITY for this case.

Thank you.

Remark-Vehicle currently not in

Best Regards,

Andy Ooi

Operations Executive, Body & Paint

Vantage Automotive Limited

305 Alexandra Road, Vantage Automotive Centre, Singapore 159942

T: +65 6477 7401 HP: +65 8383 3190 E: andy.ooi.leekeong@simedarby.com.sg

www.simedarbymotors.com | www.vantageauto.com.sg

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 24 February 2020 10:11 AM
To: Admin-D (LKKAuto); 'Teo, Grace'; assignments; 'Chan, Shu Hui Agnes'
Cc: 'Ye, Yong Kang Melvin'; SUR
Subject: RE: CMTD2000723/AGC - LKK/ GBJ4600R (SOMPO) & SLN1550G (LIBERTY) DOA: 14/02/2020 - Pls assist to arr suv tmr 20/2 @10am (waiting)
Attachments: PRELI ADVISED OF SLN 1550G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLN 1550G**
Number of days (estimated) : 5 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 19 February 2020 12:31 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>; 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD2000723/AGC - LKK/ GBJ4600R (SOMPO) & SLN1550G (LIBERTY) DOA: 14/02/2020 - Pls assist to arr suv tmr 20/2 @10am (waiting)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Wednesday, 19 February 2020 10:44 AM



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000423/AGC

Date: 24/02/2020

Our Ref: CS/SMO20002874/Etd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE P

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SLN 1550G.

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 21/2/2020 at the premises of M/s Vantage Automotive and have the following to report: -

Workshop Estimate Amount	: S\$ 19,797.50
Revised Estimate Amount	: S\$ 11,905.30
"Check" Items Amount	: S\$ 3,162.60
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the front portion.



Repair days: 5

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Steve Chen
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/02/2020 16:17
Date Of Accident	14/02/2020 09:10
Exact Location Of Accident	JUNCTION OF TANNERY ROAD AND GENTING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN1550G
Insured/Policyholder	
Name Of Registered Owner	BRUDERER PRESSES (FAR EAST) PTE LTD
Co Reg No	1XXXXX599R
Email Address	TAILEONG.FOO@BRUDERER.COM
Mobile Phone No	(LOCAL) +65-90303181
Alternative Phone No	OFFICE-65468121

Vehicle Particulars

Manufacturer	FORD
Model	FOCUS WAGON-999CC TITANIUM (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI19V04185/VPC/R02
Cover Note Number	

Driver

Name of Driver	FOO TAI LEONG
NRIC No	SXXXX098E
Date Of Birth	14/09/1970
Occupation	OUTDOOR
Date Of Driving Pass	17/11/1990
Driving Experience	29 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90303181
Fax Number	(LOCAL) +65-65468131
Contact Number	
EMail Address	TAILEONG.FOO@BRUDERER.COM

Address	BLK 550A SEGAR ROAD #14-616
Postcode	671550
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ACCIDENT STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ4600R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

CHUA SYASYA
CUSTOMER SERVICE ADVISOR
ACCIDENT & BODYSHOP

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

vehical "A"


I Foo Tai Leong driving SLN1550G travel straight along Tannery Road at the junction of Tannery Road the van GBJ4600R ^{vehical "B"} make a sudden right turn into Genting Road and cut into my ~~way~~ direction without signal.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

CHUA SYASYA
CUSTOMER SERVICE ADVISOR
ACCIDENT & BODYSHOP




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	599R
Vehicle Details	
Vehicle No.:	SLN1550G
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Feb 2020
Vehicle Make:	FORD
Vehicle Model:	FOCUS WAGON TITANIUM 1.0 GTDI S/S
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	GD43052
Chassis No.:	WF06XXGCC6GD43052
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$19,861.00
Original Registration Date:	25 Apr 2017
First Registration Date:	25 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$14,861.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2027
PARF Rebate Amount:	\$11,145.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$37,295.00
Total Rebate Amount:	\$48,440.00

The information contained herein is correct as at 22 Feb 2020

OK

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4582
Date Estimated : 18/02/2020
Prepared By : Andy Ooi Lee Keong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Bruderer Presses (Far East) Pte Ltd
65 Loyang Way

Singapore 508755

- ACCOUNT - 29092
Sompo Insurance Singapore Pte Ltd
50 Raffles Place,
#05-01/06 Singapore Land Tower,
Singapore 048623

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN1550G	WF06XXGCC6GD43052	25/04/2017	Foc 1.0 Wgn	0

DESCRIPTION

VALUE

TO CONDUCT TP CLAIM-SOMPO INS AGAINST-GBJ4600R DOA,
14.02.2020.

0.00

SUNDRIES.

30 / 100.00

LABOUR TO REMOVE, REPLACE, REPAIR REALIGN FRONT
BUMPER, BONNET, FRONT SUPPORT PANEL AND ALL AFFECTED
AREAS.

2400 / 1200 3,000.00

LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, BONNET,
FRONT FENDER RH, FRONT FENDER LH AND ALL AFFECTED
AREAS.

1200 / 3,000.00

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT
CODES, RESTORE ALL PROGRAMMING MODULE (NETT)

600.00

HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME
HEADLAMP CORRECTOR.

150 / 180.00

TO REMOVE AND REFIT A/C CONDENSOR, CONDUCT PRESSURE
TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIR
CON GAS.

600.00

TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER
(NETT)

70.00

TO REMOVE AND REPLACE AND RESPRAY FRONT BUMPER
REINFORCEMENT.

300.00

Total Labour 1: 7,850.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB8200CC	GRILL - RADIATOR FRT BUMPER	1	660.00	10.00	594.00
F1EB17757AJX	FRONT BUMPER	1	1,530.00	10.00	1,377.00
WAA					
F1EB17F788AC	SEAL COVER-UPPER FRT BUMPER	1	92.00	10.00	82.80
JF1EB17E778A	REINFORCEMENT PLASTIC-FRT BUMPER	1	315.00	10.00	283.50
A					
AM51R10922AL	REINFORCEMENT - FRT BUMPER	1	853.00	10.00	767.70
C1BB8B262BA	FRONT EMBLEM (FORD OVAL)	1	95.00	10.00	85.50
F1EB17B635AB	PANEL EXTENSION-FRT LOWER BUMPER	1	396.00	10.00	356.40
F1EB8B041AB	REINFORCEMENT-FRT SUPPORT PANEL	1	810.00	10.00	729.00

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4582
Date Estimated : 18/02/2020
Prepared By : Andy Ooi Lee Keong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN1550G	WF06XXGCC6GD43052	25/04/2017	Foc 1.0 Wgn	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB15A254AB	RHF FOGLAMP	1	312.00	10.00	280.80
PF1EBA16610A	BONNET	1	1,150.00	10.00	1,035.00
BM5116A770AC	HANDLE, BONNET - F11	1	145.00	10.00	130.50
BM5A16700AG	BONNET LATCH ASSY	1	160.00	10.00	144.00
F1EB13006BF	HEADLAMP ASSY LH	1	2,893.00	10.00	2,603.70
F1EB13005BF	HEADLAMP ASSY RH	1	2,893.00	10.00	2,603.70
PBM51A16008A	RHF FENDER ASSY	1	562.00	10.00	505.80
PF1EBA16A168	EXTENSION RH FRT FENDER	1	132.00	10.00	118.80
AM51R16114BG	INNER SHEILD-RH FRT FENDER	1	277.00	10.00	249.30
Total Parts :					11,947.50

Steve CLKK)
8321 8817

WML AL
P/P
Ry BOL SN
78 days
21/2/20, 10.00am

24/2/2020

KK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

22879.50

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	7,850.00
Parts	:	11,947.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,385.83
Grand Total	:	21,183.33

Customer Name & Signature / Company Stamp

Date

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SLN1550G

RO Number: 153153

Date: 26-02-2020

NO.	Supplementary / Check Items Parts	Part Number	Qty	U / Price	Disc %	Ext Price
1	RADIATOR CONTROL SHUTTER ASSY ? <i>over</i>	F1EB8475BC	1	\$742.00	10%	\$667.80 ✓
2	FRONT BUMPER AIR DEFLECTOR <i>DR</i>	F1EB17B769AA	1	\$293.00	10%	\$263.70 ✓
3	DEFLECTOR - AIR BOTTOM RAD PANEL (TOP) <i>CR4</i>	F1EB8312BA	1	\$175.00	10%	\$157.50 ✓
4	DEFLECTOR - AIR BOTTOM RAD PANEL (BOTTOM) <i>CR4</i>	F1EB8314AB	1	\$210.00	10%	\$189.00 ✓
Parts Total:						\$1,278.00

NO.	Supplementary Labour Charges	Price
1	TO REMOVE AND REFIX A/C CONDENSOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIRCON GAS.(NETT)	\$600.00 X
2	TO REMOVE, REPLACE AND RESPRAY FRONT BUMPER REINFORCEMENT.	\$600.00 X
3	TO REMOVE AND REFIX RADIATOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS.(NETT)	\$600.00 X

Steve (LKK)
26/2/20

Removal before paint
by hi
27/2

Total Labour:	\$1,800.00
Total Parts & Labour:	\$3,078.00
GST @ 7%:	\$215.46
Grand Total:	\$3,293.46

Raised By Technician	Approved By CSA	Acknowledge By Parts Assistant	BO Parts: Yes / No ETA: _____
-------------------------	--------------------	-----------------------------------	--------------------------------------

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4582
Date Estimated : 18/02/2020
Prepared By : Andy Ooi Lee Keong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Bruderer Presses (Far East) Pte Ltd
65 Loyang Way

Singapore 508755

- ACCOUNT - 29092

Sompo Insurance Singapore Pte Ltd
50 Raffles Place,
#05-01/06 Singapore Land Tower,
Singapore 048623

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN1550G	WF06XXGCC6GD43052	25/04/2017	Foc 1.0 Wgn	0

DESCRIPTION

TO CONDUCT TP CLAIM-SOMPO INS AGAINST-GBJ4600R DOA,
14.02.2020.

VALUE

0.00

SUNDRIES.

30 100.00

LABOUR TO REMOVE, REPLACE, REPAIR REALIGN FRONT
BUMPER, BONNET, FRONT SUPPORT PANEL AND ALL AFFECTED
AREAS.

1200 3,000.00

LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, BONNET,
FRONT FENDER RH, FRONT FENDER LH AND ALL AFFECTED
AREAS.

1200 3,000.00

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT
CODES, RESTORE ALL PROGRAMMING MODULE (NETT)

600.00

HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME
HEADLAMP CORRECTOR.

150 180.00

TO REMOVE AND REFIT A/C CONDENSOR, CONDUCT PRESSURE
TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIR
CON GAS.

? 600.00

TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER
(NETT)

70.00

TO REMOVE AND REPLACE AND RESPRAY FRONT BUMPER
REINFORCEMENT.

? 300.00

Total Labour 1: 7,850.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB8200CC	GRILL - RADIATOR FRT BUMPER	1	660.00	10.00	594.00
F1EB17757AJX	FRONT BUMPER	1	1,530.00	10.00	1,377.00
WAA					
F1EB17F788AC	SEAL COVER-UPPER FRT BUMPER	1	92.00	10.00	82.80
JF1EB17E778A	REINFORCEMENT PLASTIC-FRT BUMPER	1	315.00	10.00	283.50
A					
AM51R10922AL	REINFORCEMENT - FRT BUMPER	1	853.00	10.00	767.70
C1BB8B262BA	FRONT EMBLEM (FORD OVAL)	1	95.00	10.00	85.50
F1EB17B635AB	PANEL EXTENSION-FRT LOWER BUMPER	1	396.00	10.00	356.40
F1EB8B041AB	REINFORCEMENT-FRT SUPPORT PANEL	1	810.00	10.00	729.00

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 5305553L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4582
Date Estimated : 18/02/2020
Prepared By : Andy Ooi Lee Keong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN1550G	WF06XXGCC6GD43052	25/04/2017	Foc 1.0 Wgn	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB15A254AB	RHF FOGLAMP <i>mark ?</i>	1	312.00	10.00	280.80
PF1EBA16610A	BONNET <i>/ 00</i>	1	1,150.00	10.00	1,035.00
A					
BM5116A770AC	HANDLE, BONNET - F11 <i>X</i>	1	145.00	10.00	130.50
BM5A16700AG	BONNET LATCH ASSY <i>X</i>	1	160.00	10.00	144.00
F1EB13006BF	HEADLAMP ASSY LH <i>/ 0R</i>	1	2,893.00	10.00	2,603.70
F1EB13005BF	HEADLAMP ASSY RH <i>/ 1R</i>	1	2,893.00	10.00	2,603.70
PBM51A16008A	RHF FENDER ASSY <i>X</i>	1	562.00	10.00	505.80
G					
PF1EBA16A168	EXTENSION RH FRT FENDER <i>?</i>	1	132.00	10.00	118.80
AA					
AM51R16114BG	INNER SHEILD-RH FRT FENDER <i>X</i>	1	277.00	10.00	249.30
Total Parts :					11,947.50

Steve CLKK)
8322 8813

WML PL
P/P

Ry PL SN

5 days + 2 days

21/2/20, 10.00am

Customer Name & Signature / Company Stamp

Date

Labour 1	:	7,850.00
Parts	:	11,947.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,385.83
Grand Total	:	21,183.33

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4582
Date Estimated : 18/02/2020
Prepared By : Andy Ooi Lee Keong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Bruderer Presses (Far East) Pte Ltd
65 Loyang Way

Singapore 508755

- ACCOUNT - 29092
Sompo Insurance Singapore Pte Ltd
50 Raffles Place,
#05-01/06 Singapore Land Tower,
Singapore 048623

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN1550G	WF06XXGCC6GD43052	25/04/2017	Foc 1.0 Wgn	0

DESCRIPTION

TO CONDUCT TP CLAIM-SOMPO INS AGAINST-GBJ4600R DOA,
14.02.2020.

VALUE

0.00

SUNDRIES.

30 100.00

LABOUR TO REMOVE, REPLACE, REPAIR REALIGN FRONT
BUMPER, BONNET, FRONT SUPPORT PANEL AND ALL AFFECTED
AREAS.

9400 3,000.00

LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, BONNET,
FRONT FENDER RH, FRONT FENDER LH AND ALL AFFECTED
AREAS.

1200 3,000.00

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT
CODES, RESTORE ALL PROGRAMMING MODULE (NETT)

600.00

HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME
HEADLAMP CORRECTOR.

150 180.00

TO REMOVE AND REFIT A/C CONDENSOR, CONDUCT PRESSURE
TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIR
CON GAS.

? 600.00

TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER
(NETT)

70.00

TO REMOVE AND REPLACE AND RESPRAY FRONT BUMPER
REINFORCEMENT.

? 300.00

Total Labour 1: 7,850.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB8200CC	GRILL - RADIATOR FRT BUMPER ✓ DR	1	660.00	10.00	594.00
F1EB1775AJX	FRONT BUMPER ✓ ON	1	1,530.00	10.00	1,377.00
WAA					
F1EB17F788AC	SEAL COVER-UPPER FRT BUMPER ?	1	92.00	10.00	82.80
JF1EB17E778A	REINFORCEMENT PLASTIC-FRT BUMPER ? / DR	1	315.00	10.00	283.50
A					
AM51R10922AL	REINFORCEMENT - FRT BUMPER ✓ OT	1	853.00	10.00	767.70
C1BB8B262BA	FRONT EMBLEM (FORD OVAL) ✓ CVT	1	95.00	10.00	85.50
F1EB17B635AB	PANEL EXTENSION-FRT LOWER BUMPER ✓ DR	1	396.00	10.00	356.40
F1EB8B041AB	REINFORCEMENT-FRT SUPPORT PANEL ? / DR	1	810.00	10.00	729.00

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4582
Date Estimated : 18/02/2020
Prepared By : Andy Ooi Lee Keong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN1550G	WF06XXGCC6GD43052	25/04/2017	Foc 1.0 Wgn	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB15A254AB	RHF FOGLAMP	1	312.00	10.00	280.80
PF1EBA16610A	BONNET	1	1,150.00	10.00	1,035.00
BM5116A770AC	HANDLE, BONNET - F11	1	145.00	10.00	130.50
BM5A16700AG	BONNET LATCH ASSY	1	160.00	10.00	144.00
F1EB13006BF	HEADLAMP ASSY LH	1	2,893.00	10.00	2,603.70
F1EB13005BF	HEADLAMP ASSY RH	1	2,893.00	10.00	2,603.70
PBM51A16008A	RHF FENDER ASSY	1	562.00	10.00	505.80
PF1EBA16A168	EXTENSION RH FRT FENDER	1	132.00	10.00	118.80
AM51R16114BG	INNER SHEILD-RH FRT FENDER	1	277.00	10.00	249.30
Total Parts :					11,947.50

Steve CLKK) WRL PL
8321 8813 P/P
Ry PL SH
7 8 days
21/2/20, 10.00am

2275.5

Customer Name & Signature / Company Stamp

Date

Labour 1	:	7,850.00
Parts	:	11,947.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,385.83
Grand Total	:	21,183.33

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SLN1550G

RO Number: 153153

Date: 26-02-2020

NO.	Supplementary / Check Items Parts	Part Number	Qty	U / Price	Disc %	Ext Price
1	RADIATOR CONTROL SHUTTER ASSY ?	F1EB8475BC	1	\$742.00	10%	\$667.80
2	FRONT BUMPER AIR DEFLECTOR / DR	F1EB17B769AA	1	\$293.00	10%	\$263.70
3	DEFLECTOR - AIR BOTTOM RAD PANEL (TOP) / CR4	F1EB8312BA	1	\$175.00	10%	\$157.50
4	DEFLECTOR - AIR BOTTOM RAD PANEL (BOTTOM) / CR4	F1EB8314AB	1	\$210.00	10%	\$189.00
Parts Total:						\$1,278.00

NO.	Supplementary Labour Charges	Price	
1	TO REMOVE AND REFIX A/C CONDENSOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIRCON GAS.(NETT)	\$600.00	
2	TO REMOVE, REPLACE AND RESPRAY FRONT BUMPER REINFORCEMENT.	\$600.00	
3	TO REMOVE AND REFIX RADIATOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS.(NETT)	\$600.00	
<div>Steve (LKK)</div> <div>26/2/20</div>		Total Labour:	\$1,800.00
		Total Parts & Labour:	\$3,078.00
		GST @ 7%:	\$215.46
		Grand Total:	\$3,293.46

Raised By Technician	Approved By CSA	Acknowledge By Parts Assistant	BO Parts: Yes / No ETA: _____
-------------------------	--------------------	-----------------------------------	--------------------------------------

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Co. Regs. No. 53055563L GST Regs. No. M2-0000551-1

305 Alexandra Road

Vantage Automotive Centre

Singapore 159942

Service Booking: 6477 7399

Parts: 6477 7420

Vantage 24-Hour Assiat: 6473 8588

Fax: 6477 7300

**FINALISATION REPORT**

REPAIR ORDER NO. BG 153153	Date IN 26/02/2020	Invoice Number	Page No. 1 of 2
	Payment Term 30 Days From Invoice	Invoice Date ??	
	Customer Service Advisor Chua Syahirul Syazwani Irwan	Invoice By Chua Syahirul Syazwani Irwan	

CUSTOMER INFORMATION	INVOICE TO 29092
Bruderer Presses (Far East) Pte Ltd 65 Loyang Way Singapore 508755	Sompo Insurance Singapore Pte Ltd 50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

REGISTRATION No. SLN1550G	CHASSIS No. WF06XXGCC6GD43052	STOCK No. 15533	REGISTRATION DATE 25/04/2017	MODEL Foc 1.0 Wgn	MILEAGE 88133
-------------------------------------	---	---------------------------	--	-----------------------------	-------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM-SOMPO INS AGAINST-GBJ4600R DOA, 14.02.2020.	1	0.00	0.00
	SUNDRIES.	1	0.00	30.00
	LABOUR TO REMOVE, REPLACE, REPAIR REALIGN FRONT BUMPER, BONNET, FRONT SUPPORT PANEL AND ALL AFFECTED AREAS.	1	0.00	2,400.00
	LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, BONNET, FRONT FENDER RH, FRONT FENDER LH AND ALL AFFECTED AREAS.	1	0.00	1,200.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES, RESTORE ALL PROGRAMMING MODULE (NETT)	2	0.00	600.00
	HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR.	1	0.00	150.00
	TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER (NETT)	1	0.00	70.00
	TO REMOVE AND REFIT A/C CONDENSOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIRCON GAS.	1	0.00	600.00
	TO REMOVE, REPLACE AND RESPRAY FRONT BUMPER REINFORCEMENT.	1	0.00	300.00
	Sub-Total :			5,350.00
CODE	DESCRIPTION	UNITS	DISC %	NETT
F1EB17B635AB	PANEL EXTENSION-FRT LOWER BUMPER	1	10.00	356.40
C1B8B8262BA	FRONT EMBLEM (FORD OVAL)	1	10.00	85.50
F1EB13005BF	HEADLAMP ASSY RH	1	10.00	2,603.70
F1EB13006BF	HEADLAMP ASSY LH	1	10.00	2,603.70
F1EB17757AJXWAA	FRONT BUMPER	1	10.00	1,377.00
F1EB8200CC	GRILL - RADIATOR FRT BUMPER	1	10.00	594.00
PF1EBA16610AA	BONNET	1	10.00	1,035.00
F1EB8475BC	SHUTTER ASSY - RADIATOR CONTROL	1	10.00	667.80 ✓
F1EB17B769AA	DEFLECTOR - AIR (FRONT BUMPER)	1	10.00	263.70 ✓
JF1EB17E778AA	REINFORCEMENT PLASTIC-FRT BUMPER	1	10.00	283.50
AM51R10922AL	REINFORCEMENT - FRT BUMPER	1	10.00	767.70
F1EB88041AB	REINFORCEMENT-FRT SUPPORT PANEL	1	10.00	729.00
F1EB8312BA	DEFLECTOR - AIR TOP RAD PANEL	1	10.00	157.50 ✓
F1EB8314AB	DEFLECTOR - AIR BOTTOM RAD PANEL	1	10.00	189.00 ✓
	Sub-Total :			11,713.50

Attending CSO : Syasya

Should you require further explanation, please reach me at 92782710

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Co. Regs. No. 53055563L GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942

Service Booking: 6477 7399
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300

**FINALISATION REPORT**

REPAIR ORDER NO. BG 153153	Date IN 26/02/2020 Payment Term 30 Days From Invoice Customer Service Advisor Chua Syahirul Syazwani Irwan	Invoice Number Invoice Date ?? Invoice By Chua Syahirul Syazwani Irwan	Page No. 2 of 2
--------------------------------------	--	---	------------------------

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	17,063.50
Labour Charges	5,350.00	Less Insurance Excess	S\$	0.00
Parts Charges	11,713.50	GST @ 7%	S\$	1,194.45
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	18,257.95
		Less Deposit/Voucher	S\$	0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$	18,257.95
<p>All amounts are in Singapore Dollars. Work was carried out subject to the Company's Terms and Conditions of Service. No complaints will be entertained unless reported within seven (7) days of the date of this invoice. For credit purchases, interest @1% per month will be debited on overdue amounts.</p>				



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO20002874/Etd3e2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date : 06-03-2020	
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 4600R	Veh. Inspected	SLN 1550G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2000723/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	19/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	FORD FOCUS WAGON	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WF06XXGCC6GD43052	Colour	BROWN	
Odometer	87628	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	CONTINENTAL	5 mm	
L/H Front Tyre	205/55 R16	CONTINENTAL	5 mm	
R/H Rear Tyre	205/55 R16	CONTINENTAL	5 mm	
L/H Rear Tyre	205/55 R16	CONTINENTAL	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/02/2020	Inspection Date	21/02/2020	
Survey held at	VANTAGE AUTOMOTIVE LTD 305 ALEXANDRA ROAD SINGAPORE 155942			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 1550G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	GRILL - RADIATOR FRT BUMPER (SN)	BROKEN	594.00	594.00
1	FRONT BUMPER (SN)	DENTED	1,377.00	1,377.00
1	SEAL COVER - UPPER FRT BUMPER (SN)	NOT NECESSARY	82.80	-
1	REINFORCEMENT PLASTIC-FRT BUMPER (SN)	BROKEN	283.50	283.50
1	REINFORCEMENT - FRT BUMPER (SN)	DENTED	767.70	767.70
1	FRONT EMBLEM (FORD OVAL) (SN)	CUT	85.50	85.50
1	PANEL EXTENSION - FRT LOWER BUMPER (SN)	BROKEN	356.40	356.40
1	REINFORCEMENT-FRT SUPPORT PANEL (SN)	BROKEN	729.00	729.00
1	RHF FOG LAMP (SN)	NOT NECESSARY	280.80	-
1	BONNET (SN)	DENTED	1,035.00	1,035.00
1	HANDLE, BONNET - F11 (SN)	NOT NECESSARY	130.50	-
1	BONNET LATCH ASSY (SN)	NOT NECESSARY	144.00	-
1	HEADLAMP ASSY LH (SN)	BROKEN	2,603.70	2,603.70
1	HEADLAMP ASSY RH (SN)	BROKEN	2,603.70	2,603.70
1	RHF FENDER ASSY (SN)	NOT NECESSARY	505.80	-
1	EXTENSION RH FRT FENDER (SN)	NOT NECESSARY	118.80	-
1	INNER SHIELD-RH FRT FENDER (SN)	NOT NECESSARY	249.30	-
1	RADIATOR CONTROL SHUTTER ASSY (SN) (ADDITIONAL)	CRACKED	667.80	667.80
1	FRONT BUMPER AIR DEFLECTOR (SN) (ADDITIONAL)	BROKEN	263.70	263.70
1	DEFLECTOR - AIR BOTTOM RAD PANEL (TOP) (SN) (ADDITIONAL)	CRUSHED	157.50	157.50
1	DEFLECTOR - AIR BOTTOM RAD PANEL (BOTTOM) (SN) (ADDITIONAL)	CRUSHED	189.00	189.00
			13,325.50	11,743.50
<u>LABOUR</u>				
LABOUR TO REMOVE, REPLACE, REPAIR, REALIGN FRONT BUMPER, BONNET, FRONT SUPPORT PANEL AND ALL AFFECTED AREAS.			3,000.00	2,400.00
LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, BONNET, FRONT FENDER RH, FRONT FENDER LH AND ALL AFFECTED AREAS.			3,000.00	1,200.00

Report Ref No. CS/SMO20002874/Etd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES, RESTORE ALL PROGRAMMING MODULE.		600.00	600.00
	HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR.		180.00	150.00
	TO REMOVE AND REFIT A/C CONDENSOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIR CON GAS.		600.00	600.00
	TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER.		70.00	70.00
	TO REMOVE AND REPLACE AND RESPRAY FRONT BUMPER REINFORCEMENT.		300.00	300.00
	TO REMOVE AND REFIX A/C CONDENSOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIRCON GAS. (ADDITIONAL)	NOT NECESSARY	600.00	-
	TO REMOVE, REPLACE AND RESPRAY FRONT BUMPER REINFORCEMENT. (ADDITIONAL)	NOT NECESSARY	600.00	-
	TO REMOVE AND REFIX RADIATOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS. (ADDITIONAL)	NOT NECESSARY	600.00	-
			9,550.00	5,320.00
GRAND TOTAL			22,875.50	17,063.50

RECOMMENDED COST OF REPAIRS			17,063.50
-----------------------------	--	--	-----------

Report Ref No. CS/SMO20002874/Etd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.