

# WENG KEE MOTOR

DATE: 19-2-2020

## REPAIR ESTIMATE

VEHICLE: GBJ 7500 B  
MODEL: Nissan NV200

S/n	Description of part	Qty	Estimate
1	Rear bumper / CRU	1	495.90 /
2	Rear bumper side bracket LH/RH ? / BR	2	141.20 /
3	Rear bumper clip - set / Nec	1	30.00 /
4	Rear bumper sponge ? / CR4	1	135.20 /
5	Rear tailgate / DO	1	1,879.70 1,750
6	Rear tailgate inner trim X SVC	1	135.20 X
7	Rear tailgate inner trim clip - set X SVC	1	30.00 X
8	Rear tailgate outer garnish SK / SCH	1	175.80 /
9	Rear tailgate lock mechanism / Jam d	1	158.00 /
10	Rear tailgate weather stripe / CRU	1	125.90 /
11	Rear tailgate logo / Nec	1	75.00 /
12	Rear tailgate emblem 'NV200' / Nec	1	75.00 /
13	Rear tailgate emblem 'Vanette' / Nec	1	75.00 /
14	Rear tailgate weight limit sticker / Nec	1	35.00 /
15	Windscreen support clip / Nec	2	36.00 /
16	Tail lamp LH/RH / SCH	2	513.20 /
17	Rear end panel ? / DO	1	269.90 /
18	Rear end panel top garnish / CUF	1	75.00 /
19	Rear end panel top garnish clip - set / Nec	1	30.00 /
20	Rear end inner panel / BT	1	544.00 /
21	Rear spare tyre support bracket X SVC	1	145.30 X
22	Rear spare tyre floor panel X R	1	900.90 X
<b>Sub-total 1</b>			<b>5,290.30</b> 4,740.1
<b>Less Discount 10%</b>			<b>4,761.27</b> - 10%
			<u>4,266.09</u>
23	Rear Sticker '70 km/hr' / Nec	1	40.00 /
24	Rear Sticker '6 pax' / Nec	1	40.00 /
25	Rear number plate / SCH	1	50.00 5035
26	Rear windscreen primer / Nec	1	30.00 20
27	Rear windscreen support sponge / Nec	1	30.00 /
28	Rear windscreen sealant / Mec	1	45.00 30
29	Reverse sensor / Shuf	1	200.00 /
<b>Sub-total 2</b>			<b>435.00</b> 395
<b>Parts total</b>			<b>5,196.27</b>

### Labour

30 To straighten and panel beating rear frame members. To remove and replace above parts. 1,600.00  
1,100

# WENG KEE MOTOR

31	To putty, re-spray painting and polish affected areas.	1,200.00	1,100 900
32	To rust proof above affect area	60.00	30
33	To check and rectify wiring system	60.00	30
34	To remove and refit rear upholstery to facilitate repair	180.00	50
35	To remove and transfer boot lid components	150.00	60
36	To remove and transfer rear windscreen	150.00	120
37	To remove and replace reverse sensor and check	60.00	30
<b>Labour total</b>		<b>3,460.00</b>	<b>2,320</b>
<b>Parts &amp; Labour total</b>		<b>8,656.27</b>	

Repair day - 6 days

Lump Sum Repair

After paint photo

Sun Pin (LKK)

19/02/2020

sunpin@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P = 4,266.09

N = 395

L = 2,320

---

6,981.09

---

- 20%

---

5,584.87

4/5

\$5,600

6 days