



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

18-02-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 18/02/2020

Estimated repair cost for vehicle no: SJQ1197B TOYOTA CHR

CHASSIS: NMTKZ3BX80R022396

TP EQ.

Xigo Tony

NMTKZ3BX80R022396

S/n	Qty	Items	U/price	Amount
1	1	Rear Bumper		\$630.00 X
2	1	Rear Bumper Lower		\$507.50 X
3	10	Rear Bumper Clip	\$6.50	\$65.00 X
4	1	Rear R/H Bumper Side Retainer		\$105.00 X
5	1	Rear R/H Fender		\$560.00 X
6	1	Rear R/H Wheel Arch Protector		\$262.50 ✓
7	1	Rear R/H Door		\$1,470.00 ✓ 1184.50
8	2	Rear R/H Door Hinge	\$122.50	\$245.00 X
9	1	Rear R/H Door Lower Protector		\$262.50 ✓
10	1	Rear R/H Door Lock		\$980.00 398
11	1	Rear R/H Door Weatherstrip		\$168.00 X
12	1	Rear R/H Door Inner Trim Board		\$2,605.00 555.70
13	1	Rear R/H Door Window Motor & Regulator Assy		\$463.00 X 243.
14	2	Rear R/H Door Frame Sticker	\$76.10	\$152.20 60(su)
15	1	Rear R/H Tyre		\$380.00 X
16	1	Rear R/H Rim		\$950.00 500(su)
17	1	Rear R/H Shock Absorber		\$330.00 X
18	1	Rear R/H Axle Bearing		\$857.50 X
19	1	Rear Axle		\$2,550.00 X
20	1	R/H Rocker Panel		\$758.00 X
21	1	R/H Rocker Panel Skirt		\$390.00 ✓
22	12	R/H Rocker Panel Skirt Clip	\$6.50	\$78.00 30.
23	1	Front R/H Door Lower Protector		

✓ 254.90 ut

358150

2686.12

Subtotal :-

\$14,769.20

S.N 560.

Labour charges

To remove & refit rear R/H door, lock, glass, weatherstrip, trim board, frame sticker & window motor regulator assy

~~\$280.00~~ 80

To remove & refit reverse sensor

\$100.00 X

To remove & refit rear axle, bearing & shock absorber

\$450.00 X

To check wiring

~~\$100.00~~ 30

Tuff kote

10/0

\$150.00 X

Towing fee

\$150.00 X

Panel beating

~~\$1,200.00~~ 300

Spray painting

~~\$1,400.00~~ 600

Subtotal :- \$3,830.00

Total:- \$18,599.20

Total 425612

L/S 3.4K.

04 Days.

3.4 K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: