



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

WDB2110412B402281

TP Budget Direct.

Xiao Chen.

Page No. 1

Vehicle No. SKG7472H MERCEDES E200

| QTY                       | DESCRIPTION                                 | CONDITION      | REPAIRER'S ESTIMATE (S\$) | SURVEYOR ADJUSTMENT |
|---------------------------|---------------------------------------------|----------------|---------------------------|---------------------|
| <b>PARTS (LIST ITEMS)</b> |                                             |                |                           |                     |
| 1                         | REAR BOOTLID <i>new</i>                     |                | 2388.00                   | +                   |
| 2                         | REAR BOOTLID HINGE LH & RH @\$125.00        |                | 250.00                    | +                   |
| 1                         | REAR BOOTLID LOGO                           |                | 80.00                     | +                   |
| 1                         | REAR BOOTLID "NGT" EMBLEM                   |                | 71.00                     | +                   |
| 1                         | REAR BOOTLID "E200" EMBLEM                  |                | 82.50                     | +                   |
| 1                         | REAR BOOTLID "C&C" EMBLEM                   |                | 84.00                     | +                   |
| 1                         | REAR BOOTLID WEATHERSTRIP                   |                | 218.70                    | +                   |
| 1                         | REAR TAILLAMP RH <i>new</i>                 |                | 589.50                    | ✓                   |
| 1                         | REAR BUMPER <i>Distorted</i>                |                | <del>1815.00</del>        | 1650                |
| 1                         | REAR BUMPER FRAME LH & RH @\$75.90          | exhaust chrome | 151.80                    | ✓                   |
| 1                         | REAR BUMPER CHROME MOULDING LH              |                | 135.00                    | ✓                   |
| 1                         | REAR BUMPER CHROME MOULDING RH              |                | 135.00                    | ✓                   |
| 1                         | REAR BUMPER CHROME MOULDING CENTRE          |                | 181.00                    | ✓                   |
| 1                         | REAR BUMPER REINFORCEMENT <i>Best</i>       |                | 874.50                    | 679                 |
| 1                         | REAR BUMPER TOW COVER <i>Distorted</i>      |                | <del>101.00</del>         | 61                  |
| 1                         | REAR BUMPER LOWER TRIM <i>new</i>           |                | 541.00                    | +                   |
| 2                         | REAR BUMPER SIDE RETAINER LH & RH @\$108.40 | RH <i>new</i>  | <del>216.80</del>         | 108.80              |
| 2                         | REAR BUMPER SIDE BRACKET LH & RH @\$115.00  | <i>new</i>     | 230.00                    | +                   |
| 1                         | REAR BUMPER SPONGE <i>new</i>               |                | 219.00                    | +                   |
| 1                         | REAR END PANEL <i>Dented</i>                | 464570         | <del>1417.30</del>        | 955                 |
| 1                         | REAR END PANEL TOP GARNISH <i>new</i>       |                | 155.40                    | +                   |
| 1                         | REAR FENDER RH <i>Repair</i>                | 418113         | 2355.00                   | +                   |
| 2                         | REAR FENDER AIR FLAP LH & RH @\$54.00       |                | 108.00                    | +                   |
|                           |                                             |                | 12399.50                  |                     |
| less 10%                  |                                             |                | 1239.95                   | 10%                 |
|                           |                                             |                | 11159.55                  |                     |
| <b>SPECIAL ITEMS</b>      |                                             |                |                           |                     |
| 1 SET                     | REVERSE SENSOR <i>1 piece damaged</i>       |                | 1120.00                   | 250                 |
| 1                         | REVERSE SENSOR SEAL <i>new</i>              |                | 100.00                    | 10                  |
| 1                         | REVERSE SENSOR O RING <i>new</i>            |                | 80.00                     | 15                  |
| 1 SET                     | REAR BUMPER CLIPS <i>new</i>                |                | 100.00                    | 50                  |
| 1                         | REAR END PANEL SEALANT <i>new</i>           |                | 100.00                    | 60                  |
| 1                         | REAR FENDER SEALANT <i>new</i>              |                | 100.00                    | +                   |
| Total Parts               |                                             |                | 12759.55                  |                     |

385.



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SKG7472H MERCEDES E200

| S/N                     | DESCRIPTION                                                                                            | REPAIRER'S ESTIMATE | OUR ASSESSMENT |
|-------------------------|--------------------------------------------------------------------------------------------------------|---------------------|----------------|
| 1                       | <b>LABOUR</b><br>To remove the affected parts & fittings to commence repairs and replace damaged parts | <del>1800.00</del>  | 700            |
| 2                       | To supply paint materials, expandable items & putty, respray paint on parts replaced                   | <del>1400.00</del>  | 700            |
| 3                       | To remove and refix wiring at damaged areas                                                            | <del>180.00</del>   | 30.            |
| 4                       | To perform anti rust treatment on affected areas                                                       | <del>150.00</del>   | 80             |
| 5                       | To remove & replace reverse sensor                                                                     | <del>150.00</del>   | 60.            |
| 6                       | To conduct water seepage test                                                                          | 120.00              | x              |
| 7                       | To transfer rear boot mechanism                                                                        | 120.00              | x              |
| 9                       | To clear fault code with diagnostic computer and reset to Mercedes specification .                     | <del>250.00</del>   | 120            |
| Labour Total :          |                                                                                                        | 4170.00             |                |
| TOTAL (PARTS & LABOUR): |                                                                                                        | 16929.55            |                |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling,  
1/s 21/02/20.

05 Days.

total: 6286.13

2/s: SK

(SK)