

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

19th February 2020

TRER

Cecilia

MR2B23F3X01178992

Accident date: 18th FEB 2020

Estimated repair cost for vehicle no: SML9623B TOYOTA VIOS 1.5A (JUNE 2019)

S/n	Qty	Items/Net	U/price	Amount
1	1	Front door - LH <i>Rep</i>		\$1,120.00 X
2	1	Front head lamp-LH <i>Here</i>		\$752.10 X
3	1	Front Bumper <i>Rep</i>		\$680.20 X
4	2	Front Bumper Side Bracket <i>3M</i>	\$131.10	\$262.20 X
5	10	Front Bumper Clips	\$6.50	\$65.00 X
6	1	Front Fender-LH <i>Dented</i>		\$685.00 ✓
7	1	Front Fender Cowling		\$182.50 X
8	5	Front Fender Cowling Clips <i>3M</i>	\$6.50	\$65.00 X
9	1	Front tyre -LH <i>Here</i>		\$300.00 X
10	1	front rim -LH <i>lit</i>		\$450.00 ✓
11	1	Front lower arm- LH <i>But</i>		\$425.20 ✓
12	1	Front knuckle arm -LH <i>Dented</i>		\$381.20 ✓
13	1	Front knuckle arm bearing-LH <i>New</i>		\$181.40 ✓
14	1	Front shock absorber-LH <i>But</i>		\$485.20 ✓

Subtotal :- \$6,035.00

2500.80

1875.60

Labour charges

To remove & refix cushion

\$120.00 X

To check wheel alignment computer

\$120.00 80

To remove & refix front undercarriage

\$250.00 220

To check wiring

\$60.00 30

Towing charges

\$100.00 X

Tuff kote

\$120.00 X

Panel beating

\$800.00 300

Spray painting

\$800.00 600

Subtotal :- \$2,370.00

Total :- \$8,405.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3105.60

L/S: 2.4K 04Dys