

Standard

ASS. REC. BY:

Surveyor: Steve

REF: CS3/LPC19020771/Eyd3-1^{OK}

and Introduction:

ASSIGNMENT (Office)

From (Person): Ong lili

of JPC

Date/Time: 20/02/2020

Estimated Cost:

Bill to:

GD (P) WS / TP RES / GD RES / EVA / INV / MV / CS

To inspect Vehicle No:

GBE 4237H

Insured:

YN 4552C

at Workshop no/s:

Hon Car Repair

Tel:

9777 7266

of

Blk 1001 Bukit Merah lane 3 # 01-49

Policy No:

Claim No:

18/19/19/VCO5/022676

Year insured:

Excess:

Make of Veh:

(Client's record)

D.O.A.

19/11/19

CA / RRV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:50am 28/11/19

Person Contacted:

Susan

Vehicle:

IN OIT

Date/Time	Action/Instruction
	Should ✓
	GBE 4237H - NSA / 19/11/2019 13/4
	YN 4552C - NSA / 19/11/2019 13/4
	After repair: 2/12/2019

24/2 Submit US \$7150-00 Repair 10 day

24/2/20 Typist

[Signature]
24/2/2020

RECEIVED 24 FEB 2020

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 20 February 2020 11:01 AM
To: Admin-D (LKKAuto); assignments
Cc: MT_Claim_SG; SUR
Subject: RE: ACCIDENT INVOLVING GBE 4237H & YN 4552C ALONG BUKIT PANJANG ROAD TOWARDS CHOA CHU KANG ROAD NEAR OR AT THE TRAFFIC LIGHT JUNCTION WITH WOODLANDS ROAD ON 19th NOVEMBER 2019 @ 1.20 P.M. Our Ref:18/19/19/VC05/022676 [External General]
Attachments: 22676 TP SR.pdf

Lonpac External - General

Dear Nivitha

Attached is the TP survey report, please conduct paper survey.

The colour photographs were not provided.

Since your surveyor has conducted pre-repair survey, do you still require the colour photographs?

Regards,


Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Monday, 25 November 2019 10:53 AM

To: ONG LI LI <llong@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING GBE 4237H & YN 4552C ALONG BUKIT PANJANG ROAD TOWARDS CHOA CHU KANG ROAD NEAR OR AT THE TRAFFIC LIGHT JUNCTION WITH WOODLANDS ROAD ON 19th NOVEMBER 2019 @ 1.20 P.M. Our Ref:18/19/19/VC05/022676 [External General]

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]

Sent: Monday, 25 November 2019 9:59 AM

To: Winston Low <winstlow@singnet.com.sg>; MT_Claim_SG <mt_claim@lonpac.com>;
assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: 'weeyuweed weeyuweed' <weeyuweed@gmail.com>

Subject: RE: ACCIDENT INVOLVING GBE 4237H & YN 4552C ALONG BUKIT PANJANG ROAD TOWARDS CHOA CHU KANG ROAD NEAR OR AT THE TRAFFIC LIGHT JUNCTION WITH WOODLANDS ROAD ON 19th NOVEMBER 2019 @ 1.20 P.M. Our Ref:18/19/19/VC05/022676
[External General]

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Sir/Mdm

We are not agreeable with your list of surveyors and we shall appoint LKK Auto Consultants Pte Ltd to conduct the survey.

Dear Nivitha

FYA

Regards,


Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Winston Low [mailto:winstlow@singnet.com.sg]

Sent: Monday, 25 November 2019 9:26 AM

To: ONG LI LI; MT_Claim_SG

Cc: 'weeyuweed weeyuweed'

Subject: RE: ACCIDENT INVOLVING GBE 4237H & YN 4552C ALONG BUKIT PANJANG ROAD TOWARDS CHOA CHU KANG ROAD NEAR OR AT THE TRAFFIC LIGHT JUNCTION WITH WOODLANDS ROAD ON 19th NOVEMBER 2019 @ 1.20 P.M. Our Ref:18/19/19/VC05/022676
[External General]

Our Ref: GBE 4237H Your Ref: 18/19/19/VC05/022676

Dear Sirs

Our client objects appointing your surveyors as a single joint expert.

We propose on the following surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

- 1) Michael Yap Teck Chye (Mc-Coy Appraiser Pte Ltd)
- 2) Dixon Yeo (Treasure Appraisal Services)
- 3) Dennis Yap Teck Wee (Pal's Appraiser Pte Ltd)
- 4) Andy Yap Teck Lee (LCW Appraiser Pte Ltd)

Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Regards

M/s Winston Low & Partners

cc: client

Notice & Disclaimer:

The information contained in this email (including all attachments) is both confidential and protected by legal professional privilege. It is intended for the use only of the addressee named. If you are not the intended recipient, you are hereby notified that any dissemination, distribution, publication or copying of this email is strictly prohibited. If you have received this email in error, please accept our apologies, delete the original email from your system including all copies made, and notify us by return email at winstlow@singnet.com.sg

Winston Low & Partners do not guarantee the integrity and security of Internet communications. Although we have taken reasonable precautions to scan outgoing and incoming emails and attachments for viruses, we cannot guarantee this communication to be free of all viruses nor are we responsible for any consequences caused by viruses.

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: 25 November 2019 08:21

To: Winston Low <winstlow@singnet.com.sg>; MT_Claim_SG <mt_claim@lonpac.com>

Cc: 'weeyuweed weeyuweed' <weeyuweed@gmail.com>

Subject: RE: ACCIDENT INVOLVING GBE 4237H & YN 4552C ALONG BUKIT PANJANG ROAD TOWARDS CHOA CHU KANG ROAD NEAR OR AT THE TRAFFIC LIGHT JUNCTION WITH WOODLANDS ROAD ON 19th NOVEMBER 2019 @ 1.20 P.M. Our Ref:18/19/19/VC05/022676

[External General]

Lonpac External - General

Without Prejudice
Save as to Costs

Dear Sir/Mdm


We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

1	Robin Poon
2	Nicholas Tey
3	Jackson Quek
4	Mohammed Rasul
5	Adrian Ling
6	Kenneth Kong
7	Bryan Ang
8	Muhammad Nazril Bin Abdullah
9	Ong Hwee Jie
10	Steve Chen

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Winston Low [<mailto:winstlow@singnet.com.sg>]

Sent: Friday, 22 November 2019 5:18 PM

To: MT_Claim_SG

Cc: 'weeyuweed weeyuweed'

Subject: FW: ACCIDENT INVOLVING GBE 4237H & YN 4552C ALONG BUKIT PANJANG ROAD TOWARDS CHOA CHU KANG ROAD NEAR OR AT THE TRAFFIC LIGHT JUNCTION WITH WOODLANDS ROAD ON 19th NOVEMBER 2019 @ 1.20 P.M.

Your Ref: YN 4552C
Our Ref : GBE 4237H

Dear Sirs,

1. We act for M/s Lew Ah Bee Trading, the owners of vehicle no. GBE 4237H.

2. We are instructed to claim damages against you in connection with the above accident.
3. Pursuant to the State Courts NIMA Protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop: -

Venue: **Han Car Repairs**
Address: 1001 Bukit Merah Lane 3
#01-49, Alexandra Village
Singapore 159718
Contact: Ms. Susan Chin @ 9777 7266

4. TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Regards

Winston Low
M/s Winston Low & Partners
cc : clients (GBE 4237H)

Notice & Disclaimer:

The information contained in this email (including all attachments) is both confidential and protected by legal professional privilege. It is intended for the use only of the addressee named. If you are not the intended recipient, you are hereby notified that any dissemination, distribution, publication or copying of this email is strictly prohibited. If you have received this email in error, please accept our apologies, delete the original email from your system including all copies made, and notify us by return email at winstlow@singnet.com.sg

Winston Low & Partners do not guarantee the integrity and security of Internet communications. Although we have taken reasonable precautions to scan outgoing and incoming emails and attachments for viruses, we cannot guarantee this communication to be free of all viruses nor are we responsible for any consequences caused by viruses.

From: Winston Low [<mailto:winstlow@singnet.com.sg>]
Sent: 22 November 2019 10:11
To: 'geraldpoh@lonpac.com' <geraldpoh@lonpac.com>
Cc: 'weeyuweed weeyuweed' <weeyuweed@gmail.com>
Subject: FW: ACCIDENT INVOLVING GBE 4237H & YN 4552C ALONG BUKIT PANJANG ROAD TOWARDS CHOA CHU KANG ROAD NEAR OR AT THE TRAFFIC LIGHT JUNCTION WITH WOODLANDS ROAD ON 19th NOVEMBER 2019 @ 1.20 P.M.

Your Ref: YN 4552C
Our Ref : GBE 4237H

Dear Sirs,

1. We act for M/s Lew Ah Bee Trading, the owners of vehicle no. GBE 4237H.
2. We are instructed to claim damages against you in connection with the above accident.
3. Pursuant to the State Courts NIMA Protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop: -

Venue: **Han Car Repairs**
Address: 1001 Bukit Merah Lane 3
#01-49, Alexandra Village
Singapore 159718
Contact: Ms. Susan Chin @ 9777 7266

4. TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Regards

Winston Low
M/s Winston Low & Partners

cc : clients (GBE 4237H)

From: Winston Low [<mailto:winstlow@singnet.com.sg>]

Sent: 21 November 2019 09:46

To: 'customer_sg@lonpac.com' <customer_sg@lonpac.com>

Cc: 'weeyuweed weeyuweed' <weeyuweed@gmail.com>

Subject: ACCIDENT INVOLVING GBE 4237H & YN 4552C ALONG BUKIT PANJANG ROAD TOWARDS CHOA CHU KANG ROAD NEAR OR AT THE TRAFFIC LIGHT JUNCTION WITH WOODLANDS ROAD ON 19th NOVEMBER 2019 @ 1.20 P.M.

Your Ref: YN 4552C
Our Ref : GBE 4237H

Dear Sirs,

1. We act for M/s Lew Ah Bee Trading, the owners of vehicle no. GBE 4237H.
2. We are instructed to claim damages against you in connection with the above accident.
3. Pursuant to the State Courts NIMA Protocol, we hereby give you notice to conduct a pre-repair inspection of our client's motor vehicle at the under-stated workshop: -

Venue: **Han Car Repairs**
Address: 1001 Bukit Merah Lane 3
#01-49, Alexandra Village
Singapore 159718
Contact: Ms. Susan Chin @ 9777 7266

4. TAKE NOTICE that you are required to respond to us within 2 working days (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our client's repairers shall proceed to repair our client's vehicle.

Regards


Winston Low
M/s Winston Low & Partners

cc : clients (GBE 4237H)

Notice & Disclaimer:

The information contained in this email (including all attachments) is both confidential and protected by legal professional privilege. It is intended for the use only of the addressee named. If you are not the intended recipient, you are hereby notified that any dissemination, distribution, publication or copying of this email is strictly prohibited. If you have received this email in error, please accept our apologies, delete the original email from your system including all copies made, and notify us by return email at winstlow@singnet.com.sg

Winston Low & Partners do not guarantee the integrity and security of Internet communications. Although we have taken reasonable precautions to scan outgoing and incoming emails and attachments for viruses, we cannot guarantee this communication to be free of all viruses nor are we responsible for any consequences caused by viruses.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/11/2019 11:32
Date Of Accident	19/11/2019 13:20
Exact Location Of Accident	JUNCTION OF BT PANJANG ROAD B/F CHOA CHU KANG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE4237H
Insured/Policyholder	
Name Of Registered Owner	LEW AH BEE TRADING
Co Reg No	53318356A
Email Address	HANCARREPAIRS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82229045
Alternative Phone No	OFFICE-82229045

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100439839-04
Cover Note Number	

Driver

Name of Driver	LEW AH GEE
NRIC No	S1287840J
Date Of Birth	07/11/1958
Occupation	OUTDOOR
Date Of Driving Pass	21/11/1978
Driving Experience	40 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82229045
Fax Number	
Contact Number	OTHERS-82229045
Email Address	HANCARREPAIRS@GMAIL.COM

Address BLK 157 MEI LING STREET
 #03-70
 Postcode 104157
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN4552C
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver MAHALINGAM BALAMUGAN
 NRIC/Passport Number G79828667
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHB3532G

LONIQ

Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

TAXI
TAW NAN HOE

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please refer to **Section 2** for details of the accident to report to the police.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as prompt and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The truth and accuracy of this Form by insurance companies is an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Holders of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
7. By the signature on this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
 - i. I understand, acknowledge, agree and consent that:
 - a. My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government's agencies/authority (such as the police), for the purposes:
 - i. processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - ii. investigating the accident and/or my claims;
 - iii. carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - iv. administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - v. complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - b. all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - c. my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - d. my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - e. the information so collected under (c) above may be shared / disclosed:
 - i. to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - ii. for complying with requirements under any regulations, laws or court orders.

LEW AH BEE TRADING
653 Senja Link
#12-32 S'670653
Co Reg 53318356 A

Signature of Policyholder
Date: 20/11/2019

Signature of Insurer
Date: 20/11/2019

Sketch Plan #2



I was stationary at the traffic junction when vehicle (B) came from behind and hit my vehicle (A).
 The impact was so great that it pushed my vehicle (A) forward and hit onto vehicle (C).

DECLARATION
 (We declare the foregoing particulars are true in every respect.)

LEW AH BEE TRADING
 653 Seng Guan Link
 Tel: 32-32 5670853
 Co Reg 53318356 A

Driver's Signature & Time
 (If driver is not the policyholder)

20/4/2015
 Reporting Centre Representative's Signature
 Name: [Signature]

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 11-19019/DY / 2019
Date of Report : 11 Dec 2019

Lew Ah Bee Trading
c/o Blk 1001 Bukit Merah Lane 3
#01-49 Alexandra Village
Singapore 159718

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 19 Nov 2019

As per your instruction dated 21 Nov 2019 with regard to the above matter. We have carried out a physical inspection on the said vehicle GBE 4237 H . We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : GBE 4237 H
Model : Nissan Cabstar
Year / Capacity : 2015/2953
Chassis No : JN1SC2F24Z0857904
Engine No : ZD30346975K
Mileage : 81343
Colour : Blue

2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	: 195/70 R15	Haida	4.00	mm	Normal
REAR	O/S	: 155 R13	Tianfu	5.00/5.00	mm	Normal
FRONT	N/S	: 195/70 R15	Haida	4.00	mm	Normal
REAR	N/S	: 155 R13	Tianfu	5.00/5.00	mm	Normal

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Han Car Repairs
Blk 1001 Bukit Merah Lane 3
#01-49 Alexandra Village
Singapore 159718

5. Estimated normal period of repair : 12 working days and including lead time to complete.

6. Enclosed number of photograph : 148 copies.

7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: GBE 4237 H
 Report No: TP/ 11-19019/DY / 2019

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
1	Front windscreen rubber	Necessary	\$ 375.80	\$ 375.80 / 300 ✓
1/2	Front headlamps (RH)	Damage	\$ 838.40	\$ 838.40 / 419.20 ✓
1	Front panel	Damage	\$ 1583.70	\$ 1583.70 / 1412 ✓
1	Front panel 'CABSTAR' emblem	Necessary	\$ 48.50	\$ 48.50 ✓
1	Front grille	Damage	\$ 578.10	\$ 578.10 ✓
1	Front grille logo	Necessary	\$ 46.30	\$ 46.30 ✓
1	Front bumper	Damage	\$ 903.00	\$ 903.00 ✓
1	Front bumper reinforcement	Damage	\$ 662.60	\$ 662.60 ✓
1	Rear tailgate	Damage	\$ 1688.40	\$ 1688.40 / 1399 ✓
1	Rear tailgate 'NISSAN' sticker	Necessary	\$ 122.80	\$ 122.80 ✓
1	Rear tailgate lower panel	Damage	\$ 843.50	\$ 843.50 X R
2	Rear taillamps	Damage	\$ 430.00	\$ 430.00 ✓
2	Rear chassis members	Repair	\$ 3785.60	\$ 3785.60 ✓
			\$ 11906.70	\$ 8121.10 / 6321.59
	Discount	10.0%	\$ 1190.67	\$ 812.11 / -197
			\$ 10716.03	\$ 7308.99 / 5689.35
<u>Special Nett Items</u>				
1	Front windscreen sealant	Necessary	\$ 60.00	\$ 60.00 / 40
1	Rear tailgate '70 km/h' sticker	Necessary	\$ 25.00	\$ 25.00 / 15
1	Rear tailgate '6 PAX' sticker	Necessary	\$ 25.00	\$ 25.00 / 15
1	Rear number plate	Damage	\$ 40.00	\$ 40.00 / 30
1	Rear tailgate aluminum board	Damage	\$ 400.00	\$ 400.00 / 300 ✓
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00 / 200 ✓
1	Rear step aluminum panel	Damage	\$ 220.00	\$ 220.00 / 200 ✓
1	Front number plate	Damage	\$ 45.00	\$ 45.00 / 40 ✓
			\$ 1095.00	\$ 1095.00 / 150

Spare Parts Total \$ 11811.03 \$ 8403.99

Vehicle No: GBE 4237 H
 Report No: TP/ 11-19019/DY / 2019

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 11811.03	\$ 8403.99
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 40.00	\$ 40.00 30/
2	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 40.00	\$ 40.00 30/
3	To remove and refit air-con system, refill gas and test for leakages.	\$ 180.00	\$ 120.00 /
4	To remove and refit dashboard, meters instrument, disconnect wirings, ductings, connectors to facilitate the repairs.	\$ 300.00	\$ 250.00 200/
5	To remove and refit front windscreen glass.	\$ 150.00	\$ 120.00 /
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1800.00	\$ 1540.00 1700/
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1500.00	\$ 1100.00 700/
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 200.00	\$ 120.00 50/
Total		<u>\$ 16021.03</u>	<u>\$ 11733.99</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 9400.00

SDLS: NINE THOUSAND FOUR HUNDRED ONLY


 Qualified Appraiser

P-5689-35
 NI-780
 L-2450
 8919.35
 LIS-7135-48
 = 7150

10 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS3/LPC19020771/Eyd3e2-1	
300 BEACH ROAD		Date : 25-02-2020	
#17-04/07 THE CONCOURSESINGAPORE 199555		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 4552C	Veh. Inspected	GBE 4237H
Policy No.		Coverage (\$)	0.00
Claim No.	18/19/19/VC05/022676	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	20/02/2020
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1SC2F24Z0857904	Colour	BLUE
Odometer	81343	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/70 R15C	HAIDA	4 mm
L/H Front Tyre	195/70 R15C	HAIDA	4 mm
R/H Rear Tyre	195/70 R15C	HAIDA	4 mm
L/H Rear Tyre	195/70 R15C	HAIDA	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/11/2019	Inspection Date	25/11/2019
Survey held at	HAN CAR REPAIRS BLK 1001 #01-49 BUKIT MERAH LANE 3 ALEXANDRA VILLAGE SINGAPORE 159718		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4237H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT WINDSCREEN RUBBER (N)	NECESSARY	375.80	300.00
2	FRONT HEADLAMPS (N)	O/S DAMAGED	838.40	419.20
1	FRONT PANEL (N)	DAMAGED	1,583.70	1,412.00
1	FRONT PANEL 'CABSTAR' EMBLEM (N)	NECESSARY	48.50	48.50
1	FRONT GRILLE (N)	DAMAGED	578.10	578.10
1	FRONT GRILLE LOGO (N)	NECESSARY	46.30	46.30
1	FRONT BUMPER (N)	DAMAGED	903.00	903.00
1	FRONT BUMPER REINFORCEMENT (N)	DAMAGED	662.60	662.60
1	REAR TAILGATE (N)	DAMAGED	1,688.40	1,399.00
1	REAR TAILGATE 'NISSAN' STICKER (N)	NECESSARY	122.80	122.80
1	REAR TAILGATE LOWER PANEL (N)	TO REPAIR SEE LABOUR	843.50	-
2	REAR TAILLAMPS (N)	DAMAGED	430.00	430.00
2	REAR CHASSIS MEMBERS (N)	TO REPAIR SEE LABOUR	3,785.60	-
	LESS 10% DISCOUNT		-1,190.67	-632.15
			10,716.03	5,689.35
SPECIAL NETT ITEMS				
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR TAILGATE '70 KM/H' STICKER (SN)	NECESSARY	25.00	15.00
1	REAR TAILGATE '6 PAX' STICKER (SN)	NECESSARY	25.00	15.00
1	REAR NUMBER PLATE (SN)	DAMAGED	40.00	30.00
1	REAR TAILGATE ALUMINUM BOARD (SN)	DAMAGED	400.00	300.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR STEP ALUMINUM PANEL (SN)	DAMAGED	220.00	150.00
1	FRONT NUMBER PLATE (SN)	DAMAGED	45.00	30.00
			1,095.00	780.00
LABOUR				
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		40.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		40.00	30.00
	TO REMOVE AND REFIT AIR-CON SYSTEM, REFILL GAS AND TEST FOR LEAKAGES.		180.00	120.00
	TO REMOVE AND REFIT DASHBOARD, METERS INSTRUMENT, DISCONNECT WIRINGS, DUCTINGS, CONNECTORS TO FACILITATE THE REPAIRS.		300.00	200.00
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.		150.00	120.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR TAILGATE LOWER PANEL AND REAR CHASSIS MEMBERS.		1,800.00	1,200.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,500.00	700.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		200.00	50.00
			4,210.00	2,450.00
	GRAND TOTAL		16,021.03	8,919.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,150.00

Report Ref No. CS3/LPC19020771/Eyd3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.