



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19016594/T1td3s2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 09-04-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6782X	Veh. Inspected	SMJ 8651L
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19080871	Excess (\$)	0.00
Assign From	DERRICK TAN	Assign Date	20/02/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2040312A841442	Colour	BLACK
Odometer	86171	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/08/2019	Inspection Date	19/04/2019
Survey held at	1 BUKIT BATOK CRESENT #05-55		
Repairer	GARAGE B PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------