

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: TL Swift Transport
 INSURER: MS First Capital Insurance Limited
 POLICY NO: 5113185313
 DOA: 19/02/2020

REPAIR ESTIMATE

Est No. : EST20020032
 Date : 19-Feb-20
 Vehicle Num : SMP7237A
 Make/Model : Honda Shuttle
 Chassis # : GK82100208
 Engine # : L15B6020267
 Yr. Of Manu : 2019

No.	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	Rear Bumper x(R)	1.00	1250.60	1250.60 \$
2	Rear Bumper Clips xnn	10.00	3.50	35.00
3	Rear Bumper Chrome Garnish ser	1.00	108.30	108.30
4	Rear Bumper Reflector LH/RH xnn	2.00	55.00	110.00
5	End Panel ?	1.00	560.80	560.80
6	End Panel Top Garnish xnn	1.00	155.50	155.50
7	Tailgate Buc	1.00	1293.00	1293.00 \$1195
8	Tailgate "LOGO" Emblem nec	1.00	38.00	38.00
9	Tailgate "SHUTTLE" Emblem nec	1.00	55.00	55.00
10	Inner Taillamp RH/LH ?	2.00	520.00	1040.00
11	Tailgate Chrome Garnish ser	1.00	83.10	83.10
12	Rear Number Plate Lamp xnn	2.00	35.20	70.40
13	Tailgate Lock ?	1.00	187.50	187.50
14	Tailgate Lock Stricker xnn	1.00	34.70	34.70
				Amt S\$ 5021.90
				Discount (20.00%) S\$ 1004.38
				Subtotal S\$ 4017.52

Section: SPECIAL NETT ITEMS

15	Rear Number Plate With Cover ser	1.00	50.00	50.00
				Amt S\$ 50.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 50.00

Continue on next page...

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: TL Swift Transport
 INSURER: MS First Capital Insurance Limited
 POLICY NO: 5113185313
 DOA: 19/02/2020

REPAIR ESTIMATE

Est No. : EST20020032
 Date : 19-Feb-20
 Vehicle Num : SMP7237A
 Make/Model : Honda Shuttle
 Chassis # : GK82100208
 Engine # : L15B6020267
 Yr. Of Manu : 2019

No.	Description	Qty	U/P	Amt
Section: LABOUR				
16	To Panel Beat on Necessary Damaged Parts	1.00	780.00	780.00 \$450
17	To Sand Down, Putty and Spray Paint on Necessary Damaged Parts	1.00	580.00	580.00 \$400
18	To Check Wiring	1.00	50.00	50.00
19	To Remove & Refit Rear Windscreen to Facilitate Repair	1.00	120.00	120.00 \$120
Amt S\$				1530.00
Discount (0.00%) S\$				0.00
Subtotal S\$				1530.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Ram (LKK)
20/2/2020 1745hrs
Parasuram@lkkauto.com
88622778
(LIS)
Dismantle required
(5) days

 

Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 4017.52
SPECIAL NETT ITEMS Subtotal S\$ 50.00
LABOUR Subtotal S\$ 1530.00
Total S\$ 5597.52