



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20003057/Aga3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 03-06-2020



ATTN:RICHARD

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SME 5283L	<b>Veh. Inspected</b>	SMM 7570C
<b>Policy No.</b>	VPA/P2190157	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S0M02GY3	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	24/02/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA SHUTTLE HYBRID	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	GP71214543	<b>Colour</b>	SILVER
<b>Odometer</b>	66586	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/55 R15	CRUCERO	6 mm
<b>L/H Front Tyre</b>	195/55 R15	CRUCERO	6 mm
<b>R/H Rear Tyre</b>	195/55 R15	CRUCERO	6 mm
<b>L/H Rear Tyre</b>	195/55 R15	CRUCERO	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.  
DAMAGES SEE DETAILS

### 5. General Information

<b>Accident Date</b>	20/02/2020	<b>Inspection Date</b>	24/02/2020
<b>Survey held at</b>	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**