

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AXA	DATE	: 21/02/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SMM7570C		<i>Cecilia</i>
MODEL	: HONDA SHUTTLE		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 20/02/2020
		TIME	: 16:40HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	BONNET <i>Neu</i>	1	\$ 820.00	\$ 820.00	x
2	FRONT BUMPER <i>toru</i>	1	\$ 1,163.00	\$ 1,163.00	✓
3	FRONT BUMPER SIDE RETAINER <i>LH only</i>	2	\$ 62.40	\$ 124.80	<i>62.40</i>
4	HEADLAMP <i>could LH</i>	2	\$ 444.60	\$ 889.20	<i>444.60</i>
5	FRONT FENDER LH <i>Dented.</i>	1	\$ 468.00	\$ 468.00	-
6	FRONT FENDER INNER COWLING LH <i>Not all</i>	1	\$ 254.00	\$ 254.00	+
7	FRONT FENDER EMBLEM 'HYBRID' <i>Neu</i>	1	\$ 80.00	\$ 80.00	-
8	FRONT DOOR LH <i>Repair</i>	1	\$ 1,288.90	\$ 1,288.90	x
9	FRONT DOOR HINGE <i>Not all</i>	2	\$ 80.00	\$ 160.00	x
10	FRONT SIDE MIRROR LH <i>Damaged</i>	1	\$ 587.40	\$ 587.40	-
11	FRONT SIDE MIRROR COVER LH <i>Delivered</i>	1	\$ 89.40	\$ 89.40	✓
12	FRONT KNUCKLE ARM LH <i>Neu</i>	1	\$ 398.00	\$ 398.00	x
13	FRONT KNUCKLE BEARING LH <i>Neu</i>	1	\$ 198.90	\$ 198.90	✓
14	FRONT WHEEL HUP LH <i>only</i>	1	\$ 284.00	\$ 284.00	✓
15	FRONT SHOCK ABSORBER LH <i>Neu</i>	1	\$ 494.50	\$ 494.50	x
16	FRONT LOWER ARM LH <i>Best</i>	1	\$ 425.40	\$ 425.40	✓

TOTAL PRICE \$ 7,725.50

LESS 25% \$ 1,931.38

3803.10

3042.48

SUB TOTAL PRICE \$ 5,794.13

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 ✓
2	FRONT FENDER SEALANT RH <i>new</i>	1	\$ 80.00	\$ 80.00 ✓
3	FRONT FENDER COWLING RH CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00 ✓
4	FRONT WHEEL TYRE <i>new</i>	1	\$ 350.00	\$ 350.00 ✓
5	FRONT WHEEL SPORT RIM (SET) <i>lt</i>	1	\$ 800.00	\$ 800.00 ✓ 400
		<i>420</i>	TOTAL	\$ 1,270.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>450</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>400</i>
3	WIRING AND BULB CHECK	\$ 120.00	<i>30</i>
4	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	<i>x</i>
5	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 350.00	<i>220</i>
6	FOUR WHEEL ALIGHMENT	\$ 120.00	<i>80</i>
7	TO REMOVE AND REFIX FRONT DOOR MECHANISM	\$ 450.00	<i>x</i>
TOTAL		\$4,820.00	<i>1180</i>

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,064.13
 TOTAL LABOUR COST : \$ 4,820.00
 TOTAL REPAIR COST : \$ 11,884.13

Advan King
2/2 24/02/20

APPROVED DETAILS

EXCESS

NO. OF WORKING DAY
 RE-SURVEY
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To inspect damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

05 Days
total: 4642.48
L/S: 3.7K ✓