

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT NETT PRICE	TOTAL NETT PRICE
28	REAR BUMPER SIDE RETAINER LH/RH / BR	2	\$ 35.20	\$ 70.40
29	REAR BUMPER INNER SPONGE / BR	1	\$ 125.30	\$ 125.30
30	REAR BUMPER IMPACK BRACKET LH/RH X NAI	2	\$ 96.90	\$ 193.80
31	REAR BUMPER INNER SIDE SHIELD LH/RH X NAI	2	\$ 51.30	\$ 102.60
32	REAR BUMPER INNER TAILGATE ANTENNA SENSOR X / BR	1	\$ 196.50	\$ 196.50
33	REAR END PANEL / ON	1	\$ 552.80	\$ 552.80
34	REAR END PANEL INNER TOP GARNISH / CRU	1	\$ 105.90	\$ 105.90
35	REAR END PANEL TAILGATE LOCK STEIKER X NAI	1	\$ 94.90	\$ 94.90
36	SPARE TYRE PANEL X R	1	\$ 611.90	\$ 611.90
37	SPARE TYRE PANEL INNER TOP TOOLS SPONGE / CRU	1	\$ 163.90	\$ 163.90
38	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD / TN	1	\$ 243.70	\$ 243.70
39	SPARE TYRE PANEL INSULATOR MAT 'ORIGINAL' / MC	1	\$ 210.90	\$ 210.90
40	SPARE TYRE PANEL LOWER TOW HOOK BRACKET X NAI	1	\$ 154.10	\$ 154.10
41	REAR FENDER INNER TRIM BOARD LH/RH / CRU	2	\$ 286.30	\$ 572.60
42	REAR EXHAUST SILENCER BOX X NAI	1	\$ 552.90	\$ 552.90
43	REAR EXHAUST RUBBER MOUNTING X NAI	3	\$ 36.10	\$ 108.30
44	REAR EXHAUST ALUMINIUM HEAT SHIELD X NAI	1	\$ 144.10	\$ 144.10
TOTAL PRICE				\$ 15,081.89
LESS -10%				\$ (1,508.19)
SUB TOTAL PRICE				\$ 13,573.70

6252.80
- 10%
5627.52

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR TAILGATE SEALANT / MC	1	\$ 100.00	\$ 100.00
2	REAR TAILGATE WINDSCREEN PRIMER WITH SEALANT SET / MC	1	\$ 100.00	\$ 100.00
3	REAR TAILGATE OUTER GARNISH CLIPS SET / MC	1	\$ 50.00	\$ 50.00
4	REAR TAILGATE INNER TRIM BOARD CLIPS SET / MC	1	\$ 80.00	\$ 80.00
5	REAR TAILLAMP CLIPS SET LH/RH X NAI	2	\$ 50.00	\$ 100.00
6	REAR TAILLAMP INNER PANEL SEALANT LH/RH X NAI	2	\$ 60.00	\$ 120.00
7	REAR BUMPER CLIPS SET / MC	1	\$ 60.00	\$ 60.00
8	REAR END PANEL SEALANT / MC	1	\$ 100.00	\$ 100.00
9	REAR END PANEL INNER TOP GARNISH CLIPS SET / MC	1	\$ 50.00	\$ 50.00
10	SPARE TYRE PANEL SEALANT X NAI	1	\$ 120.00	\$ 120.00
11	REAR FENDER INNER TRIM BOARD CLIPS SET LH/RH / MC	2	\$ 80.00	\$ 160.00
12	REAR EXHAUST GASKET X NAI	1	\$ 35.00	\$ 35.00

TOTAL \$ 1,075.00

195

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,600.00	1190	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,400.00	1900	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 175.00	50	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 250.00	X	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ 150.00	120	
TO PERFORM TRANSFER REAR TAILGATE MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 150.00	80	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	30	
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 180.00	X	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	80	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	30	

TOTAL

\$ 4,425.00

2520

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5627-52
 N-195
 L-2520
 8342-52
 415-6674-01
 = 6650

SMP1878P

QUOTATION SUMMARY

PAGE 04

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	14,648.70
TOTAL LABOUR COST	:	\$	4,425.00
TOTAL REPAIR COST	:	\$	<u>19,073.70</u> ✶

APPROVED DETAILS

NO. OF REPAIR DAYS : 7 DAYS

REPAIR UNDER : PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM : Steve CLKK) WH ProjL

CONTACT NUMBER : L/S

FAX NUMBER : Ry AL SLJ

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

24/2/20, 2.30pm

EXCESS :

0. c
1018.2 +

82.9 +
12.1 +
427.3 +
55. +
255.6 +
99.1 +
36.2 +
282.1 +
36.3 +
213.2 +
106.2 +
871.6 +
460. +
70.4 +
125.3 +
196.5 +
552.8 +
105.9 +
163.9 +
243.7 +
210.9 +
572.6 =
6,252.8 *

6,252.8 x
90. %
5,627.52 *

40. +
30. +
10. +
20. +
30. +
30. +
15. +
20. =
195. *

4/8 - \$66.50

1,100. +
1,000. +
50. +
30. +
120. +
80. +
30. +
80. +
30. =
2,520. *

5,627.52 +
195. +
2,520. =
8,342.52 *

8,342.52 x
80. %
6,674.016 *

0. c