

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
UNITED OVERSEAS INSURANCE LTD F			Ref : CS/UOI20003087/Ayd3e2		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date: 08-05-2020 Code: UOI2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKZ 2365S	Veh. Inspected	SJG 7777R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	M12D13002003	Excess (\$)	0.00	
	Assign From	JOSEPHINE WONG	Assign Date	24/02/2020	
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 320I	c.c	1997	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	WBA3B16020NS50439	Colour	BLACK	
	Odometer	55305	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
	L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
	R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
	L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	21/02/2020	Inspection Date	25/02/2020	
	Survey held at PREMIUM CARZ SERVICES PTE LTD				
		1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
	-				