

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 02.03.20

TO : **AIG** MOTOR CLAIMS DEPTS

VEHICLE NO : **SLS6912L**

MODEL : **TOYOTA C-HR**

DATE OF ACCIDENT : 20.02.20

TIME OF ACCIDENT : 10:55HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>3 piece</i>	1	\$ 1,080.60	\$ 1,080.60
2	FRONT BUMPER SIDE RETAINER	1	\$ 107.40	\$ 107.40
3	FRONT DOOR LOWER PROTECTOR RH <i>lit</i>	1	\$ 265.10	\$ 265.10
4	FRONT FENDER RH <i>Repair</i>	1	\$ 578.60	\$ 578.60
5	FRONT FENDER ARCED GARNISH RH <i>new</i>	1	\$ 180.80	\$ 180.80
6	FRONT FENDER COWLING RH <i>new</i>	1	\$ 156.40	\$ 156.40
7	FRONT WHEEL RIM RH <i>lit</i>	1	\$ 1,580.30	\$ 1,580.30
8	FRONT ABS SENSOR RH <i>new</i>	1	\$ 480.20	\$ 480.20
9	FRONT KNUCLE ARM RH <i>new</i>	1	\$ 450.30	\$ 450.30
10	FRONT KNUCLE BEARING RH	1	\$ 199.50	\$ 199.50
11	FRONT WHEEL HUP RH	1	\$ 367.70	\$ 367.70
12	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 530.60	\$ 530.60
13	FRONT LOWER ARM RH	1	\$ 548.70	\$ 548.70
14	SIDE MIRROR RH <i>new</i>	1	\$ 1,441.90	\$ 1,441.90
15	FRONT DOOR RH <i>Dented</i>	1	\$ 1,295.10	\$ 1,295.10
16	FRONT DOOR OUTER MOULDING RH <i>new</i>	1	\$ 175.40	\$ 175.40
17	FRONT DOOR WEATHER STRIP RH <i>new</i>	1	\$ 325.10	\$ 325.10
18	FRONT DOOR INNER LOCK RH <i>new</i>	1	\$ 589.10	\$ 589.10
19	FRONT DOOR LOCK CATCH RH <i>new</i>	1	\$ 24.20	\$ 24.20
20	FRONT DOOR INNER TRIM BOARD RH <i>new</i>	1	\$ 1,097.10	\$ 1,097.10
21	FRONT DOOR POWER WINDOW MOTOR RH <i>new</i>	1	\$ 779.10	\$ 779.10
22	FRONT DOOR SPEAKER RH <i>new</i>	1	\$ 436.60	\$ 436.60
23	FRONT DOOR REGULATOR RH <i>new</i>	1	\$ 248.50	\$ 248.50
24	SIDE SKIRT RH <i>lit</i>	1	\$ 609.70	\$ 609.70
25	REAR DOOR RH <i>Repair Dented</i>	1	\$ 1,279.80	\$ 1,279.80
26	REAR DOOR LOWER GARNISH PROTECTOR RH <i>lit</i>	1	\$ 258.40	\$ 258.40
27	REAR DOOR OUTER MOULDING RH <i>new</i>	1	\$ 167.30	\$ 167.30
28	REAR DOOR HINGE RH <i>new</i>	2	\$ 48.90	\$ 97.80

TO : **AIG MOTOR CLAIMS DEPTS**
 VEHICLE NO : **SLS6912L**
 MODEL : **TOYOTA C-HR**
 DATE OF ACCIDENT : 20.02.20
 TIME OF ACCIDENT : 10:55HRS

29	REAR DOOR CHECKER RH <i>Ne n</i>	1	\$ 106.70	\$ 106.70	+
30	REAR DOOR WEATHER STRIP RH <i>Ne n</i>	1	\$ 319.40	\$ 319.40	+
31	REAR DOOR INNER LOCK RH <i>3M</i>	1	\$ 568.70	\$ 568.70	+
32	REAR DOOR LOCK CATCH RH <i>3M</i>	1	\$ 25.30	\$ 25.30	+
33	REAR DOOR INNER TRIM BOARD RH <i>3M</i>	1	\$ 976.40	\$ 976.40	+
34	REAR DOOR POWER WINDOW MOTOR RH <i>3M</i>	1	\$ 752.30	\$ 752.30	+
35	REAR DOOR SPEAKER RH <i>Ne n</i>	1	\$ 214.70	\$ 214.70	+
36	REAR FENDER ARCED GARNISH RH <i>Ne n</i>	1	\$ 194.60	\$ 194.60	+
37	REAR WHEEL RIM RH <i>Ne n</i>	1	\$ 1,580.30	\$ 1,580.30	+
38	REAR ABS SENSOR RH	1	\$ 256.40	\$ 256.40	+
39	REAR LOWER ARM RH	1	\$ 542.30	\$ 542.30	+
40	REAR UPPER ARM RH <i>NP</i>	1	\$ 625.40	\$ 625.40	+
41	REAR SWING ARM RH <i>Ne</i>	1	\$ 594.70	\$ 594.70	+
42	REAR SHOCK ABSORBER RH	1	\$ 530.60	\$ 530.60	+
43	REAR LINKAGE RH	1	\$ 101.40	\$ 101.40	+

SN: ~~500~~ 3708-10
 2781-07

TOTAL PRICE \$ 22,740.50
 LESS 25% \$ 5,685.13
SUB TOTAL PRICE \$ 17,055.38

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>3M</i>	1	\$ 50.00	\$ 50.00	+
2	FRONT FENDER COWLING CLIP (SET) <i>3M</i>	1	\$ 50.00	\$ 50.00	+
3	FRONT FENDER ARCED GARNISH CLIP LH (SET) <i>Ne n</i>	1	\$ 50.00	\$ 50.00	+
4	FRONT WHEEL TYRE RH <i>Ne n</i>	1	\$ 450.00	\$ 450.00	+
5	SIDE SKIRT RH CLIP <i>Ne n</i>	1	\$ 80.00	\$ 80.00	30
6	FRONT DOOR OUTER MOULDING CLIP RH (SET) <i>Ne n</i>	1	\$ 50.00	\$ 50.00	+
7	FRONT DOOR TRIM BOARD CLIP (SET) <i>Ne n</i>	1	\$ 50.00	\$ 50.00	+
8	SIDE SKIRT CLIP RH (SET) <i>Repaired</i>	1	\$ 80.00	\$ 80.00	+
9	REAR DOOR LOWER GARNISH PROTECTOR CLIP RH (SET) <i>Ne n</i>	1	\$ 50.00	\$ 50.00	20
10	REAR DOOR TRIM BOARD CLIP (SET) <i>Ne n</i>	1	\$ 80.00	\$ 80.00	+
11	REAR FENDER ARCED GARNISH CLIP RH (SET) <i>3M</i>	1	\$ 50.00	\$ 50.00	+
12	BRAKE OIL <i>Ne n</i>	1	\$ 30.00	\$ 30.00	+

50

TOTAL \$ 1,070.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	500.

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLS6912L**
 MODEL : **TOYOTA C-HR**
 DATE OF ACCIDENT : 20.02.20
 TIME OF ACCIDENT : 10:55HRS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	400
3	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	x
4	TUFF COAT	\$ 250.00	40
5	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
6	WIRING CHECK	\$ 180.00	30
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	x
8	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	x
9	REMOVE & REFIX AUDIO SPEAKER	\$ 100.00	x
10	RESET ABS LIGHT	\$ 350.00	x
11	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	✓
12	TRANSFER REAR DOOR MECHANISM	\$ 80.00	✓
13	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	x.
14	FOUR WHEEL ALIGNMENT	\$ 120.00	80
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x.

TOTAL \$ 7,040.00

ESTIMATE REPORT

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts to be replaced will be confirmed
 • Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• NB: THIS IS ONLY AN ESTIMATE AND

Supplementary item(s) must be resurveyed and is subject to change in the course of repair. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED

ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

Acknowledged by Repairer

PARTS PRICES ARE SUBJECT TO CHANGES.

Signature:

Date:

Adrian Lj
 1/5 02/03/20
 05 days

total: 4491.07

1/5 3.6K

1210