



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H

REPAIR PERFORMA INVOICE

SOMPO

Vehicle number	SLT9700G
Make / Model	TOYOTA HARRIER
Chassis number	ZSU600083968
Accident date	23/2/20
Reference	2002-44

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	REAR BUMPER SPONGE	245.90 381.02 <i>com</i> ✓
		381.02
	Less 25%	95.25
		285.77

184.42