



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC20000243/Gyf3s2-1

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 28-04-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 7488R	Veh. Inspected	GBC 507R
Policy No.		Coverage (\$)	0.00
Claim No.	19/20/20/VC05/022860	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	25/02/2020

2. Vehicle Particulars & Condition

Make & Model	FIAT FIORINO 1.3	c.c	1248
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	ZFA22500000160033	Colour	SILVER
Odometer	161479	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14	GRENLANDER	6 mm
L/H Front Tyre	175/70 R14	GRENLANDER	6 mm
R/H Rear Tyre	175/70 R14	GRENLANDER	6 mm
L/H Rear Tyre	175/70 R14	GRENLANDER	6 mm

4. Description of Damages

THE VEHICLES SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/01/2020	Inspection Date	06/01/2020
Survey held at	PEK TIONG AUTO SERVICES BLK 1017 YISHUN INDUSTRIAL PARK A #01-250 SINGAPORE 768759		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------