

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG NO : 201316380R

Vehicle Number : SJD 9755G

Date : 24.02.2020

Vehicle Model : TOYOTA VIOS E

Chassis : MR053HY9305057335

Accident Date : 23.02.2020

TP Ins. AIG

Original Reg Date : 11.04.2008 (10.04.2028)

## ESTIMATE

1	1 pc	Boot Lid			596.20	bt ✓
2	1 pc	Boot Lid Badge			48.00	nei ✓
3	1 pc	Boot Lid Emblem E			52.00	nei ✓
4	1 pc	Boot Lid Emblem VIOS			52.00	nei ✓
5	1 pc	Boot Lid Emblem SPORT			52.00	nei ✓
6	2 pcs	Boot Lid Stopper	18.00		36.00	x nn
7	1 pc	Boot Lid Inner Lock			129.50	? bt ✓
8	1 pc	Boot Lid Weatherstrip			192.20	nei ✓
9	2 pcs	Boot Lid Hinges	72.40		144.80	Ry
10	1 pc	Rear Bumper			556.20	de ✓
11	2 pcs	Rear Bumper Side Retainers	80.70	LH-x nn	161.40	RH de ✓
12	2 pcs	Rear Bumper Attachment Retainers	56.20	LH-y nn	112.40	RH de ✓
13	1 set	Rear Bumper Clips			50.00	30 nei ✓
14	1 pc	Rear Bumper Brackets RH		LH-y	87.20	RH de ✓
15	1 pc	Rear Bumper Reflectors RH			98.00	? cra ✓
16	1 pc	End Panel			612.50	bt ✓
17	1 pc	End Panel Top Trim			227.70	cm ✓
18	1 set	End Panel Top Trim Clips			30.00	20w ✓
19	2 pcs	Spare Tyre Panel Top Side Sponge	192.00		384.00	de ✓
20	1 pc	Rear Fender Inner Trim RH			256.10	x nn
21	1 set	Rear Fender Inner Trim Clips			40.00	x nn
22	1 pc	Rear Fender Inner Shield RH			59.60	nei ✓
23	1 set	Rear Fender Inner Shield Clips		15	25.00	nei ✓
24	2 pcs	Taillamps	343	396.40	686 792.80	at ✓
25	2 pcs	Taillamps Inner Sealer		38.00	nn 76.00	x
26	2 set	Taillamps Clips		25.00	50.00	nei ✓
27	1 pc	Taillamps Panels LH			131.50	Ry
28	1 pc	Rear Exhaust Silencer			683.10	Ry
29	2 pcs	Rear Exhaust Mountings		42.70	nn 85.40	x
30	1 pc	Rear Exhaust Gasket			nn 59.50	x

5,881.10

Less 25% 1,470.28

C/F 4,410.83

4085  
25% - 3063.75

# EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG NO : 201316380R

Vehicle No : SJD 9755G

B/F

4,410.83

### Special Nett

1	1 set	Boot Lid Sticker	80.00
2	1 set	Body Panel Joint Sealant	120.00
3	1 set	Reverse Sensor	250.00
4	1 pc	Rear Bumper Spoiler	800.00
5	1 pc	Rear Exhaust Chrome Pipe	120.00

4000  
6000  
2000  
du 500  
at  
920

### Labour

Panel Beating	1,200.00
Spray painting	1,300.00
Check Wiring	40.00
Anti rust	100.00
Remove and install carpet and seat.	120.00
Remove and install reverse sensor	90.00
Remove and install rear exhaust pipe	120.00

900.  
1100  
30.  
30.  
60.  
30.  
60 2210

8,750.83

Less 20% 1,750.17

**Lump sum 7,000.66**

3063.75

920

2210

6193.75

4/5 \$4950

7 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749  
'wp'

25/2/2020 3:57pm

Lump sum

Review after repair.

Taufik / Khairi on  
0.7 days