



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
 Email: motor@wahhong.sg
 (199806235M)

Vehicle No. EM989U MERCEDES BENZ E200

QTY	DESCRIPTION (SUPPLEMENTARY PARTS)	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Driver seat headrest mechanism RH ✓	malfunction	680.00 ✓	
1	Passenger seat headrest mechanism LH ✓	malfunction	680.00 ✓	
			1360.00	
		Less 10%	136.00	
			1224.00	
		Total Parts	1224.00	

Steve
 10/3/20

1360
 -10%
 1224