

fwg



Automobile Integrated Management Pte Ltd
Co. & G.S.T. Reg no. 201605297G
Office: 28 Sin Ming Lane #07-147 Midview City Singapore
573972
Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing)
Singapore 415933
Email: automim.claim@gmail.com Tel: 9119 8371

ESTIMATE

Our Ref: AC2020016/TP/GBB8211X-22.02.2020

Vehicle number: GBB8211X

Vehicle Made & Model: NISSAN NV200

Items	Qty	^{not} Use Items
1	1	Tailgate - LH
2	1	Tailgate outer garnish
3	1	Tailgate lower lock
4	1	Tailgate inner lock
5	1	Tailgate inner lock actuator
6	1	Tailgate inner trim
7	1	Tailgate checker
8	1	Tailgate opening w/strip
9	1	Tailgate - RH
10	1	Tailgate w/strip
11	1	Tailgate lower lock
12	1	Tailgate lower lock striker
13	1	Tailgate checker
14	2	Taillamps - L/R @ 286.50
15	1	Rear bumper
16	2	Rear bumper reflectors - L/R @ 65.50
17	1	Rear bumper tow cover
18	1	Rear bumper foam
19	2	Rear bumper side retainers - L/R @ 48.60
20	1	Rear end panel
21	1	Rear end panel inner member
22	1	Rear end panel top trim
23	1	Rear exhaust pipe
24	1	Rear spare wheel carrier
25	1	Rear spare wheel lock catch

	Amount \$
20/set	1,281.60
17	336.10 X
17	106.50 X
17	183.90 X
17	190.60 X
17	130.50 X
17	89.90 X
20/set	130.60
17	960.90 X
rec	86.90
17	106.50 X
17	41.50 X
17	89.90 X
17	573.00 X
20/set	624.80
17	131.00 X
17	28.90 X
17	130.20 X
17	97.20 X
17	424.00 X
17	518.10 X
17	89.90 X
17	291.60 X
17	175.60 X
17	105.20 X

Sub-total 6,924.90
Less 10% 692.49
Total List 6,232.41

Special Nett Items

26	1 set	Rear	reverse sensor
27	1	Rear	stricker "70 KM/H"
28	1	Rear	sticker "5 PAX"
29	1 set	Rear	bumper clip

should 280.00 200
rec 10.00 ✓
rec 10.00 ✓
rec 30.00 ✓

not returned
LH
27/2/20
1/5 \$2700
3 days.
Take the other way

30	2 set	Tailgate glass sealant - L/R @ 60	120.00	80
31	2 set	Tailgate foam tape - L/R @ 45	90.00	X
32	1 set	Tailgate inner trim clip	60.00	X
Total Special Nett			<u>600.00</u>	

Labour charges

33	To check rear electrical wiring	50.00	30
34	To remove, refix tailgate glass	300.00	200
35	To remove, refix rear reverse sensor	80.00	50
36	To remove, refix rear exhaust	100.00	X
37	To respray undercoating	150.00	60
38	To remove, refix rear interior trims to assist repair	120.00	X
39	To respray painting and etc	1,200.00	300
40	Panel beating, cut, weld remove & replacing above parts	1,500.00	500
Total Labour		<u>3,500.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

10,332.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-212390
1070
P-1911-57
S-N-330.00
L-1140.00
3381.57
202
2205