

JHAUTO TRADING

Blk 14 Defu Lane 10

#01-398

Singapore 539195

H/P: 9771 8731

Email: gjh-wjh@hotmail.com

Business Registration : 53240776L

CASH SALE

Invoice Date: 20/02/20

Vehicle No: SKZ1749A

Make/Model: Honda Vezel

Chassis No:

Mileage:

To: 3rd Party Claim

S/N	QUANTITY	PARTICULARS	UNIT PRICE	AMOUNT (\$)
01	01	Rear Bumper <i>crn /</i>		\$480.50
02	01	Rear Boot <i>bt /</i>		\$802.50
03	01	Rear Inner Panel <i>repair</i>		\$406.60
04	01	Rear Windscreen (Dark) <i>X</i>		\$963.00
05	02	Windscreen Gums <i>na /</i>		\$80.00
06		Windscreen Labour <i>na /</i>	<i>120</i>	\$150.00
07	01	Rear Right Tail Lamp <i>X</i>		\$385.20
08	02	Rear Bumper Retainer <i>X</i>	\$40.60	\$81.20
09	01	Rear Boot Moulding <i>na /</i>		\$135.70
10	1 Set	Reverse Sensor <i>?</i>		\$180.00
11		Reverse Sensor Labour <i>na /</i>	<i>60</i>	\$120.00
12		Rear Boot Lock <i>bt /</i>		\$245.00
13		Rear Bumper Plastic Garnish <i>X</i>		\$385.00
14	02	Rear Boot Hinges <i>X</i>	\$68.00	\$136.00
15		Windscreen Moulding <i>na /</i>		\$117.70
16		Honda Emblem, Vezel Emblem <i>X</i>		\$120.00
17		Labour For Accident Area, Panel Re-alignment & Above Parts Installation	<i>500</i>	\$1800.00
18		Spray Painting For Accident Area	<i>600</i>	\$900.00
			Total:	\$7488.20

Rasul

Hp 90010068

5 days

L/S

24/02/2020 @ 1150

Resy after repair