



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20003187/Ksd3e2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 04-06-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKL 1247E	Veh. Inspected	JQQ 2293
Policy No.		Coverage (\$)	0.00
Claim No.	C10005674	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	24/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA INNOVA (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	PN111NV4018641602	Colour	METALLIC GREY
Odometer	59161	Steering	JAMMED
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R15	MICHELIN	9 mm
L/H Front Tyre	205/65 R15	MICHELIN	9 mm
R/H Rear Tyre	205/65 R15	MICHELIN	9 mm
L/H Rear Tyre	205/65 R15	MICHELIN	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/02/2020	Inspection Date	25/02/2020
Survey held at	AE AUTO PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
--	------------------------