

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\; FAX$

Immediate Advice

To: AXA Insurance Pte Ltd DATE: 16/06/2020

Survey Details:

Date of loss	17.02.2020
Date of appointment	26.02.2020
Date of survey	27.02.2020
Location of survey	Bifrost Auto Pte Ltd

Vehicle Details:

Claim Type:	Third party	7
Vehicle number	SHC8425U	7
Make and Model	HYUNDAI I40 1685cc	
Date of registration	03.09.2015	1
Excess		
Market Value/ Book Value	-	(est)
Parf/COE Rebate	-	(est) (est)
Nett Value/ ERV	-	(est)

Repair details:

Initial Estimate	\$ 29,036.12

Proposed/Revised repair cost:

Total Lump Sum(if applicable)	\$ \$	11,028.24 8,800.00
Total	خ ا	11 020 24
Supplementary	\$	550.88
Labour	\$	1,930.00
Check items (estimate)		NIL
Parts	\$	8,547.36

Number of days for repair	<u>7</u>



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Remarks:

Insured driver made right turn and collided with third party		

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 9,416.00	
Loss of use	NIL	
Loss of rental	\$ 1,149.50	(10days x \$114.95)
Loss of income	\$ 500.00	(10days x \$50.00)
LTA/GIA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 11,072.95	