

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO: SXXX7209J
POO BEE HUAT
BLK 52 NEW UPPER CHANGI ROAD
15-1496
SINGAPORE 461052
TEL: FAX:
PH: 96753872
ATTN:

ESTIMATE BILL

Number: EB00005424
Date: 21/02/2020
Case No: AD00010983
Vehicle No: CB6478U
Chassis: BE637JB00332
Year of Mfr: 2000
Policy No:
Model: MITSUBISHI ROSA
BE637

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR DOOR LH	1.0	4,790.46	0	4,790.46
2	REAR DOOR RH	1.0	1,689.57	0	1,689.57
3	REAR SIGNAL LAMP RH	1.0	123.69	0	123.69
4	REAR BRAKE LAMP RH	1.0	123.69	0	123.69
5	REAR BUMPER	1.0	1,652.83	0	1,652.83
6	REAR BUMPER LAMP RH	2.0	76.77	0	153.54
7	REAR EXHAUST PIPE	1.0	536.15	0	536.15
8	REAR NUMBER PLATE LAMP	2.0	62.33	0	124.66
9	REAR DOOR GLASS RUBBER RH	1.0	284.87	0	284.87
10	REAR DOOR GLASS RUBBER LH	1.0	284.87	0	284.87
11	REAR BUMPER BRACKET RH	1.0	76.18	0	76.18
12	REAR BUMPER BRACKET LH	1.0	76.18	0	76.18
List Price - Parts Sub Total					9,916.69
13	REAR DOOR STICKER - 60KM/H	1.0	30.00	0	30.00
14	REAR NUMBER PLATE	1.0	30.00	0	30.00
15	END PANEL - REPAIR	1.0			
16	REAR DOOR CORNER PANEL PILLAR RH - REPAIR	1.0			
17	REAR CHASSIS RH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					60.00
Parts Total					9,976.69
18	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,200.00	0	1,200.00
19	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
20	ANTI-RUST COATING	1.0	150.00	0	150.00
21	TO REMOVE & REFIT WINDSCREEN	1.0	120.00	0	120.00
22	WIRING	1.0	80.00	0	80.00
Labour 1 Sub Total					2,750.00
SINGAPORE DOLLARS : THIRTEEN THOUSAND SIX HUNDRED SEVENTEEN AND CENTS FIFTY-SIX ONLY					
Less Excess					0.00
SUBTOTAL					12,726.69
GST 7.00%					890.87
TOTAL					13,617.56

Date of accident: 18/02/2020 07:45 AM Place of accident: BEDOK NORTH ROAD NEAR BLK180 BUS STOP P-410827

E. & O. E.

I KK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

Page 1 of 1

* N = Item not subjected to GST

Issued by: Anyisia