

**BIFROST AUTO PTE LTD**

## REPAIR ESTIMATE

DATE: 14-Feb-20

INSURANCE: China太平

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH8109B

DESCRIPTION	QTY	LIST PRICE	AMOUNT
FRONT BUMPER COVER <i>distorted</i>	1	\$499.90	\$499.90
FRONT BUMPER REINFORCEMENT <i>HH</i>	1	\$696.40	\$696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>HH</i>	1	\$115.70	\$115.70
FT BUMPER LOWER REINFORCEMENT BRACKET <i>HH</i>	1	\$330.00	\$330.00
FRONT BUMPER SPONGE <i>HH</i>	1	\$78.80	\$78.80
FRONT BUMPER CENTRE GRILLE <i>HH</i>	1	\$301.90	\$301.90
FRONT BUMPER LOWER GRILLE <i>HH</i>	1	\$148.60	\$148.60
LAMP ASSY, FOG, RH <i>2 HH</i>	1	\$920.00	\$920.00
FRONT BUMPER CLIPS <i>HH</i>	1	\$22.00	\$22.00
FRONT BUMPER SIDE RETAINER <i>HH</i>	1	\$77.00	\$77.00
REINFORCEMENT, FRONT BUMPER LOWER <i>HS</i>	1	\$236.10	\$236.10
BRACKET, FRONT BUMPER EXTENSION MOUNTING <i>HS</i>	1	\$110.40	\$110.40
SUPPORT FR BUMPER, RH <i>HH</i>	1	\$81.70	\$81.70
FRONT BUMPER CENTRE FRAME <i>HS</i>	1	\$236.90	\$236.90
BRACKET, FRONT BUMPER SIDE, RH <i>broken</i>	1	\$82.30	\$82.30
BRACKET, FRONT BUMPER MOUNTING <i>HH</i>	1	\$29.60	\$29.60
BRACKET, FRONT BUMPER MOUNTING, NO. 2 <i>HH</i>	1	\$97.80	\$97.80
ABSORBER, FRONT BUMPER, LOWER <i>HH</i>	1	\$127.70	\$127.70
UNIT ASSY, HEADLAMP, RH (LED) <i>2 money broken</i>	1	\$3,455.00	\$3,455.00
TOP PANEL CENTRE <i>HH</i>	1	\$364.98	\$364.98
TOP PANEL SIDE <i>HH</i>	1	\$145.90	\$145.90
BRACKET, HEADLAMP MOUNTING, RH <i>HH</i>	1	\$25.50	\$25.50
FENDER SUB-ASSY, FRONT RH <i>Distorted</i>	1	\$945.30	\$945.30
FRONT FENDER SHIELD <i>distorted</i>	1	\$198.50	\$198.50
FRONT FENDER SHIELD CLIP <i>HH</i>	1	\$14.90	\$14.90
FRONT FENDER HYBRID EMBLEM, RH <i>HH</i>	1	\$86.50	\$86.50
BRACKET, FRONT SIDE PANEL, RH <i>HH</i>	1	\$44.50	\$44.50
EXTENSION, FRONT FENDER, RH <i>HS</i>	1	\$47.20	\$47.20
PROTECTOR, FRONT FENDER SIDE PANEL, RH <i>HS</i>	1	\$113.90	\$113.90
SEAL, FRONT FENDER TO COWL SIDE, RH <i>HH</i>	1	\$15.20	\$15.20
GUSSET, FRONT FENDER APRON, LOWER RH <i>HH</i>	1	\$34.90	\$34.90
EXTENSION, FRONT FENDER APRON, FRONT RH <i>HH</i>	1	\$23.20	\$23.20
MEMBER, FRONT APRON TO COWL SIDE, UPPER RH <i>HH</i>	1	\$138.40	\$138.40
FRONT APRON TO COWL SIDE, LOWER FRT RH <i>HH</i>	1	\$82.30	\$82.30
MIRROR ASSY, OUTER REAR VIEW, RH <i>HH</i>	1	\$1,728.70	\$1,728.70
WIPER SPARE TANK <i>distorted</i>	1	\$183.75	\$183.75
WIPER SPARE TANK MOTOR <i>HH</i>	1	\$242.70	\$242.70
WIPER SPARE TANK FLOAT (NECK) <i>HH</i>	1	\$55.50	\$55.50
FRONT WHEEL RIM <i>HH</i>	1	\$1,570.55	\$1,570.55
FRONT WHEEL HUB CAP <i>HH</i>	1	\$175.80	\$175.80
FRONT WHEEL HUB BEARING <i>2 Down</i>	1	\$559.94	\$559.94



FRONT SUSPENSION LOWER ARM (RH) <i>2 distal</i>	1	\$631.90	\$631.90	<i>✓</i>
FRONT SHOCK ABSORBER (RH) <i>2 distal</i>	1	\$398.20	\$398.20	<i>✓</i>
ABSORBER TOP MOUNTING <i>HN</i>	1	\$196.20	\$196.20	<i>X</i>
FRONT DRIVE SHAFT (RH) <i>HN</i>	1	\$1,764.00	\$1,764.00	<i>X</i>
RACK & PINION ASSY <i>HN</i>	1	\$1,621.30	\$1,621.30	<i>X</i>
BAR, STABILIZER <i>HN</i>	1	\$352.40	\$352.40	<i>X</i>
LINK ASSY, FRONT STABILIZER, <i>HN</i>	1	\$196.80	\$196.80	<i>X</i>
KNUCKLE, STEERING, RH <i>2 distal</i>	1	\$580.80	\$580.80	<i>✓</i>
JOINT ASSY, LOWER BALL, FRONT RH <i>HN</i>	1	\$199.98	\$199.98	<i>X</i>
HUB SUB-ASSY, FRONT AXLE, RH/LH <i>HN</i>	1	\$549.70	\$549.70	<i>X</i>
END SUB-ASSY, TIE ROD, RH <i>HN</i>	1	\$159.30	\$159.30	<i>X</i>
ENGINE UNDER COVER <i>HN</i>	1	\$457.20	\$457.20	<i>X</i>
ENGINE CROSS MEMBER <i>HN</i>	1	\$2,504.40	\$2,504.40	<i>X</i>
FRT ABS WIRE <i>HN</i>	1	\$450.70	\$450.70	<i>X</i>

<b>SUB TOTAL</b>			<b>\$24,508.80</b>	
<b>LESS 20% 25%</b>			<b>\$4,901.76</b>	
<b>DISCOUNTED TOTAL</b>			<b>\$19,607.04</b>	

FRONT TYRE (LH/RH) <i>SVL</i>	Nett	1	\$216.00	\$216.00	<i>X</i>
FRONT NO. PLATE <i>HN</i>	Nett	1	\$25.00	\$25.00	<i>X</i>
FRONT NO. PLATE TRIM COVER <i>HN</i>	Nett	1	\$30.00	\$30.00	<i>X</i>
FRONT NO. PLATE GARNISH <i>HN</i>	Nett	1	\$99.00	\$99.00	<i>X</i>
FRONT BUMPER LOGO <i>HN</i>	Nett	1	\$87.10	\$87.10	<i>X</i>
<b>SUB TOTAL</b>				<b>\$457.10</b>	

Labour Charge				
Panel Beating	1	\$1,200.00	<del>\$1,200.00</del>	600/-
Spray Painting Charge	1	\$1,000.00	<del>\$1,000.00</del>	600/-
Wiring Charge	1	\$120.00	<del>\$120.00</del>	30/-
Tuff Kote	1	\$150.00	<del>\$150.00</del>	40/-
Towing Charge	1	\$50.00	\$50.00	HN
Remove/Refix Undercarriage (Frt)	1	\$200.00	<del>\$200.00</del>	150/-
Rear Wheel Alignment	1	\$120.00	<del>\$120.00</del>	60/-
Remove/Refix Radiator	1	\$90.00	\$90.00	HN
Remove/Refix Aircon & Refill Gas	1	\$150.00	\$150.00	HN
TOTAL LABOUR			\$3,080.00	

**ESTIMATE TOTAL** **\$23,144.14**

quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the

LKK Auto Components Centre, notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

19/02/2020 e 1030m

na Antman

4/5mm 5 days.

Mr LKK Auto