



p=330.75
L=610
940.15
- 200
752.6

L/S = \$750

3 days

CARZ AUTO SERVICES PTE LTD

UEN/ GST 2014094570
61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047
Email: alex@carzauto.com.sg Tel: 65 6 458 1924 Fax: 65 6 458 1928

Insurance Company: **FWD Singapore Pte Ltd**
Address: 6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986
Telephone: Fax:

Carz Auto Consultants hereby notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Make/ Model : TOYOTA HIACE
Chassis No : KDH2010215305
Date/Time of Accident : 22/2/2020 17:10

Date: 25/2/2020
Vehicle No: GBH 4893 Y

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	DESCRIPTION (LIST PARTS)	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	REAR WHEEL HUP CAP LH <i>✓ CRU</i>	1	\$ 100 201.10	25%	\$ 150.83
2	REAR WHEEL BEARING INNER LH <i>✗ 2 / BR</i>	1	\$ 200 313.00	25%	\$ 234.75
3	REAR WHEEL BEARING OUTER LH <i>✗ 2 / BR</i>	1	\$ 141 261.60	25%	\$ 196.20
4	REAR WHEEL AXLE SHAFT LH <i>✗ SVC</i>	1	\$ 599.45	25%	\$ 449.59
5	REAR WHEEL AXLE SHAFT OIL SEAL LH <i>✗ SVC</i>	2	\$ 53.80	25%	\$ 40.35
6	REAR WHEEL SHOCKABSOBER LH <i>✗ SVC</i>	1	\$ 166.20	25%	\$ 124.65
TOTAL LIST COST PRICE & AFTER DISCOUNT					\$ 1,196.36

SPECIAL NETT ITEM

SPECIAL ITEMS	DESCRIPTION (SPECIAL NETT PARTS)	QTY	PRICE \$	FINAL PRICE \$
1	REAR WHEEL TYRE LH <i>✗ SVC</i>	1	\$ 250.00	\$ 250.00
TOTAL SPECIAL NETT ITEM				\$ 250.00

Labour Works / Panel Beating Related Works

Job Scope	Quotation
TO REMOVE AND RENEW <u>REAR</u> DAMAGED PARTS-REPLACE REALIGNED ALL AFFECTED PARTS	\$ 200 400.00

Repair tender

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 500.00

250

Labour Works

Job Scope	Quotation
TO COMPUTERISED FOUR WHEEL ALIGNMENT	\$ 60 80.00
TO REMOVE AND REPLACE REAR UNDERCARRIAGE	\$ 100 250.00
OTHER LABOUR COST	\$ 430.00

Repair day - 3 days
Lump Sum
After paint photo

Sun Pin (Lklc)
25/02/2020
TP without prejudice.

GRAND TOTAL \$ 2,776.36