

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref

: D20001136MFSH

Date: 12th March 2020

Our Ref

: CS4/FCI20003253/Nsf3s2

M/s MS First Capital Insurance Ltd

36 Robinson Road #16-01 City House Singapore 068877 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHC 313L ACCIDENT ON 20/02/2020

Instruction was received to inspect the vehicle Reg. No. SHC 313L. The inspection was conducted on 26/02/2020 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

The following vehicle information was recorded:

Registration Number

: SHC 313L

Make/Model

: Mercedes Benz Viano CDI 2.2

Year of Registration

: 2013

Body Colour

: White

Chassis Number

: WDF63981323795586

Engine Capacity

: 2143 cc

The vehicle front portion, including engine and interior burnt. The Estimated repair cost of such vehicle is S\$75,347.98 (Sin Dollars: Seventy-Five Thousand Three Hundred Forty-Seven and Ninety Eight Cents only.) (Details see photographs enclosed)



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "Total Loss".

| (a) | If the vehicle to be "Total Loss" |
|-----|-----------------------------------|
| | Book Value |

| S\$ | 46,901.82 |
|-----|-----------|
| | , |

Less: LTA Reimbursement Value (RV)

(S\$ 42,228.00)

Nett Liability

S\$ 4,673.82

S\$ 4,673.82

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 75,347.98

Nett Liability

S\$ 75,347.98

$$(a) - (b) =$$

(S\$ 70,674.16)

The amount of estimated saving of S\$70,674.16 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

MUHD NAZRIL (NAZ)

Technical Investigator LL.B. (Hons) London

K.K.LAU
MSc(Fng M) R Fng(Hons) Pe

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust), MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA),

AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.