



TAN LIM MOTOR PTE LTD

Miss Concern Trading Pte Ltd

Date : 13 February 2020

209: 644-

04/03/2020 @ 1440h

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front grille with moulding X	
02	1 pc	front bumper de -	\$ 608.10
03	2 ps	front bumper side brackets @ \$50.00 LH-acc / RH-X	\$ 1,560.00
04	1 pc	front bumper tow hook cover X	\$ 100.00
05	1 pc	front bumper reinforcement X	\$ 41.25
06	8 ps	front bumper clips @ \$4.30 ac -	\$ 425.00
07	1 pc	n/s headlamp X	\$ 34.40
			\$ 1,289.80
		Less 25 %	\$ 4,058.55
			\$ 1,014.64
			\$ 3,043.91
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	
02		Panel beating, knocking and straighten the necessary portion,	\$ X 50.00
03		remove and renewal of parts, adjust and realign the same.	\$ 200 400.00
		Putty and spray painting of the affected portion.	\$ 200 500.00
			\$ 950.00
	Total		\$ 3,993.91

04/03/2020 @ 1440h

978

50

✓

LS

1062.40

25%

796.80

1604.40

41.10

1233.30

250

400

650.00

1583.30

20%

1506.64

Reg after repair

Lump sum \$1,500.00

3 days repair