

Date: 28 Feb 2020

ASSESSMENT FOR REPAIR: HONDA FJS400A - FBL532U

Chassis No.: JH2NF039X9K000238

Engine No.: NF01E5222438

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Left front signal	\$120 \$195.00 ✓ SCR
1 pc	Right front signal	\$120 \$195.00 ✓ SCR
		<hr/>
		\$390.00
	Less discount 10%	\$39.00
		<hr/>
		\$351.00
		<hr/>
	Total Estimate	<hr/>
		\$351.00

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd