



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg Tel: 65 6493 1924 Fax: 65 6493 1928

Insurance Company: **China Taiping Insurance (Singapore) Pte Ltd**

Address: 3 Anson Rd
#16-00 Springleaf Tower
Singapore 079909

Telephone: Fax:

Make/ Model : TOYOTA WISH Date: 27/2/2020

Chassis No : JTDGJ20W305001190 Vehicle No: SLS 6275 S

Date/Time of Accident : 26/2/2020 10:27

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR					
ITEMS	DESCRIPTION (LIST PARTS)	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	TAIL GATE / PD	1	\$1,272 1,460.40	25%	\$ 1,095.30
2	TAIL GATE WINDSCREEN MOULDING / NEC	1 SET	\$ / 210.20	25%	\$ 157.65
3	TAIL GATE WEATHERSTRIP / CRA	1	\$ / 399.15	25%	\$ 299.36
4	TAIL GATE LOGO / NEC	1	\$ / 49.15	25%	\$ 36.86
5	TAIL GATE LOGO MOLDING / CRA	1	\$ / 292.60	25%	\$ 219.45
6	TAIL GATE REFLECTOR ? LH / SCH / RH / CH 2	2	\$ / 607.70	25%	\$ 455.78
7	TAIL GATE INNER TRIM BOARD ? / CHU	1	\$ / 606.40	25%	\$ 454.80
8	TAIL GATE TOP LOCK X SVC	1	\$ X 399.85	25%	\$ 299.89
9	TAIL GATE LOCK SENSOR ? X SVC	1	\$ X 697.75	25%	\$ 523.31
10	REAR BUMPER REAR BUMPER SIDE RETAINER / BR 1/2	1/2	\$ 68.38 136.76	25%	\$ 102.57
11	REAR BUMPER REFLECTOR ? LH / CRA 1/2	1/2	\$ 69.9 139.80	25%	\$ 104.85
12	REAR BUMPER BRACKET ? X SVC	2	\$ X 130.70	25%	\$ 98.03
13	REAR TAIL LAMP LH / CRA / RH / SCH 2	2	\$ / 803.30	25%	\$ 602.48
14	REAR TAIL LAMP PANEL LH ? / PD	1	\$ / 198.85	25%	\$ 149.14
15	REAR TAIL LAMP LOWER BRACKET X SVC	2	\$ X 116.70	25%	\$ 87.53
16	REAR END PANEL ? / BP	1	\$ / 519.95	25%	\$ 389.96
17	REAR END PANEL TOP GARNISH X / CRA	1	\$ / 292.65	25%	\$ 219.49
18	REAR END PANEL BOTTOM PANEL ? X SVC	1	\$ X 201.45	25%	\$ 151.09
19	REAR END PANEL CORNER PANEL LH ? / BT	1	\$ / 185.15	25%	\$ 138.86
20	REAR FLOOR PANEL X R	1	\$ X 599.85	25%	\$ 449.89
21	REAR FLOOR PANEL TOOLS BOARD COVER X SVC	1	\$ X 185.15	25%	\$ 138.86
22	REAR FLOOR PANEL TOOLS BOARD HOLDER X SVC	1	\$ X 110.25	25%	\$ 82.69
23	REAR FENDER LH / PD	1	\$ / 806.65	25%	\$ 604.99
24	REAR FENDER SPLASHIELD LH ? X SVC	1	\$ X 128.75	25%	\$ 96.56
25	REAR FENDER INNER TRIM COVER LH ? / cut	1	\$ / 546.80	25%	\$ 410.10
26	REAR FENDER QUARTER GLASS WITH MOULDING LH / NEC	1	\$ / 585.15	25%	\$ 438.86
TOTAL LIST COST PRICE & AFTER DISCOUNT			7,513.98		\$ 7,808.33

- 25%

5,635.49

SPECIAL NETT ITEM					
SPECIAL ITEMS	DESCRIPTION (SPECIAL NETT PARTS)	QTY	PRICE \$		FINAL PRICE \$
1	TAIL GATE WINDSCREEN SEALANT ✓ Nec	1	\$ 50.00		\$ 50.00 30
2	REAR NUMBER PLATE X SVC	1	\$ 50.00		\$ 50.00 X
3	REAR BUMPER CLIP - Nec	8	\$ 64.00		\$ 64.00 30
4	REAR TAIL LAMP CLIP ✓ Nec	4	\$ 32.00		\$ 32.00 10
5	REAR FENDER QUARTER GLASS SEALANT LH < Nec	1	\$ 50.00		\$ 20 50.00 30
6	REAR FLOOR PANEL INSULATOR ? ✓ Nec	1	\$ 150.00		\$ 150.00 30
7	REAR REVERSE CAMERA X SVC	1	\$ 450.00		\$ 450.00 X
8	REAR REVERSE SENSOR ✓ short	1	\$ 280.00		\$ 280.00 200
TOTAL SPECIAL NETT ITEM					\$ 1,126.00 320

Labour Works / Panel Beating Related Works

Job Scope	Quotation
TO REMOVE AND RENEW <u>REAR</u> DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS	\$ 1,800.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,400.00

Labour Works

Job Scope	Quotation
TO REMOVE/ REFIX WIRING CHECKS	\$ 30 60.00
TO TUFFCOAT AFFECTED AREA	\$ 60 200.00
TO REMOVE AND REFIX <u>REAR</u> WINDSCREEN	\$ ✓ 120.00
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	\$ 40 100.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 30 100.00
TO REMOVE AND RE-INSTALL RENEW VIDEO CAMERA	\$ 30 150.00
TO REMOVE AND REPLACE TAIL GATE MECHANISM	\$ 60 100.00
TO REMOVE AND REPLACE ONE QUARTER GLASS	\$ 60 100.00
OTHER LABOUR COST	\$ 930.00

GRAND TOTAL \$ 13,064.33

Jeslyn
CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
Job Title: Motor Claim
Mobile: 65 8322 7418
Email: jeslyn@carzauto.com.sg

P = 5,635.49

N = 320

L = 2,630

8,585.49

- 20%

6,868.39

Repair day - 8 days

Lump Sum

After paint photo

Sun Pm (1400)

27/02/2020

TP without prejudice

L/S

\$ 6,850

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: