

ASS. REC. BY:

REF: CS / MSG 20003290 / Tls B3

n2
Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Katherine Wong

of MSG

Date/Time: 27.2.2020 15.49pm

Estimated Cost:

Bill to:

OD-TP-WS-TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 3295B

Insured: XD 8583B

at Workshop m/s CYS Automobile

Tel: 6219 2098

of 38 Woodland Industrial Park East 1 #07-17

Policy No: 1001299832

Claim No: 239566

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25.2.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 27/2/2020 4:17pm

Person Contacted: Wee Sin

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLJ 3295B - X
	XD 8583B - X
02/03/20	@ 15:31 pm revised PA to Katherine Wong via me:men.

ASS. REC. BY: TaufshREF: MS19

ASSIGNMENT

From: _____ Date: 28/11/2020

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLJ 3295B
at Workshop m/s CYS Automobile Servicesof 36 woodlands Industrial Park East 1 #07-17

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS mp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLJ 3295B Yr Regn: 2016 Dec.Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Axio C.C. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 188350 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NRE1610021217Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CST

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Survey held at CYS, WLDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/34/5 \$2300 5 days email to w/s
C \$1,524.45 Red - 40%?

RECEIVED 12 MAR 2020

Date/Time, File Pass to?

12/03/201) Typist

Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / I.B. / I.S. \$2,300/- 45Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$ _____)☐ Interview (\$ _____)☐ Tech. Invs (\$ _____)☐ Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

150
11
161

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 02 Mar 2020

Preliminary Advice

Insured Vehicle No	: XD8583B	Accident Date	: 25/02/2020
TP Vehicle No	: SLJ3295B	Assignment Date	: 27/02/2020
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 5 days
Date of Inspection	: 28/02/2020		
Inspection At	: CYS Automobile Services Pte Ltd (Woodlands) 38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park Singapore 757700		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,824.45
Revised Amount	:S\$	3,075.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,075.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2020 13:18		27 Feb 2020 15:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SAMWOH RESOURCES PTE LTD, Co. Reg. No.: 199105225W		
Main Claimant:	CYS CAR RENTAL PTE LTD, Co. Reg. No.: 201205697K		
Vehicle Reg. No.:	SLJ3295B	Date of Loss:	25/02/2020 15:00 - :59 [85 Months and 24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 239566	Policy/Cover Note No.:	1001289832 (Third Party Only) Coverage: 21/01/2020 - 20/01/2021
Vehicle Reg. No. (Insured):	XD8583B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	CYS Automobile Services Pte Ltd (Woodlands) 38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park, 757700 Woodlands - Tel: 6219 2098		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 28/02/2020]		
Driver/Custodian (Insured):	TIAN WEI (), NRIC: G8125507K Email:		
Adj Asg. Remarks:	on WP, OI:Samwoh. Liab: unclear. Disagree on SJE. Contact: Wee Sin @ 6219 2098.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: CYSAUTO <cysauto@singnet.com.sg>
Sent: Thursday, 12 March 2020 9:24 am
To: Taufikh (LKKAuto)
Subject: RE: OUR REF: SLJ3295B - FINALISATION & PHOTOS - CONFIRMED COR AT \$2,300

Dear Mr Taufikh,

WITHOUT PREJUDICE

Confirmed with thanks

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD
38 Woodlands Industrial Park E1 #07-17 S(757700)
Tel: 62192098 Fax: 62192096
Email: cysauto@singnet.com.sg

From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]
Sent: Tuesday, March 10, 2020 9:43 AM
To: 'CYSAUTO' <cysauto@singnet.com.sg>
Subject: RE: OUR REF: SLJ3295B - FINALISATION & PHOTOS

Hi Wee Sin,

Sorry for this case can refinalise because my office check taillamp price abit high.
I revised taillamp price to \$548.20. So final COR I/s\$2300 , 5 days.

Regards
Taufikh
LkkAuto

From: CYSAUTO [mailto:cysauto@singnet.com.sg]
Sent: Thursday, 5 March 2020 11:17 AM
To: 'Taufikh (LKKAuto)'
Subject: OUR REF: SLJ3295B - FINALISATION & PHOTOS

Dear Mr Taufikh,

WITHOUT PREJUDICE

Attached herewith estimate and photos for your attention.

We have calculate the repair cost at \$2,450.00 based on lump sum.

Kindly check and confirm. Thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Shirley Hiew (LKK Auto)

From: Taufikh (LKKAuto)
Sent: Friday, 6 March 2020 10:20 am
To: 'CYSAUTO'
Cc: Shirley Hiew (LKK Auto)
Subject: RE: OUR REF: SLJ3295B - FINALISATION & PHOTOS

Hi Wee Sin

COR I/s\$2450 , 5 days.

Regards
Taufikh
Lkk Auto

From: CYSAUTO [mailto:cysauto@singnet.com.sg]
Sent: Thursday, 5 March 2020 11:17 AM
To: 'Taufikh (LKKAuto)'
Subject: OUR REF: SLJ3295B - FINALISATION & PHOTOS

Dear Mr Taufikh,

WITHOUT PREJUDICE

Attached herewith estimate and photos for your attention.

We have calculate the repair cost at \$2,450.00 based on lump sum.

Kindly check and confirm. Thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Professional. Fast. Free.

Streamline Your Online Operations and Work More Efficiently. Create

toyota axio Price Range Depreciation 2016 Vehicle Type Search

Advanced Search

Home » Used Cars » Viking Motor Pte Ltd » Toyota Corolla Axio 1.5A X

Toyota Corolla Axio 1.5A X

Overview Financial Insurance Accessories Similar Research Photos Map



Price	\$57,800		
Depreciation	\$8,030 /yr View models with similar degree	Reg Date	08-Dec-2016 (6yrs 9mths 5days COE left)
Mileage	32,000 km (9.9k /yr)	Manufactured	2016
Road Tax	\$682 /yr	Transmission	Auto
Dereg Value	\$39,636 as of today (change)	OMV	\$16,857
COE	\$50,951	ARF	\$6,857
Engine Cap	1,496 cc	Power	80.0 kW (107 bhp)
Curb Weight	1,050 kg	No. of Owners	1
Type of Vehicle	Mid-Sized Sedan		

Features

1.5L Reliable And Efficient 16 Valves 4 Cylinders VVT-i DOHC Engine, Low Fuel Consumption At 17.2Km/L, ABS, Dual SRS Airbags. View specs of the Toyota Corolla Axio (2015-2019)

Accessories

Pioneer DVD/Bluetooth/Audio Sound System, New Leather Seats, Retractable Side Mirrors, Halogen Headlights.

Description

1 Owner Only! Very Good Condition! View To Believe! 100% Accident Free! 100% Loan Approval! \$0 Down Payment! High Trade In Welcome! Bank Loan Or In House Loan Available! Call Me Now Before It's Sold!

Category

PARF Car, Low Mileage Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more


Posted on: 01-Mar-2020 | Last Updated on: 01-Mar-2020

Upfront Payment

» more Financial info

Transfer Fee	\$25	
Down Payment	\$17,340 (change)	Maximum 70% Loan
1st Instalment	\$600	Based on 2.98% interest rate
Insurance	\$624 onwards (Get a quote) Extra 15% Off for MINDEF, MHA & POGIS policyholders Quote assumes a standard profile. "Get a quote" for exact figure.	

Compare



Shortlist Compare Add note
Report Error More Actions

Seller Information

Viking Motor Pte Ltd

34 vehicles for sale, 53 sold in past 3 mths

210 Turf Club Road Lot B33
Car Mall @ The Grandstand
Tel: 63146133

Search cars nearby

Ayden Lam	88151068
Alex	90016932
Jeffrey	86601482
Danny	82000318

Powered by
AVIVA



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 697K

Vehicle Details

Vehicle No.: SLJ3295B

Vehicle to be Exported: No

Intended Deregistration Date: 02 Mar 2020

Vehicle Make: TOYOTA

Vehicle Model: COROLLA AXIO 1.5X A

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: 2NR8666929

Chassis No.: NRE1610021217

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$16,781.00

Original Registration Date: 05 Dec 2016

First Registration Date: 05 Dec 2016

Transfer Count: 0

Actual ARF Paid: \$6,781.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 04 Dec 2026

PARF Rebate Amount: \$5,085.00

Intended COE Rebate Details

COE Expiry Date: 04 Dec 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$50,951.00

COE Rebate Amount: \$34,419.00

Total Rebate Amount: \$39,504.00

The information contained herein is correct as at 02 Mar 2020

OK



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR CYS CAR RENTAL PTE LTD
38 WOODLANDS INDUSTRIAL PARK E1
#07-10 SINGAPORE 757700

POLICY NO : THIRD PARTY CLAIM
YOUR REF : XD 8583 B (MSIG)
OUR REF : TP 6143
VEHICLE NO : SLJ 3295 B
MAKE/MODEL : TOYOTA AXIO
DATE OF ACCIDENT : 25.02.20

SURVEY BY

DATE : 26.02.20

- 1 PC REAR WINDSCREEN GLASS MOULDING
- 1 PC REAR FENDER RH
- 1 PC TAILLAMP ASSY RH
- 1 PC TAILLAMP PANEL RH
- 1 PC REAR BUMPER
- 1 PC REAR BUMPER SIDE RETAINER RH

2320.50

1740.38 LESS 25%

S\$ 97.80 *del*
892.10 *bul*
757.30 *crs* 548.20
159.00 *R*
682.70 *del* 598.50
99.70 *del*
S\$ 2,688.60 2524.60
672.15
S\$ 2,016.45 1847.20

- 1 PC REAR WINDSCREEN GLASS SEALANT
- 1 SET REAR BUMPER CLIPS
- 1 SET REVERSE SENSOR

S\$ *del* 40.00 S/NETT
del 28.00 "
X 250.00 "
S\$ 318.00 68

TO REMOVE AND REFIX REAR WINDSCREEN GLASS

S\$ 140.00 120

TO REMOVE AND REFIX CUSHION SEAT & REAR FENDER INNER TRIM

80.00 40

TO CHECK WIRING FUNCTION

20.00 ✓

TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL

50.00 30

LABOUR CHARGES

600.00 450

TO PUTTY AND SPRAY PAINTING CHARGES

600.00 450

S\$ 3,824.45 1110

SIN DOLLARS: THREE THOUSAND EIGHT HUNDRED TWENTY-FOUR AND CENTS FORTY-FIVE ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taujikh 97495747 3075.20
'WP' 4342450
28/2/20 @ 4pm 5 days
Lumpsum
Resurvey after repair 2918.38
sur @ 1km town 4/5/2380
5 days 5 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20003290/T1SF3N2
Date: 17/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001289832
Claimant Vehicle No: SLJ3295B Insured Vehicle No: XD8583B
Date of Loss: 25/02/2020 Nature of Claim: TP Claim No: 239566

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLJ3295B
Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A) Engine No: 2NR8666929
Reg. Date: 05/12/2016 (Man. Year: 2016) Chassis No: NRE1610021217
Colour: Blue Odometer: 188350 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15
Front Left Side: CST 6 mm Rear Left Side: CST 6 mm
Front Right Side: CST 6 mm Rear Right Side: CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,334.45	1,808.37	526.08	22.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	1,110.00	380.00	25.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,824.45	2,918.37	906.08	23.69
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	3,824.45	2,300.00	1,524.45	39.86
+ GST 7.00/7.00% (S\$)	267.71	161.00	106.71	39.86
Nett Amount (S\$)	4,092.16	2,461.00	1,631.16	39.86

INSPECTION

Date of Assignment: 27/02/2020
Date Inspected: 28/02/2020 Inspected At: CYS Automobile Services Pte Ltd (Woodlands)
38 Woodlands Industrial Park East 1, #07-17,
Admiralty Industrial Park
Singapore 757700
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2020)
Parts:	143	TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ3295B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	97.80 FL	*97.80 FL
2	1		*REAR FENDER RH	Buckled	892.10 FL	*892.10 FL
3	1		*TAILLAMP ASSY RH	Cracked	757.30 FL	*548.20 FL
4	1		*TAILLAMP PANEL RH	Repair	159.00 FL	*- FL
5	1		*REAR BUMPER	Deformed	682.70 FL	*682.70 FL
6	1		*REAR BUMPER SIDE RETAINER RH	Necessary	99.70 FL	*99.70 FL
7	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
8	1		*SET REAR BUMPER CLIPS	Necessary	28.00 FS	*28.00 FS
9	1		*SET REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
					Sub Total (\$\$)	3,006.60 2,388.50
					- List Item Discount on L Items 25.00/25.00% (\$\$)	672.15 580.13
					Total Parts (\$\$)	2,334.45 1,808.37

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	140.00	120.00
2	TO REMOVE AND REFIX CUSHION SEAT & REAR FENDER INNER TRIM	New	80.00	40.00
3	TO CHECK WIRING FUNCTION	New	20.00	20.00
4	TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL	New	50.00	30.00
5	LABOUR CHARGES	New	600.00	450.00
6	TO PUTTY AND SPRAY PAINTING CHARGES	New	600.00	450.00
Gross Labour Cost (\$\$)			1,490.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >