

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFZ 2796 R

| S/N | Nature of Jobs | Estimated Charges | Surveyor's Reccomendations |
|-----------------------------|--|-----------------------------|----------------------------|
| 1 | To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages. | S/N \$ 280.00 / | |
| 2 | To dismantle lhs rear door and lhs sill panel trim. To renew lhs rear door. Re-organise rear crash management components. Reinstall all parts removed. | \$ 2,100.00 500 | |
| 3 | To respray lhs rear door, lhs front door, door handles and lhs sill panel trim. | \$ 3,000.00 1500 | |
| 4 | To carry out diagnostic check. | S/N \$ 192.00 / | |
| TOTAL LABOUR CHARGES | | : <u>\$ 5,572.00</u> | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFZ 2796 R

| S/N | Parts Description | Damage Parts & Prices | | Remarks |
|-----|---|-----------------------|-------------|---------|
| | | S/Nett | | |
| 1 | REAR DOOR LH <i>lt</i> | 1 | \$ 2,125.00 | |
| 2 | REAR DOOR WIRING SET LH <i>? . x nn</i> | 1 | \$ 275.00 | |
| 3 | REAR DOOR INNER TRIM LH <i>? . xnn</i> | 1 | \$ 3,000.00 | |
| 4 | REAR DOOR STRIP OUTER LH <i>? . nec</i> | 1 | \$ 350.00 | |
| 5 | REAR DOOR OUTER SEAL LH <i>? . xnn</i> | 1 | \$ 150.00 | |

| | | |
|----------------------|---|--------------|
| TOTAL SPARE PARTS | : | \$ 5,900.00 |
| TOTAL LABOUR CHARGES | : | \$ 5,572.00 |
| GRAND TOTAL | : | \$ 11,472.00 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax



Name : *RASUL - HP 90010068*
Surveyed Date : *27/02/2020 @ 1100*
Authorised Date : *4 days*
Excess Cost :
Liability :
Remarks : *Ready before paint*

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant