

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
LONPAC INSURANCE BHD			Ref : CS/LPC20003320/Qyd3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date: 13-05-2020 Code: LPC2			
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 9255C	Veh. Inspected	SML 7937J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	19/20/20/VC06/023112	Excess (\$)	0.00	
	Assign From	ONG LI LI	Assign Date	28/02/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS PLUS	c.c	1798	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	JTDZS3EU00J040569	Colour	RED	
	Odometer	53758	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	ARIVO	5 mm	
	L/H Front Tyre	205/60 R16	ARIVO	5 mm	
	R/H Rear Tyre	205/60 R16	ARIVO	5 mm	
	L/H Rear Tyre	205/60 R16	ARIVO	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	25/02/2020	Inspection Date	28/02/2020	
	Survey held at MY CAR CONSULTANT PTE LTD				
	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				