



ALLSWELL MOTOR TRADERS

25, Defu Lane 9, Singapore 539266

GST Reg No.: 53192889J

Tel No.: 6679 1146 / 91478545

Email: ben@allswellmotor.com.sg

account5@allswellmotor.com.sg

Not Withheld
C/Ling @ 215d.
Resurvey After Pain

4 days

(3rd Party Claim Against ⁱⁱⁱ Insured SHA7022R)

DOI: 23.02.2020

Repair Estimate

Vehicle No. : SKK3149Y

Submitted by : Ben

Make & Model : Nissan Sylphy 1.5

COE Expiry : 31-05-2021

S/No	Part Description	Qty	Price	Unit Price	Disposition by
01	Front bumper 636.20 B	01	\$1,510.00		✓
02	LH headlamp 638 m/c m	01	\$900.00		✓
03	LH returner / RH returner C/M	01	\$51 / \$51		✓
04	Support panel B7 fender B7	01	\$720.00		X 672.70
05	Lower arm S	01	\$400.00		X
06	Linkage L	01	\$180.00		X
07	LH wheel knuckle L	01	\$395.00		X
08	LH headlamp lower bracket D/I	01	\$45.00		✓
Special nett					
01	Clips / returner studs M	01	\$40.00		✓
Labour Description					
01	Disassemble / Assembly of all affected parts	01	\$600.00		\$600
02	Panel knocking of support panel M	01	\$300.00		X
03	Spray painting of all affected parts	01	\$400.00		✓

Note: If any the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

Kenneth Kong @ kkkauto.com

GIA & 105 land

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: