



NINETEEN
AUTOWERKS

NINETEEN AUTOWERKS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-05
Bartley Biz Centre, Singapore 417807
Tel: (65) 9270 5882
nineteenautowerks@gmail.com

not Authorized

28 February 2020

ACCIDENT DATE : 27 Feb 2020
OWNER : JOSEPH LIM DIANNING
REG NO. : SLE 2095 U
MAKE/MODEL : HONDA VEZEL

*2 late
4/5 \$4200
5 days.
The total After repair*

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
LIST ITEMS		
1	Front door -R/H	\$ 12 1,085.70 X
1	Front door lower rubber	\$ 11 122.70 X
1	Front door weatherstrip	\$ 11 130.80 X
1	Rear door -R/H	\$ 3 body 1,085.50
1	Rear door checker	\$ 11 62.50 X
2	Rear door hinges	\$ 11 117.00 X
1	Rear door inner trim board	\$ 266.50 588.90
1	Rear door inner lock	\$ 11 285.00 X
1	Rear door regulator come with motor	\$ 325.50 488.80
1	Rear door weatherstrip	\$ 11 130.80
1	Rear taillamp -R/H	\$ 11 695.00 X
1	Rear bumper	\$ 507.20 950.60
1	Rear bumper - side	\$ 225.30
1	Rear bumper side retainer	\$ 11 50.90 X
1	Rear fender -R/H	\$ 12 1,500.70 X
1	Rear fender inner shield	\$ 11 149.80 X
1	Rear fender wheel arch garnish	\$ 300.70
1	Rear wheel hup come with bearing	\$ 11 332.50 X
1	Rear shock absorber	\$ 11 421.00 X
1	Rear axle beam	\$ 11 1,513.30 X
		\$ 10,237.50
Less 20%		\$ 2,047.50
		\$ 8,190.00

*2-2786.60
20%
2229.28*

SPECIAL NETT ITEMS

1	Front door black tape (1 set)	\$	11	120.00	X
1	Rocker panel side skirt -R/H	\$	De/Toon	450.00	✓
1	Rear door black tape (1 set)	\$	new	120.00	80
1	Rear bumper lower spoiler	\$	gms	500.00	✓
1	Rear tyre	\$	su	400.00	X
1	Rear wheel rim -R/H	\$	Cu7	750.00	550
		\$		2,340.00	

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$	11	180.00	X
3	To remove and refit rear undercarriage.	\$	11	350.00	X
4	To conduct wheel alignment.	\$		150.00	60
5	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$		400.00	60
6	To apply undercoating.	\$		180.00	40
7	Panel beating.	\$		1,600.00	500
8	To re-spray painting on the affected areas.	\$		1,500.00	800
		\$		4,440.00	

GRAND TOTAL :

\$ 14,970.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2229-28
S.V-158000
L-1480.00
5289.28
202
4731