

Trale

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKW 6568 M

OK
6/3

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
<i>1</i>	FRONT BUMPER <i>X Repair. cut</i>	\$	2,449.00
2	FRONT BUMPER FIXING PARTS <i>X</i>	\$	420.00
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>X</i>	\$	41.00
<i>4</i>	FRONT FENDER - LH <i>/ BNC</i>	\$	1,525.00
5	FRONT FENDER ATTACHMENT PARTS <i>X</i>	\$	72.00
<i>6</i>	FRONT FENDER BRACE - LH <i>?</i>	\$	96.00
<i>7</i>	S-LINE INSCRIPTION <i>/ dec.</i>	2 \$	233.00
8	WHEEL HOUSING LINER <i>?</i>	\$	226.00
9	WHEEL HOUSING LINER ATTACHMENT PARTS <i>?</i>	\$	52.00
10	REAR WHEEL HOUSING LINER - LH <i>X</i>	\$	256.00
<i>11</i>	FRONT WHEEL COVER - LH / RH <i>/ dec.</i>	2 \$	1,080.00
<i>12</i>	FRONT ALUMINIUM RIM - LH <i>/ cut</i>	\$	1,542.00
13	FRONT WISHBONE LINK <i>?</i>	\$	388.00
14	SUSPENSION GUIDE <i>?</i>	\$	972.00
15	GUIDE - LH UPPER FRONT / REAR <i>?</i>	\$	610.00
16	WHEEL BEARING HOUSING - LH <i>?</i>	\$	733.00
17	SWIVEL JOINT <i>?</i>	\$	208.00
18	WHEEL HUB <i>?</i>	\$	460.00
19	DOUBLE ANGLED BALL BEARING <i>?</i>	\$	237.00
20	TIE ROD END <i>?</i>	\$	190.00
21	TYRE <i>X</i>		TBC
22	SUNDRIES <i>?</i>	\$	400.00
TOTAL SPARE PARTS		:	\$ 12,190.00
TOTAL LABOUR CHARGES		:	\$ 8,752.00
GRAND TOTAL		:	\$ 20,942.00

Paul
24/03/2020

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Subject to insurance approval